

သံလွင် 16866

အိမ်ဆောက်ပစ္စည်း နှင့် ကရိုနီးဝန်ဆောင်မှု

မြစ်ငယ် - မြစ်ဦးလွင်အတက်လမ်း၊ နားထောင်းကျ၊ အုန်းချော၊ ပန္နလေး။

📞 09-772215437, 09-2015462

ဝယ်ယူအမည် ကျော့အောင်စိမ့် နေ့စွဲ 3/8/23

ကျန်းစ. - 1500000

ကျွမ်း-သေ

1500000

လက်မှတ် -----



ရွှင်လန်၊ ချမ်း၊ ခမ္မိ ကြပါ ၁၀၀၀

ကိုသေးမင်းကျော် + မပိုးနိုးကြွယ် 3621

ထွန်းအောင်ကျော်

တွင်-စက်မှုလက်မှု

အုန်းချော၊ မန္တလေး-ပြင်ဦးလွင်လမ်း။ ☎ 09-40266652, 09-2012365, 09-258600245

အမည် ဦးစိတ်ဦးလွင်

နေ့စွဲ 31.7.2023

နေရပ်

စဉ်	ဦးရေ	နှုန်း	သင့်ငွေ
①			1000000
<p>ဘက် ဖိုးလက်ဖောက်ခြားတန်း သံဖြား 2 ဖက် ချိုက်ကတ် ဖျတ်ကျောက်တိုက်ကတော ဆော်</p>			
		မအူဝါ	7

အားပေးမှုအတွက် အထူးကျေးဇူးတင်ပါသည်။

လက်မှတ်

စုစုပေါင်း

1000000

စရန်ငွေ

ကျန်ငွေ



SERVICE REPORT

Job Order No. MOY/JA/23/10/1715
 Customer Name U Win Hlaing
 Machine Location Oba Cha W
 Machine Model SE290
 Machine SR No. 000029
 Engine Brand Commins
 Engine Model damaged
 Engine Sr.No damaged
 Hour Meter (oil am) 313hr
 Job Site Distance 250 mile
 Application Mining
 Number of Trip 1

	Date	Time
Customer Call Date	10/23	
Confirm with Customer		
Go to Job Site Time		10:50 Am
Arrival Job Site Time		10:53 Am
Job Start Time		10:57 Am
Job Finish Time		12:31 Pm
On Back From Site		12:35 Pm
Arrival Office Time		1:41 Pm
Job Delay Date & Time		
Reason of Job Delay		

Customer Call Problem

Belt rope damage

Root of Problem

Alternator pulley abnormal

Recommendation We inspected the belt rope and it was damaged so we checked the fan pulley, water pump pulley, belt tensions and alternator pulley. Alternator pulley was abnormal. So we dismantled it and send to local workshop. We need to continue.

Excess/Correct Part

No	Part Description	Part No	Qty	Remarks

*Cash On Service Work Done၊ ဓာတ်ပြုခြင်းက ကုသခံငွေများအား ဖြစ်ဆဲပင်၊ ချက်ချင်းပေးသွင်းရန်။
 *In case must settle within 7days (ဆင်ကြောင်းအမျိုးမျိုးကြောင့် ချက်ချင်း ငွေပေးချေနိုင်ပါက (၇)ရက်အတွင်း ပေးချေရမည်။)

Customer Sign U Win Hlaing

Service Person Sign Jee
 Service Person Name IZOG KTH

Responsible (Service Dept. Head)	Comments	Media	
		Excessive Visit	
Responsible (Engine Operation Head)	Comments	STD Job Time (HR)	
		Actual Job Time (HR)	
		% to STD Time	
		Customer Comments	



SERVICE REPORT

Job Order No.
Customer Name
Address & Location
City/Town/Village
Telephone No.
Engine Brand
Engine Model
Engine No.
Make/Model (if Kit)
Job Site Location
Approximate
Number of Trip

MDY/08/23/09/1872
 15 Unit Mining
 Ohn chaw
 SE 890
 00029
 Generator
 damaged
 damaged
 137-4401
 2.5hr
 Mining

	Date	Time
Customer Call Time		
Confirmed with Customer		
Go to Job Site Time	7:45 AM	10:00 AM
Arrival at Job Site		11:00 AM
Job Start Time		11:30 AM
Job Finish Time		2:53 PM
Go Back From Site		3:00 PM
Arrival Office Time		3:32 PM
In Office Date & Time		
Reason of Job Delay		

Customer Call Location
 Boom frame dismounting

Job Location
 Dismounting

Service Action
 We inspected the site and we dismounted the bucket pins, bucket and pipes. And, we dismounted the arms cylinder pins, boom arm pin and boom frame and cylinder. Then, we dismounted the boom cylinder (unit) and pipes and boom pin and boom frame. Job was finished.

Exhaust/Cancel Part

No	Part Description	Part No	Qty	Remark

* Cash On Service Work Done (အပ်ငြိခြင်း ကျဆုံးစေရန်အား ဖြစ်နိုင်ပါ သွက်ဆင်းပေးရမည်)
 * In case must settle within 7 days (အပ်ကြောင်းအချိုးအကြား သွက်ဆင်း ပေးပေးရမည်ပင် (၇)ရက်အတွင်း ပေးဆပ်ရမည်)

Customer Sign: [Signature] Service Person Sign: [Signature]
 Customer Name: ကျော်စွာစော Service Person Name: TSC-VO, B100

Service Sign Service Sign Service Sign Service Sign	Comment <u>Carefully</u>	Note Estimate Time STD Job Time (min) Actual Job Time (min)
	Comment _____	Note (TD) Time Customer Comments



SERVICE REPORT

Job Order No: MMJ JR 128/09/1355
 Customer Name: U Win Hlaing
 Machine Location: Ohn Chaw
 Machine Model: SF 290
 Machine SN No: SF 290 AB 000029
 Engine Brand: Cummins
 Engine Model: B5.9-C
 Engine SN No: J5245030
 Hour Meter (hr) Km: 250.3 hr
 Job Site Distance: ~ 30 miles
 Application: Logging
 Number of Trip: 1

	Date	Time
Customer Call Date		
Confirm with Customer		
Go to Job Site Time	5:09 PM	10:07 AM
Arrival Job Site Time		11:22 AM
Job Start Time		11:22 AM
Job Finish Time		1:21 PM
Go Back From Site		1:21 PM
Arrival Office Time		
In-Delay Date & Time		
Reason of Job Delay		

Customer Call Problem: Engine oil leakage abnormal.

Type of Problem: Injection pump abnormal and senses leakage.

Service Action: When we arrived on job site, firstly we check around to machine. We found that injection pump is oil leakage. Then we cleaned around oil leakage with diesel. And checked lubri oil level, coolant level condition. Start up to machine and checked oil leakage. Injection pump and senses from back are leaked. So we suggested to customer need to repair.

No.	Part Description	Part No.	Qty	Remark
	<u>Injection</u>			

*On Service Work Done (အပ်ပြုပြင်မှု ကျဆုံးသည့်နေ့မှစ၍ အပ်ဆင်ပေးရန်အတွက် ချက်ချင်းပေးသွင်းရန်)
 *In case must settle within 7days (အပ်ကြောင်းအမျိုးမျိုးကြောင့် ချက်ချင်း ဝေပေးချေနိုင်ပါက (၇)ရက်အတွင်း ပေးချေရမည်)

Customer Sign: [Signature] Service Person Sign: [Signature]
 Customer Name: U Win Hlaing Service Person Name: KHM SEH
 Contact No: 09-881284015 Phone No: 09-96762170

Work Order	Comments	Notes
Service Order: <u>MMJ JR 128/09/1355</u>		
Service Type: <u>Repair</u>		
Service Order	Comments	Notes
Approved By: <u>[Signature]</u>		
Approved Date: <u>11/21/09</u>		