


TOOLS DAMAGE REPORT FORM



Santhemum wealth

PIC Section Name

Machining & Fabrication

Date : 18-2-2025

Reason:

Damage
 Lost


Previous Handover Data

Doc. Refr. No. :

Date Jun'24

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Hand Grinder	4"	Makno	-	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

Hand grinder's armature coil is scorched. So, we repaired it for (2 time). Now, it can't be repaired. We need a new grinder. because of grinding job. in M&F section

Department Head Judgement/ Decision

Reported By

[Signature]
Mechanic

Myo Min Hlue

Checked By

[Signature]
Supervisor

Myo Min Hlue

Approved By

[Signature]
Department Head

Aung Kyaw Thu

Cause of Damage

TOOLS REQUEST FORM

Date: 18/2/25

Request Section

Production

Country Maker

Brand

Types of Tools

- Common Tools
- Measuring Tools
- Installation Tools
- Special Tools

Applicable for

Back Ground History

- More than wiring job in Remon.
- The current model of meter being used now.
- The meters currently in use are not fully functional.

Purpose of Request


To buy a full-function meter.

Required Raw Material (if the tools is made in Local)

No	Tools Name	Dimension	Qty	Unit	Remark
1.	Multimeter.		1	pc	

Requested By


Mechanic

Sign: 

Name SITHA AENG

Checked By


Section Head

Sign: 

Name T.Z.L.

Approved By

Production Manager

Sign: 

Name AKT.

Received By

Admin

Sign: 

Name SSK