



# SERVICE REPORT

UMG

Job Order No MC-TGM-JR-2501105  
 Customer Name UMG 6003085  
 Machine Location U D  
 Machine Model Selena  
 Machine Sr.No AL512AKA5000330  
 Engine Sr.No VZ51P52QMS-6000338  
 Hour Meter or) Km 1km  
 Job Site Distance .....  
 Application .....  
 Number of Trip .....

	Date	Time
Customer Call Date		
Confirm with Customer		
Go to Job Site Time		
Arrival Job Site Time		
Job Start Time	19.1.20.25	1:00 PM
Job Finish Time	19.1.20.25	4:00 PM
Go Back from Site		
Arrival Office Time		
Job Delay Date&Time		
Reason of Job Delay		

OT

Customer Call Problem

Inspection & Repair

Cause of Problem

Service Action

- cover removing front shock absorber dismounting
- shock absorber replacing rear shock absorber dismounting
- front/rear shock absorber corporal salt and painting with
- bring front shock absorber installing cover replacing
- install the cover to machine electrical system inspection
- engine test run

Failure Causal Part

No	Part Description	Part No	Qty	Remark

Service Charges

Customer Sign .....

Service Person Sign *Khaw'g*

Customer Name .....

Service Person Name .....

Checked By

Acknowledge By

Approved By

Name: Khaw'gwin

Name: Saw Elsay Wah

Name: *M. Khaw'g*

Sign: *Khaw'g*

Sign: *el say*

Sign: *M. Khaw'g*

Service Man

Service SH

Service DH

# SERVICE REPORT

Job Order No. MC-YGN-JR-2501204  
 Customer Name LIU GUOJIAO  
 Machine Location UD  
 Machine Model Selena  
 Machine S/N No. 0122312KAS000326  
 Engine S/N No. 31P52DM3G000326  
 Hour Meter (or) Km 1km  
 Job Site Distance \_\_\_\_\_  
 Application \_\_\_\_\_  
 Number of Trip \_\_\_\_\_

	Date
Customer Call Date	
Confirm with Customer	
Go to Job Site Time	
Arrival Job Site Time	
Job Start Time	19 1.29.25 12:15 PM
Job Finish Time	19 1.29.25 12:25 PM
Go Back from Site	
Arrival Office Time	
Job Delay Date&Time	
Reason of Job Delay	

Customer Call Problem

Inspection & Repair

Cause of Problem

Service Action

- covers removing front shock absorber dismounting
- shock absorber replacing rear shock absorber dismounting
- front/rear shock absorber corporal salt and painting with
- bring front shock absorber installing covers Replacing
- install the covers to machine electrical system inspection
- engine test run.

Failure Causal Part

No	Part Description	Part No	Qty	Remark

Service Charges

Customer Sign \_\_\_\_\_ Service Person Sign Khai D  
 Customer Name \_\_\_\_\_ Service Person Name \_\_\_\_\_

Checked By

Name: Wong Wai  
 Sign: [Signature]  
 Service Man

Acknowledge By

Name: Saw Eley Wah  
 Sign: [Signature]  
 Service SH

Approved By

Name: [Signature]  
 Sign: [Signature]  
 Service DH