

SERVICE REPORT



Job Order No MC-KAN-JR-2506437
 Customer Name UMG MOTORS
 Machine Location U.D. SHOWROOM
 Machine Model SELENA
 Machine Sr.No RLQ51GJTBKA500331
 Engine Sr.No
 Houe Meter or) Km
 Job Site Distance
 Application
 Number of Trip

	Date	Time
Customer Call Date		
Confirm with Customer		
Go to Job Site Time		
Arrival Job Site Time		
Job Start Time	<u>9.6.25</u>	<u>5:00pm</u>
Job Finish Time	<u>9.6.25</u>	<u>8:00pm</u>
Go Back from Site		
Arrival Office Time		
Job Delay Date&Time		
Reason of Job Delay		

Customer Call Problem
Repaired job

Cause of Problem
~

Service Action
 We checked the steering system ball steel, lower ring, upper ball, frame, race (strg bot), ball to damage, so new installed steering system. (job in progress)

Faiture Causal Part

No	Part Description	Part No	Qty	Remark

Service Charges

Customer Sign Service Person Sign [Signature]
 Customer Name Service Person Name KTP, IRM, STP

Checked By	Acknowledge By	Approved By
Name : <u>[Signature]</u>	Name :	Name :
Sign: <u>[Signature]</u>	Sign:	Sign:
Service Man	Service SH	Service DH

02-BMC-ASD-FRM-004-01