



No. 89B/99Q, Anawrahta Industrial Zone
Mya Sein Yaung Phayaz Road, Yangon-Pathein Highway Road, Hlaingtharya, Yangon



CLAIM REQUEST FORM

Requestor Name : Nyein Nyein	Budget Type : Include Budget
Department Name: Service (ATT)	Payment Type : Claim Payment
Request Date : 2025-05-26	Prepared By : Zin Nyein Oo(2)
Payment Voucher : EX-ATT-2025-05-00037	Superior Approved : Aung Kyaw Myint(3)
No	By
Payment Method : Cash/Bank	Last Approved By : Aung Kyaw Myint(3)
Payment Amount : 372000.0	
Currency : MMK	
Exchange Rate : 4,440.0	

No.	Description	Department	Request Amount	Remark
1	Branch support, ATT BU To Nyaung-U, Customer-Ko Aye Min Htun, DF60-1873, Problem-Hydraulic function abnormal, PIC-Nay Htun Win	Service Department (ATT)	372,000.00	

Expense Total 372,000.00 K
Additional/Refund

Note:

<p style="text-align: center;"></p> <p style="text-align: center;">Superior Check By Aung</p> <p>Name : <u>Aung Kyaw Myint</u></p> <p>NRC No :</p> <p>Date : <u>26.5.25</u></p> <p>Remark :</p>	<p style="text-align: center;"></p> <p style="text-align: center;">F&A Zin</p> <p>Name : <u>Zin Nyein Oo</u></p> <p>NRC No :</p> <p>Date : <u>26.5.2025</u></p> <p>Remark :</p>	<p style="text-align: center;"></p> <p style="text-align: center;">GM/AGM Ko Myung Myung</p> <p>Name : <u>Ko Myung Myung</u></p> <p>NRC No :</p> <p>Date :</p> <p>Remark :</p>	<p style="text-align: center;"></p> <p style="text-align: center;">COO Aung Kyaw Myint</p> <p>Name : <u>Aung Kyaw Myint</u></p> <p>NRC No :</p> <p>Date :</p> <p>Remark :</p>
--	--	---	--



GENERAL EXPENSE CLAIM FORM



BU/BR/DIV Name : ASU BU
 Department Name : Service department

No.	Date	PIC Name	Description	Category (Customer (Or) Operation)	Cost (MMK)	Remark
1	8.5.25	Nay Hten Win	Fuel change s	Operation	8000 ✓	မှတ်ပုံတင် -> မှတ်ပုံတင်
2	9.5.25	"	"	"	4000 ✓	မှတ်ပုံတင် -> မှတ်ပုံတင်
3	11.5.25	"	"	"	4000 ✓	"
4	12.5.25	"	"	"	5000 ✓	"
5	12.5.25	Aung Hsu Kyaw	Convey charges	"	70000	မှတ်ပုံတင် -> မှတ်ပုံတင်
Total General Expense					725000	

Requested by: Nay Hten Win (Requester)
 Approved by: Mujit Moe Aung (Department Head)
 Checked by: Zin Mar (Finance & Account)
 Approved by: [Signature] (OM/AGM/GM)
 Approved by: [Signature] (ACOO/COO/MD/VCN)

02-ATT-FNA-FRM-002-01

9.5.25
 ... we change the ...
 one hydraulic oil filter.
 we test run the machine
 we found the hydraulic
 lift function abnormal.
 Firstly visual check and
 we check dismounted

Reported by: Nay Hten Win (Section Head)
 Checked by: [Signature] (DH/AGM/GM)
 Approved by: Aung Hten Win (COO)

05-CHL-HRM-FRM-064-01

⇒ Change New hyds; filter.
 Old pump (hyd; oil)
 Old hydraulic control valve. } All BU supply.