LOCAL INVENTORY PURCHASE REQUEST FORM

Member of UMG

BU Name : .....CE3 BU.....

Proposal No. : ...CE3-PRT-2025-02-168.....

Proposal Date : .....22.2.2025.....

Order Type : Service Use

Supplier - A

Name: Ko Bo Bo

Contact No. 09-43095433,09-761635357, 09-978391458

Address ...Building (B/4) Room (7) Corner of Market Circle, Bayint Naung Market Square

Supplier -B

Name...Multipart.....

Contact No....09260144931.../09-5177792.....

Address .....

.....

Supplier - C

Name: MBM HEAVY DUTY MACHINERY SPARE PARTS TRADIND CO.,LTD

Contact No. 09 956510510,09 420709077

Address ...SHOP (4) ,NO.88,MIN GYI MAHAR MIN KHAUNG ROAD,ZONE - 2,HLAING THARYAR

No.	Brand	MC Model	Description	Parts No.	Qty	Price	Amount	Qty	Price	Amount	Qty	Price	Amount
1	Local	ML20	Hydraulic control Valve for ML20	DG926-06100	1	1,800,000	1,800,000		No Stock			No Stock	
Total Amount					1		1,800,000						

Selling Margin	-
Remark	Service use , MR No . (0004/17/02/2025), Hydraulic control valve function abnormal . Model - ML20, Sr no. - 472 (Repossess Machine)

Requested by

Sign :

Name : Soe Yu Nandar

(Inventory)

No Stock

Checked by

Sign :

Name : Hnin Nu Nu Hlaing

(DH)

Acknowledged by

Sign :

Name : Zarni Aung

(AGM/GM)

Approved by

Sign :

Name : Aung Hein Ulin. 24/2/25.

(ASS)

Approved by

Sign : 24/02/2025 Amuthan

Name :

(COO/VCM)

02-CE3-PRT-FRM-003-03

- Old past. ml past inventory ကွင်းဆင်ပြန်ကွင်းပေးရန်

Remark: Normally, there have 2 spool on control valve that is used for bucket tilt and boom up/down function. For bucket tilt function, spool is used with spring tension type & bucket is not used like this. Customer want to used spring type for boom function also. & customer requirement.

CamScanner