

# Ground Damage

No.	Brand	Parts No	Item Description	Excel Closin	Actual	Difference	Damage	Selling Price(\$)	Total Price(\$)	GIA No.	Remark	BU Remark
1	Fleetguard	KW2337-CEIII	Air-Cleaner Element(Inner/Outer) of MR1215.	2	2	0	2	-	-	Not have	Damage(2pc)Old Remark	To make issue Service Use ✓
2	SHANTUI	175-63-13000-CEIII	Kit, Lifting Cyl for SD32	3	3	0	3	-	-	Not have	3 pc damage old remark	To make issue Service Use ✓
3	SHANTUI	23Y-64B-00000-CEIII	Kits, Ripper Cyl; for SD22	4	4	0	4	-	-	Not have	damage old remark	To make issue Service Use ✓
4	Local	J236-64C-000051(L)	Dust Preventive Ring(100*115*4) of ME315	14	14	0	6	5.4	32.4	CE3-GIA-25060013	6pc Damage old remark	Damage(1pc= \$ 5.4) ✓
							<b>Total Qty</b>	<b>15</b>	<b>Total Amount (MMK)</b>	<b>32.4</b>		

*Handwritten signature and date:*  
 13/08/2017  
 A. M. H. Khan





### Concrete Equipment 3

#### Good Issue

Customer Name :  
Address Name :  
Phone/Fax :

GI No : CE3-GIA-25060013  
GI Date : 2025-06-06 11:37:02  
Related to :

No	Description	Parts Number	Qty	UOM
1	Dust Preventive Ring(100*115*4) of ME315	J236-64C-000051(L) 	6.00 	PC

Status : BU/Warehouse( done )

Note : All 6pcs of these parts are damaged because of part life time.

  
6/6/25  
HAL

Prepared By

Approved By

Issued By

Delivery By

Received By

Admin( Name )

PRT Dept Head  
( Only BR )

Warehouse

Salesman/Transporter

Customer