

Date : 21.6.24

BU/BR/Division : MCBU IS BU

Department : Administration

Issue Amount : 200,000 Kyats/ USD

Budget Include (or) Not : urgent Budget

Yes [] Budgeted Title and Amount :
No [] Reasons for :

Required For:
In Server room, Aircon Indoor coil Replacement
မှတ်ချက်။
(၁) အဆင့်ဆင့်သက်ဆိုင်ရာတာဝန်ရှိသူကြီးမင်းများအားလုံး သေချာစွာစစ်ဆေး၊ တွက်ချက်ပြီးထားသော ငွေပမာဏဖြစ်ရပါမည်။
(The amount requested must be properly calculated, checked and verified by respective authorized person)
(၂) ထုတ်ယူငွေနှင့် ပတ်သက်၍ အမှားအယွင်း၊ လိမ်လည်မှု နှင့် အလွဲသုံးစားမှု တစ်စုံတစ်ရာ ရှိခဲ့ပါက၊ သက်ဆိုင်ရာ၊ တာဝန်ရှိစစ်ဆေးအတည်ပြုသူက အပြည့် အဝ ပြန်လည်ရရှိအောင် တာဝန်ယူ ဆောင်ရွက်ပေးရမည်
(If there is errors, frauds or misappropriation, the authorized person must take full responsibility to recover the loss)

Request By

Signature of Requester

Requester

Min Theit Lyau Zin

Checked By

Signature of Manager/DH

Mgr/DH

Thee Mu Aoi

Checked By

Signature of Finance & Account

Finance & Account

Zin Kothkue

Approved By

Signature of GM/AGM/COO

GM/AGM/COO

Chit San ko

Approved By

Signature of CMC/CEO/Chairwoman

CMC/CEO/Chairwoman

04-CFD-CAS-FRM-005-03

Urgent Budget

Check

21/6/24

Signature

Ums Zan

Signature 21/6/24

21/6/24

