



## Concrete Equipment 3

### Good Receipt

**Customer Name** : AIK HTUN LU,U(13/MAHSATA(N)055039)  
**Address** : MUSE TOWNSHIP, TEE MA VILLAGE.  
**Phone** : 09-692525637/09-42786807509-692525637/09-427868075

**GR No** : CE3-GR-25010011  
**GR Date** : 2025-01-14 13:28:09  
**Related No** : CE3-SO-24120004

No	Description	Part Number	From Location	To Location	Qty	UOM
1	Oil return filter element for ME210	Y221-78A-040020-CEIII	Customer	CEIII_Parts	1.00	PC
2	Oil Suction Strainer for ME210	J221-78B-041000(OEM)	Customer	CEIII_Parts	1.00	PC

**Note** : This part is return cause of ME315 & ME210 Model error  
PLO(This Parts Arrived by BU Return arrival on 14.01.2025.  
Checked by SLM

Prepared By

Approved By

Validated By

Related By

BU DH

HO WHS/BU WHS