



No.	Vehicle No.	Repair Date	Referenced Code	Responsible Person	Repair Information	Advance	Actual
1	1E/8720	10-Jul-2024	MCS/R/144	Chan Myae Lwin	Left Door Repair & Lower Inspection & Tyre Changing	26,000 ✓	26,000 ✓
					Left Door Repair Cost=15000ks Lower Inspection & Tyre Changing Service Charges for Charges=11000ks		

Print Date : 13-Jul-2024

Vehicle Repair Information Listing

No. 589-592, New Tha Ka Ta (1), Bo Aung Kyaw Street, Hialing Thar Yar Township, Yangon, Myanmar.

UMG



Prepared By: *[Signature]*

Check By: *[Signature]*

Check and Approve By: *[Signature]*

Approve By: *[Signature]*

Admn: *[Signature]*

Scue Lee Hnin

Zin Mar Lwin

HR.

Then Zee Lin

DM

Making Mhang GM.

13-7-2024