

SZBJ<sup>®</sup>

BM9208



全保护电路

DH

AUTO POWER OFF

SEL

CE

±15°  
cm

NPN

PNP



E

C

B

B

C

HFE

BM9208

V = 

10





同徑

50-160mm

海恒量量

址：上海市

话：021-





# TOOLS DAMAGE REPORT FORM



Date : 8-Aug-2024

Reason:

Damage  
 Lost

Production


Date : Sep' 2022

Previous Handover Data

Ref. No.

No.	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Dial Gauge	-	King Tony	-	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

Can't get accurate measurement, the dial pointers are many points gap. Need new one to ~~make~~ make specified measurement.

Department Head Judgement/ Decision

Long term usage and frequently usage, we have only two dial gauge over many jobs.

For

Reported By

Theet Zawlatt

Mechanic

Checked By

Theet Zawlatt

Supervisor

Approved By

Win Aung

Department Head

02-BRM-PDD-FRM-009-00

Cause of Damage

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6) Consume life of Tools
- 7) Poor maintenance

