

CLAIM PAYMENT FORM

Requestor Name : Thandar Soe(2)
 Department Name :
 Payment Date : 2025-06-27
 Payment Voucher : EX-CE5-2025-06-00015
 No
 Payment Method : Cash/Bank
 Payment Amount : 9060.0
 Currency : MMK
 Exchange Rate : 4,600.0

Budget Type : Include Budget
 Payment Type : Claim Payment
 Prepared By : CE5_ServiceDataEntry
 Superior Approved : Hein Thiha Soe
 By
 Last Approved By : CFD Cashier


No.	Description	Department	Paid Amount	Remark
1	Claim Charges for Overtime Charges for ME220*1U#SH02349(23/6/2025) this machines are needed to change Arm Frame Dust Seal and to dismount broken track guard bolt (in CNC Yard) as repair purpose from Service Department- OT Assign Person-Yee Myo Min, Thura Aung, Pyae Sone Khant. Issued By- Thandar Soe, Issued Amount-9,060MMK.	Service Department(CE5)	9,060.00	Claim Charges for Overtime Charges for ME220*1U#SH02349(23/6/2025) this machines are needed to change Arm Frame Dust Seal and to dismount broken track guard bolt (in CNC Yard) as repair purpose from Service Department- OT Assign Person-Yee Myo Min, Thura Aung, Pyae Sone Khant. Issued By- Thandar Soe, Issued Amount-9,060MMK.


Expense Total 9,060.00 K
 Additional/Refund

Note: _____

Paid _____

Description: _____

Paid By

 Name : Soe Myo Tan
 NRC No : 31/01/PC/2165117
 Date : 29/06/25

Received By

 Name : K. N. P. O. 287-44
 NRC No : 287-44
 Date : 29-6-25



CLAIM REQUEST FORM





Requestor Name : Thandar Soe(2)
 Department Name :
 Request Date : 2025-06-24
 Payment Voucher : EX-CE5-2025-06-00015
 No
 Payment Method : Cash/Bank
 Payment Amount : 9060.0
 Currency : MMK
 Exchange Rate : 4,600.0

Budget Type : Include Budget
 Payment Type : Claim Payment
 Prepared By : CE5_ServiceDataEntry
 Superior Approved : Hein Thiha Soe
 By
 Last Approved By : Hein Thiha Soe

No.	Description	Department	Request Amount	Remark
1	Claim Charges for Overtime Charges for ME220*1U#SH02349(23/6/2025) this machines are needed to change Arm Frame Dust Seal and to dismount broken track guard bolt (in CNC Yard) as repair purpose from Service Department- OT Assign Person-Yee Myo Min, Thura Aung, Pyae Sone Khant. Issued By- Thandar Soe, Issued Amount-9,060MMK.	Service Department(CE5)	9,060.00	Claim Charges for Overtime Charges for ME220*1U#SH02349(23/6/2025) this machines are needed to change Arm Frame Dust Seal and to dismount broken track guard bolt (in CNC Yard) as repair purpose from Service Department- OT Assign Person-Yee Myo Min, Thura Aung, Pyae Sone Khant. Issued By- Thandar Soe, Issued Amount-9,060MMK.

Expense Total 9,060.00 K
 Additional/Refund

Note:

<p>Superior Check By  Name : Shi Nan ko NRC No : Date : Remark :</p>	<p>F&A  Name : Tin Zan Hlaing NRC No : Date : Remark :</p>	<p>GM/AGM  Name : Aung Thu Win NRC No : Date : Remark :</p>	<p>COO  Name : Aye Min Htoon NRC No : Date : Remark :</p>
--	--	--	---

MG

OVERTIME REQUEST FORM

DIV Name : Mandalay Resources

Department Name : Service

Reason for Overtime : To change Arm frame dust seal and to dismount broken track guard bolts

No.	Date	Name	Position Level	Time		Hours	Amount	Remark
				From	To			
1.	23-6-25	Yee Myo Min	SH	5:30PM	7:30PM	2H	30 20	This machine are needed to change
2.	23-6-25	Thara Aung	Mechanic	5:30PM	7:30PM	2H	30 20	arm frame dust seal and to
3.	23-6-25	Pyaeone Kha nt	Mechanic	5:30PM	7:30PM	2H	30 20	dismount broken track guard bolts for ME220XU# SHO 2349

Total Hours	6H	9060
Total Amount		

Requested by

Sign :

Name : Phandar Obe
(Requestor)

Approved by

Shi Nari Ko
(DH)

Approved by

Aung Thee Win
(GM/AGM/COO)

Checked by

Moe Thazin
(HR)