





CGD & PG BU
16 members



CGD & PG BU
16 members



Dear Sayar U Aye Min Htoon and
Ko Zaw Min Myat

Rental မှ 350KVA မီးစက်

Model..MVP 370S
Sr no...2012651908
Hr..8729hr
Problem... Engine Can't start
Root Cause...EECU fault
Location..HO

Engine Can't start problem ဖြစ်နေ
သည့်အတွက် PG BU service team
မှ အဖြေရှာ ပြုပြင်ပေးနေပါတယ်။

လက်ရှိ စစ်ဆေးပီးတဲ့ နောက်ပြစ်ချက်
မှာ EECU fault ဖြစ်နေသည့်အတွက်
EECU ပြင်ရန် သို့မဟုတ် လဲရန် အကြံ
ပြုလာပါတယ် ခင်ဗျ။

EECU အသစ်မှာ လက်ရှိ stock မရှိ
သည့်အတွက် မှာချိန် ကြာမည့်အပြင်
ဈေးနှုန်းလဲ(Est cost..\$3000) များ
တာကြောင့် Urgent Budget တင်ပေး
EECU ကို ပြုပြင် ခွင့်ပြုရန် ခွင့်တောင်း
ပါတယ် ခင်ဗျ။

EECU repair charge...1350000mmk
Repair time .3days
Warranty...3months

🙏 12:01 PM ✓

Ko Zaw Myint Myat admin

Aung Ko Oo
Dear Sayar U Aye Min Htoon...

Pls proceed to fix the problem
with urgent budget

12:23 PM

Ko Zaw Myint Myat
Pls proceed to fix the probl...



EECU repair charge... 1350000mmk
Repair time .3days
Warranty...3months

🙏 12:01 PM ✓

Ko Zaw Myint Myat admin

Aung Ko Oo
Dear Sayar U Aye Min Htoon...

Pls proceed to fix the problem
with urgent budget

12:23 PM

Ko Zaw Myint Myat
Pls proceed to fix the probl...



12:24 PM ✓

Aye Min Htoon

Aung Ko Oo
Dear Sayar U Aye Min Htoon...

Please proceed MMK 1,350,000
to repair.

5:10 PM

Aye Min Htoon
Please proceed MMK 1,35...



5:31 PM ✓



Message

