


TRAVELLING REPORT

Date :

Report To		
Employee Name	Nay Han Wan	
Position	SA	
Department	Service	
Business	AGU B2	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
Total Days		
Trip Information	1. From AGU B2 To 1.2.14.14	
	2. From To	
	3. From To	
Purpose For Travelling	Hydraulic function abnormal	
Travel Date	Activities	Remark
	Our Service team Firstly visual check all oil level checked, And then we test run the machine and we check the hydraulic function It's OK. But engine RPM abnormal. So, we check the fuel line we found the fuel auto pump damage	

Reported by
 Sign : 
 Name : Nay Han Wan
 Position : Section Head

Checked by
 Sign :
 Name :
 Position :

(DH/AGM/GM)

Approved by
 Sign :
 Name :
 Position :

(COO)

05-CHL-HRM-FRM-064-01

TRAVELLING REPORT

Therefore we change the new on fuel auto pump and test run with load. It's ok. Job was finished

Remarks	Activities	Travel Date
	<p>On 10/10/2023, we replaced the fuel auto pump on the vehicle and conducted a test run with a load. The operation was successful, and the vehicle is now running smoothly. The job was completed on the same day.</p>	

