



KHIN MAUNG TUN,U
No (180/4) (29) Ward , Kauk Lyin Street ,
Thuwana Thingangyun Yangon Myanmar

Invoice SI-SER-ISU-2023-10-00086

Invoice Date:
10/12/2023

Due Date:
10/12/2023

Source:
SV-ISU-2023-10-00059

Description	Quantity	Unit Price	Taxes	Amount
Service Charges for Steering Power Pipe Changed	1.00 PC	11.26	5%	\$ 11.26
Service Charges for Steering Oil Pipe Dismounted and Mounted	1.00 PC	9.00	5%	\$ 9.00
Untaxed Amount				\$ 20.26
Taxes on \$ 20.26				\$ 1.01
Total				\$ 21.27

Please use the following communication for your payment : **SI-SER-ISU-2023-10-00086**

Service Charges for Steering Power Pipe Changed and Steering Oil Pipe Dismounted and Mounted (serial number-LA61AAA7XKB509657#2R-4389#10530 KM#JR-23/09/0777#INV NO-202309063)