

Print Date : 08-Jul-2025

Monthly Kilo Record

Vehicle No	Holding Business	Out Date	Time Out	In Date	Time In	Start Kilo	End Kilo	Different Kilo	Purpose	Way	Driver Name	Remark
5J/4048	Construction Equipment 2	2025-06-02	06:15	2025-06-02	18:49	206,275	206,334	59	Ho to Reman,Recon & CNC to check stock maintenance and to repair inline pump in reman and then bring to home (Shwe Pauk Kan).	CNC,Recon ,Reman	Thandar Soe(2)	Ho to Reman,Recon & CNC to check stock maintenance and to repair inline pump in reman and then bring to home (Shwe Pauk Kan).
5J/4048	Construction Equipment 2	2025-06-03	06:10	2025-06-03	18:52	206,334	206,411	77	Go to Recon & CNC to check stock maintenance and go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan).	CNC,Recon ,Bayint Naung	Thandar Soe(2)	Go to Recon & CNC to check stock maintenance and go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan).
5J/4048	Construction Equipment 2	2025-06-04	06:04	2025-06-04	18:39	206,411	206,459	48	Go to CNC to check stock maintenance and go to Reman to repair Compressor and then bring to home.(Shwe Pauk Kan)	CNC,Reman	Sai Nan Ko	Go to CNC to check stock maintenance and go to Reman to repair Compressor and then bring to home.(Shwe Pauk Kan)
5J/4048	Construction Equipment 2	2025-06-05	06:10	2025-06-05	18:40	206,459	206,520	61	Go to CNC,Recon to check stock maintenance and go to HO to take a sign and to take accessories for machine GI from Warehouse and then bring to home.	CNC, Recon,HO	Sai Nan Ko	Go to CNC,Recon to check stock maintenance and go to HO to take a sign and to take accessories for machine GI from Warehouse and then bring to home.
5J/4048	Construction Equipment 2	2025-06-06	06:15	2025-06-06	18:19	206,520	206,608	88	Go to Mindama to take budget ang go to CNC to check stock maintenance ang go to HO to take a Diesel Sign and then bring to home (Shwe Pauk Kan)	Mindama,HO,CNC	Sai Nan Ko	Go to Mindama to take budget ang go to CNC to check stock maintenance ang go to HO to take a Diesel Sign and then bring to home (Shwe Pauk Kan)
5J/4048	Construction Equipment 2	2025-06-07	06:30	2025-06-07	18:15	206,608	206,658	50	Go to COP to make machine inspection and repair for ready to sale for ZX210LCH-5GX1U#305145 and then bring to home (Shwe Pauk Kan)	COP	Sai Nan Ko	Go to COP to make machine inspection and repair for ready to sale for ZX210LCH-5GX1U#305145 and then bring to home (Shwe Pauk Kan)
5J/4048	Construction Equipment 2	2025-06-09	06:04	2025-06-09	18:25	206,658	206,714	56	Go to CNC to check stock maintenance and go to Z5 to testing Controller From MYK BR and then bring to home.(Shwe Pauk Kan)	CNC,Z5	Sai Nan Ko	Go to CNC to check stock maintenance and go to Z5 to testing Controller From MYK BR and then bring to home.(Shwe Pauk Kan)

Vehicle No	Holding Business	Out Date	Time Out	In Date	Time In	Start Kilo	End Kilo	Different Kilo	Purpose	Way	Driver Name	Remark
5J/4048	Construction Equipment 2	2025-06-10	06:10	2025-06-10	18:40	206,714	206,812	98	Go to CNC, Recon to check stock maintenance and go to HO (3 times) to take GI and to take a sign and go to Z5 to take Under Cover and then bring to home.(Shwe Pauk Kan)	CNC, Recon,HO,Z5	Sai Nan Ko	Go to CNC, Recon to check stock maintenance and go to HO (3 times) to take GI and to take a sign and go to Z5 to take Under Cover and then bring to home.(Shwe Pauk Kan)
5J/4048	Construction Equipment 2	2025-06-11	06:19	2025-06-11	18:40	206,812	206,891	79	Go to CNC (2 times) to check stock maintenance and go to Thama Gone to buy accessories and go to Pagoda Road to make Battery Charging and then bring to home. (Shwe Pauk Kan)	CNC,Thama Gone, Pagoda Road	Sai Nan Ko	Go to CNC (2 times) to check stock maintenance and go to Thama Gone to buy accessories and go to Pagoda Road to make Battery Charging and then bring to home. (Shwe Pauk Kan)
5J/4048	Construction Equipment 2	2025-06-12	06:01	2025-06-12	18:25	206,891	206,987	96	Go to CNC, Recon to check stock maintenance and go to HO to take GI and go to Reman to take Repair machine Accessories and then bring to home.(Shwe Pauk Kan)	CNC, Recon,HO,Reman	Sai Nan Ko	Go to CNC, Recon to check stock maintenance and go to HO to take GI and go to Reman to take Repair machine Accessories and then bring to home.(Shwe Pauk Kan)
5J/4048	Construction Equipment 2	2025-06-13	06:04	2025-06-13	18:40	206,987	206,998	11	Go to CNC to check stock maintenance and then bring to home (Shwe Pauk Kan.)	CNC	Thandar Soe(2)	Go to CNC to check stock maintenance and then bring to home (Shwe Pauk Kan.)
5J/4048	Construction Equipment 2	2025-06-14	06:04	2025-06-14	18:45	206,998	207,006	8	Go to UD to repair car body & engine can't start for 5J/4048 .	UD	Thandar Soe(2)	Go to UD to repair car body & engine can't start for 5J/4048 .
5J/4048	Construction Equipment 2	2025-06-25	00:49	2025-06-25	18:49	207,006	207,098	92	Go to Recon ,Reman ,CNC to check stock maintenance and then go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan.)	CNC, Recon,Reman, Bayint Naung	Thandar Soe(2)	Go to Recon ,Reman ,CNC to check stock maintenance and then go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan.)/14-Jun-25 to 24-Jun-25 (Car Repair in UD WS)
5J/4048	Construction Equipment 2	2025-06-26	06:15	2025-06-26	18:30	207,098	207,197	99	Go to Recon ,CNC to check stock maintenance and then go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan.)	Recon ,CNC, Bayint Naung	Thandar Soe(2)	Go to Recon ,CNC to check stock maintenance and then go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan.)
5J/4048	Construction Equipment 2	2025-06-27	06:15	2025-06-27	18:30	207,197	207,288	91	Go to Recon ,CNC,Z5 to check stock maintenance and then go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan.)	CNC,Recon ,Z5, Bayint Naung	Thandar Soe(2)	Go to Recon ,CNC,Z5 to check stock maintenance and then go to Bayint Naung to buy accessories and then bring to home (Shwe Pauk Kan.)

Vehicle No	Holding Business	Out Date	Time Out	In Date	Time In	Start Kilo	End Kilo	Different Kilo	Purpose	Way	Driver Name	Remark
5J/4048	Construction Equipment 2	2025-06-28	06:19	2025-06-28	18:30	207,288	207,393	105	Go to HO(3 times) to take a sign and go to CNC,Recon ,Winfood to chck machine inspection and to make stock maintenance ang then bring to home(Shwe Pauk Kan)	HO,CNC,Recon, Winfood	Thandar Soe(2)	Go to HO(3 times) to take a sign and go to CNC,Recon ,Winfood to chck machine inspection and to make stock maintenance ang then bring to home(Shwe Pauk Kan)
5J/4048	Construction Equipment 2	2025-06-30	06:25	2025-06-30	18:40	207,393	207,453	60	Go to Recon ,CNC to check stock maintenance and then bring to home (Shwe Pauk Kan.)	CNC, Recon	Thandar Soe(2)	Go to Recon ,CNC to check stock maintenance and then bring to home (Shwe Pauk Kan.)