



My Company

GEO ASIA INDUSTARY AND MINNING CO.,LTD  
PYAY NYAUNG VILLAGE Thazi Meiktila  
Myanmar  
9453690491

# Invoice SI-SER-MDY-1-2024-12-00034

**Invoice Date:**  
12/27/2024

**Due Date:**  
12/27/2024

**Source:**  
SV-MDY-1-2025-01-00027

Description	Quantity	Unit Price	Taxes	Amount
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for engine wire harness overhaul</i> EC290BP (#19732) MDY/JR/24/12/1403	1.00 PC	400,000.00		400,000.00 K
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for final drive resealing</i> EC290BP (#19732) MDY/JR/24/12/1403	2.00 PC	250,000.00		500,000.00 K
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for boom dismounting &amp; mounting and boom cylinder resealing</i> EC290BP (#19732) MDY/JR/24/12/1403	2.00 PC	600,000.00		1,200,000.00 K
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for bucket dismounting &amp; mounting and bucket cylinder resealing</i> EC290BP (#19732) MDY/JR/24/12/1403	1.00 PC	400,000.00		400,000.00 K
<b>Total</b>				<b>2,500,000.00 K</b>

Please use the following communication for your payment : **SI-SER-MDY-1-2024-12-00034**