








Damage Photo for CE1 Parts

No	Product Code	Trim	Product Name	Qty	Pprice	Total	Photo	Remark
1	11110022	11110022	Air Filter (out)	4	56.46	225.84		For Repossess Machine 3pc ထုတ်ရန်/ 1 PC Scrap လုပ်ရန် ✓
2	11110175	11110175	Filter (out - air cleaner)	4	45.60	182.40		For Repossess Machine 2pc ထုတ်ရန်/ 2 PC Scrap လုပ်ရန် ✓
3	11110176	11110176	Air Filter(In)	1	32.67	32.67		To Issue Scrap လုပ်ရန် ✓
4	11110533	11110533	Air Filter (in)	1	41.02	41.02		To Issue Scrap လုပ်ရန် ✓
5	14503269	14503269	Filter	2	21.68	43.36		To Issue Scrap လုပ်ရန် ✓ 1- scrap 1- Repossess
6	14513715 (N)	14513715 (N)	Seal Kit (Arm Cyl:)	1	1.50	1.50		To Issue Scrap လုပ်ရန် ✓

7	195-13-13420	195-13-13420	Element Strainer, Torque Converter	2	3.46	6.92		To Issue Scrap လုပ်ရန် ✓
8	6I0273T	6I0273T	Air Filter (In+Out)	5	35.37	176.85		To Issue Scrap လုပ်ရန် ✓
9	20966749	20966749	Cylinder Liner kit	1	529.79	529.79		X Liner မကောင်း Piston ကောင်း၍ ထားထားသည် ✓
10	980832	980832	Plastic Pipe (15m, 1pack)	1	6.62	6.62		Service Use ထုတ်ရန် about 3' ✓ To give to PMC (FOC)
11	11033996	11033996	Air Filter (out)	4	54.86	219.44		For Repossess Machine Remark နှင့် ထားရန် ✓ EC290, EC300
12	07000-05165	07000-05165	O-Ring, Final Drive Case	1	0.35	0.35		To Issue Scrap လုပ်ရန် ✓
13	20998367	20998367	Water Separator (Primary)	19	43.65	829.35		To Issue - 19/ Damage all Scrap လုပ်ရန် ✓


21	JX1008L	JX1008L	Engine oil filter	4	6.25	25.00		5 hanku ထုတ်၍ Scrap လုပ်မည် Rush
			Total Amount	61		2,569.17		


* To proceed as to comments in Remark Column.



Prepared By
S'Part Admin
Zaw Myo


Checked By
S'part DH
Aye Theingi Myint


Anknowledge By
F&A Head
Saw Nan Hlaing


Anknowledge By
GM/OM
Min Thu Ya
Zaw Min Myat


Approved By
GM(After Sale Division)
Aung Hein Win


Approved By
COO(After Sale Division)
Aye Min Htoon

On ground KEWH စစ်ဆေးတာကြောင့် VCM တံတိုက်ပြန်ဖြတ်ပေးရန်။