



My Company



win motors

No. 898/990, Anawrahta Industrial Zone
Mya Sein Young Phayar Road, Yangon-Pathein Highway Road, Hlaingtharya, Yangon



ADVANCE CLEAR VOUCHER

Requestor Name : Nyein Nyein	Budget Type : Include Budget
Department Name : Service (ATT)	Payment Type : Advance Clearing
Payment Date : 2025-01-06	Advance No : ADV-ATT-2024-12-00063
Payment Voucher No : AC-ATT-2025-01-00011	Prepared By : ATT-Service
Payment Method : Cash/Bank	Superior Approved By : ATT-Service
Payment Amount : 226500.0	Last Approved By : ATT-Service
Currency : MMK	
Exchange Rate : 4,540.0	

No.	Description	Department	Request Amount	Remark
1	Branch support, ATT To MTL BR, Customer - DawTin Tin Sint, DF75-44123, Problem-Oil leakage 4W shaft seal and engine rpm abnormal, PIC-Nay Htun Win	Service Department (ATT)	226,500.00	Branch support, ATT To MTL BR, Customer - DawTin Tin Sint, DF75-44123, Problem-Oil leakage 4W shaft seal and engine rpm abnormal, PIC-Nay Htun Win

Expense Total	226,500.00 K
Advance Total	200,000.00 K
Additional	26,500.00 K

Note: Branch support, ATT To MTL BR, Customer - DawTin Tin Sint, DF75-44123, Problem-Oil leakage 4W shaft seal and engine rpm abnormal, PIC-Htun Win

Superior Check By	F&A	GM/AGM	COO
Name : <u>Ma Zin Mar</u>	Name : <u>Ma Zin Mar</u>	Name : <u>Ma Zin Mar</u>	Name : <u>Ma Zin Mar</u>
NRC No : _____	NRC No : _____	NRC No : _____	NRC No : _____
Date : <u>7.1.25</u>	Date : <u>7.1.25</u>	Date : <u>7.1.25</u>	Date : <u>7.1.25</u>
Remark : _____	Remark : _____	Remark : _____	Remark : _____

- BR MP were using at GEO ASIA Project and can not handle job by BR.

- Proper lead time and proper job handling by BU service.