



No.898, Thudamar (4/6), Anawrahta Industrial Zone, Patheingyi Highway Road, Hlaing Thar Yar Township, Yangon
 Tel : + 95(1) 645 410, 645 420
 Fax:

ADVANCE CLEARING

Voucher No. : ATT-AC2024080017

To : Swe Lae Hnin

Voucher Date : 2024-08-07

Advance No : ATT-ADV2024070157

Currency : MMK Rate : 0.00018519

Cashier :

Payment Method	Status
Cash On Hand - MMK - ATT	posted

No.	Description	Track - 1	Track - 2	Amount
1	Advance Clear fo Car Repair Charges for 7L/6062 PIC-Thar Zaw Lin (ADV KS-250,000/-, EXP KS -250,000/-, REF KS- 0/-)			250000.00

Advance Total :	250000.00
Expense Total :	250000.00
Refund / Collect :	0.00

Note : Swe Lae Hnin [ATT-EM-0104]. Advance Clear fo Car Repair Charges for 7L/6062 PIC-Thar Zaw Lin (ADV KS-250,000/-, EXP KS -250,000/-, REF 0/-)

Date : 2024.08.07 Name/NRC No : Ei Hnwe Ngone Signature : [Signature]
71 Thar Zaw Lin (N) 115393

Total Att - 4000E
 vs - 1000E



CASH ADVANCE CLEAR FORM

Date : 2.8.2024

BU/BR/Division : ATT

Department : Marketing

Advance Issue : 250,000 Kyats / USD

No	Issue Time	Date	Payment Voucher No	Amount		Descriptions
				USD	Kyats	
1	1 st Time Advance	26.7.2024	ATT-ADV2024 070157	7	250,000K	Car Repair Charges
2	2 nd Time Advance					For 7L/6062
3	3 rd Time Advance					PIC - Thar Zaw Lin
Total Advance					250,000K	
Total Actual					250,000K	
Balance Refund/Additional					0	

Request By

Checked By

Checked By

Approved By

Approved By

[Signatures]



ကိုဏ်မင်းအောင်

ကားဘော်ဒါ ဆေးမှုတ်လုပ်ငန်း

☎ : 09-422534608, 09-777464040

Name: Car No: 7L.6062 Type of Car: 27.7.24

No.	Description	Qty	Price	Amount
①	ရောင်ဖျက်ပေးရန် ပြုပြင်မှု	1	250000	250000
②	ဖွင့်ပြုပြင်မှု ပြုပြင်မှု	1	250000	250000

0124 ခုစုပေါင်းသင့်ငွေ 250000%

ကြိုတင်သင့်ငွေ
ကျန်ငွေ

Signature

Print Date : 02-Aug-2024

Vehicle Repair Information Listing

No.	Vehicle No	Repair Date	Referenced Code	Responsible Person	Repair Information	Amount	Status	Advance		Voucher No.	Actual Repaired
								Acknowledge By	Approve By		
1	7L/6062 Dmax	25-Jul-2024	MCS/R/144 95	Than Zaw Lin	To fix the insufficient roof of the car	250,000	✓				To fix the insufficient roof of the car

Prepare By: Swe Loe Hnin Admin

Check By: Loe Loe Mon HR.

Check By: Than Zaw Lin OM

Approve By: Maung Aung Aung

