



My Company

GEO ASIA INDUSTARY AND MINNING CO.,LTD
PYAY NYAUNG VILLAGE Thazi Meiktila
Myanmar
9453690491

Invoice SI-SER-MDY-1-2024-12-00033

Invoice Date:
12/27/2024

Due Date:
12/27/2024

Source:
SV-MDY-1-2025-01-00026

Description	Quantity	Unit Price	Taxes	Amount
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for main control valve dismounting & mounting and resealing EC290BP (#19732) MDY/JR/24/12/1403</i>	1.00 PC	1,100,000.00		1,100,000.00 K
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for main pump dismounting & mounting and resealing EC290BP (#19732) MDY/JR/24/12/1403</i>	1.00 PC	1,000,000.00		1,000,000.00 K
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for swing drive dismounting & mounting and resealing EC290BP (#19732) MDY/JR/24/12/1403</i>	1.00 PC	800,000.00		800,000.00 K
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Service charges for swing motor dismounting & mounting and resealing EC290BP (#19732) MDY/JR/24/12/1403</i>	1.00 PC	600,000.00		600,000.00 K
[External_Service_Product_MDY-1] External_Service_Product_MDY-1 <i>Main wire harness overhaul charges EC290BP (#19732) MDY/JR/24/12/1403</i>	1.00 PC	1,100,000.00		1,100,000.00 K
Total				4,600,000.00 K

Please use the following communication for your payment : **SI-SER-MDY-1-2024-12-00033**