



ADVANCE PAYMENT FORM

Requestor Name : Thandar Soe(2)
 Department Name :
 Payment Date : 2025-03-06
 Payment Voucher : ADV-COP-2025-03-00001
 No
 Payment Method : Cash/Bank
 Payment Amount : 4000000.0
 Currency : MMK
 Exchange Rate : 4,480.0

Budget Type : Include Budget
 Payment Type : Advance Payment
 Advance Due Date : 03/20/2025
 Prepared By : COP_BudgetDataEntry
 Superior Approved : F&AManagerCOP
 By
 Last Approved By : Budget-Management

No.	Description	Department	Paid Amount	Remark
1	Advanced Pay For Chain Repair Charges(Track Link Ton 20 PIN + Bushing Dismounted / Mounted ,Track Shoe Dismounted / Mounted & Crane Charges) , Broken Bolt Remover,Idler Repiar & Aircon Gas Refill & Rent Generator Fees For ME220X1U # SHO2089 (Repossessed Machine) as repair purpose From Service Department For Ready to Sale. Advanced Amount - 4,000,000 MMK.Issue By - Thandar Soe.	Service Department(COP)	4,000,000.00	Advanced Pay For Chain Repair Charges(Track Link Ton 20 PIN + Bushing Dismounted / Mounted ,Track Shoe Dismounted / Mounted & Crane Charges) , Broken Bolt Remover,Idler Repiar & Aircon Gas Refill & Rent Generator Fees For ME220X1U # SHO2089 (Repossessed Machine) as repair purpose From Service Department For Ready to Sale. Advanced Amount - 4,000,000 MMK.Issue By - Thandar Soe.

Expense Total 4,000,000.00 K
 Amount Remain 4,000,000.00 K

Note: -----

Paid By *Hlaing*
 Name : Bu Su Hlaing
 NRC No : 91622000 (W) 258879
 Date : 6/03/25

*gen**
 Received By
 Name : Zin Ma Hlaing
 NRC No : 91622000 (W) 258879
 Date : 6.3.25

45

No. 152, Hlaingtharya Industrial Zone (4)
Min Gyi Mahar Min Street, Hlaingtharya, Yangon

ADVANCE REQUEST FORM

Requestor Name : Thandar Soe(2)	Budget Type : Include Budget
Department Name :	Payment Type : Advance Payment
Payment Date :	Advance Due Date : 03/20/2025
Payment Voucher : ADV-COP-2025-03-00001	Prepared By : COP_BudgetDataEntry
No	Superior Approved : F&AManagerCOP
Payment Method : Cash/Bank	By
Payment Amount : 4000000.0	Last Approved By : COP_BudgetDataEntry
Currency : MMK	
Exchange Rate : 4,500.0	

No.	Description	Department	Request Amount	Remark
1	Advanced Pay For Chain Repair Charges(Track Link Ton 20 PIN + Bushing Dismounted / Mounted ,Track Shoe Dismounted / Mounted & Crane Charges) , Broken Bolt Remover, Idler Repair & Aircon Gas Refill & Rent Generator Fees For ME220X1U # SHO2089 (Repossessed Machine) as repair purpose From Service Department For Ready to Sale. Advanced Amount - 4,000,000 MMK. Issue By - Thandar Soe.	Service Department(COP)	4,000,000.00	Advanced Pay For Chain Repair Charges(Track Link Ton 20 PIN + Bushing Dismounted / Mounted ,Track Shoe Dismounted / Mounted & Crane Charges) , Broken Bolt Remover, Idler Repair & Aircon Gas Refill & Rent Generator Fees For ME220X1U # SHO2089 (Repossessed Machine) as repair purpose From Service Department For Ready to Sale. Advanced Amount - 4,000,000 MMK. Issue By - Thandar Soe.

Expense Total 4,000,000.00 K
Amount Remain 4,000,000.00 K

Note:

<p>Superior Check By Name : <u>Sai Naik Ko</u> NRC No : _____ Date : <u>4.3.25</u> Remark : _____</p>	<p>F&A Name : <u>Lin Za Hsing</u> NRC No : _____ Date : <u>4.3.25</u> Remark : _____</p>	<p>GM/ASM Name : <u>Aung Thu Win</u> NRC No : _____ Date : <u>4.3.25</u> Remark : _____</p>	<p>COP Name : <u>Aye Min Hoon</u> NRC No : _____ Date : <u>4.3.25</u> Remark : _____</p>
---	--	---	--



Ko Aung Thu
last seen recentl



OK NYI 7:49 AM

March 3

Forwarded from

Thandar Soe

Advanced Pay For Chain
Repair Charges(Track Link
Ton 20 PIN + Bushing
Dismounted / Mounted ,Track
Shoe Dismounted / Mounted &
Crane Charges) , Broken Bolt
Remover,Idler Repiar & Aircon
Gas Refill & Rent Generator
Fees For ME220X1U # SH02089
(Repossessed Machine) as
repair purpose From Service
Department For Ready to Sale.
Advanced Amount - 4,000,000
MMK.Issue By - Thandar Soe.

4:19 PM ✓✓

အကိုရေ

Budget တင်ဖို့ လေး စစ်ပေးပါဦး

4:20 PM ✓✓

Thandar Soe

Advanced Pay For Chain Repair Ch...

Ok

Pls proceed as advance

4:41 PM



Message

