

TRAVELLING REPORT

Date : 9.5.25.....

Report To	COO	
Employee Name	Arkes Mm	
Position	Senior Mechanic	
Department	Production	
Business	A00 BU	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
Total Days		
Trip Information	1. From A77 To 6.5.25 87	
	2. From To	
	3. From To	
Purpose For Travelling	Shooting hydraulic function abnormal	
Travel Date	Activities	Remark
9.5.25	Our service team, firstly check the oil level. And then we test the hydraulic function is abnormal. So we was check the hydraulic link assembly and cleaning. Hydraulic link is abnormal. So we was repair and testing. It was Ok. And clutch function. testing. Next it abnormal. So we was change the clutch servo (copper) and we test the maching. It was Ok.	

Reported by
 Sign : *[Signature]*
 Name : Arkes Mm
 Position : Jr. Mechanic

Checked by
 Sign :
 Name : Ko Mang Mang
 Position : GM

Approved by
 Sign :
 Name :
 Position :

(DH/AGM/GM)

(COO)

10.5.25. Our service team check the steering Func abnormal. So we was cleaning the steering hydraulic gether and we was change the steering control unit. And we test the steering function. It was ok. Job was finished.

Job No.	Customer Name	Vehicle Make & Model	Year	Color	Engine No.	Chassis No.	Work Done	Technician	Supervisor
							Our service team check the steering Func abnormal. So we was cleaning the steering hydraulic gether and we was change the steering control unit. And we test the steering function. It was ok. Job was finished.		

