

Agriculture Tractor And Truck

Purchase Order

Document Number : ATT-PRT-PO-23070007
Document Date : 2023-07-13
Ref No. : SPO/LOVOL/2023/03/026

Supplier : HI-BRIGHT INTERNATIONAL CO., LIMITED
Contact Person : Charlie Chan, MR
Tel No : 0086-0536-8285038/+86-0536-82859290086-0536-8285038/+86-0536-8285929

Purchase Type : DAF
Currency : USD
Freight :

Fax No :
Email : yongningc@163.com
Address : Room 1917, Building No.7, Sunshine City Plaza 100, No.5051 East Shengli Street, WEIFANG, SHANDONG, CHINA.

| No | Product | Description | UOM | Wet(kg) | Qty | Price | Dis(%) | Amount |
|----|--------------------|--|-----|---------|--------|--------|--------|----------|
| 1 | RGV1401020003K | Jockey Pully Assembly(carrier) (RV01401140003) | PC | | 14.00 | 33.01 | | 462.14 |
| 2 | RGV1401020001K | Thrust Wheel Assembly | PC | | 50.00 | 39.91 | | 1,995.50 |
| 3 | DV01302000131K | Vertical Auger Weldment | PC | | 20.00 | 34.76 | | 695.20 |
| 4 | RV03201000601 | Front Concave plate assembly | PC | | 4.00 | 50.94 | | 203.76 |
| 5 | RGV1306020005K | Lower box assembly | PC | | 2.00 | 135.06 | | 270.12 |
| 6 | RV01306050022 | 15 Teeth Bevel Gear | PC | | 20.00 | 3.68 | | 73.60 |
| 7 | DV01401060010 | Track Roller Oil Seal Subassembly | PC | | 150.00 | 5.80 | | 870.00 |
| 8 | RV03201000602 | Back Concave plate assembly | PC | | 4.00 | 49.19 | | 196.76 |
| 9 | DV01416000008 | Combine Steel Wire Assembly | PC | | 15.00 | 3.69 | | 55.35 |
| 10 | RV01108000004K | feeder chain(RGV3108010003K) | PC | | 20.00 | 27.73 | | 554.60 |
| 11 | RV01108000149 | Chain Harrow | PC | | 60.00 | 2.18 | | 130.80 |
| 12 | RV01103000002 | Moving (26)Cutter Combination with ball seat(88T small tank) | PC | | 20.00 | 18.90 | | 378.00 |
| 13 | DV01105010010 | Floating Block | PC | | 10.00 | 3.68 | | 36.80 |
| 14 | DV01206030001 | Threshing Body | PC | | 20.00 | 41.00 | | 820.00 |
| 15 | RV01103000021 | bearing | PC | | 15.00 | 0.34 | | 5.10 |
| 16 | DV01402010067 | HST Output Shaft | PC | | 10.00 | 7.35 | | 73.50 |
| 17 | RV01401140004 | Tensioner Combination(idler assembly) | PC | | 50.00 | 37.30 | | 1,865.00 |
| 18 | DV01402000005 | Driving Wheel | PC | | 30.00 | 23.70 | | 711.00 |
| 19 | DV01401000091 | Front Guide | PC | | 30.00 | 14.38 | | 431.40 |
| 20 | RGV1102020001K-ATT | Tilting ring drive assembly | PC | | 10.00 | 130.80 | | 1,308.00 |
| 21 | RV01102000042 | SWING ARM | PC | | 15.00 | 11.03 | | 165.45 |

| | | | | | | | | |
|----|-------------------|------------------------------------|----|--|-------|--------|--|--------|
| 22 | RV03104010011 | Variable speed pully assembly | PC | | 2.00 | 29.29 | | 58.58 |
| 23 | RV03401000044b | Rear Guide(MH108) | PC | | 20.00 | 14.50 | | 290.00 |
| 24 | RV01301020005 | 08B Chain (44 Elements) | PC | | 30.00 | 1.56 | | 46.80 |
| 25 | DV01301000114 | 19-Tooth Sprocket | PC | | 30.00 | 2.45 | | 73.50 |
| 26 | DV01302000113 | 16-Tooth Chain Pulley | PC | | 30.00 | 1.80 | | 54.00 |
| 27 | DV01301000018 | Sprocket 15 Teeth | PC | | 30.00 | 1.86 | | 55.80 |
| 28 | DV01302000052 | 17-Tooth Chain Pulley | PC | | 30.00 | 2.90 | | 87.00 |
| 29 | RV01302010001 | 08B Chain (58 Elements) | PC | | 50.00 | 2.05 | | 102.50 |
| 30 | DV01302000060 | Pulley | PC | | 20.00 | 5.58 | | 111.60 |
| 31 | RV01301020006K | SEED HOUSING | PC | | 5.00 | 61.20 | | 306.00 |
| 32 | RV03701000009 | key assembly(88T) | PC | | 10.00 | 9.56 | | 95.60 |
| 33 | RV01604050001 | HST pump(MH88T) | PC | | 1.00 | 688.58 | | 688.58 |
| 34 | DV01108020052 | Tension Chain Pulley Installation | PC | | 15.00 | 4.31 | | 64.65 |
| 35 | RV01205000011 | Rod gear weldment 1 | PC | | 2.00 | 17.17 | | 34.34 |
| 36 | RV01205000012 | Rod Gear Weldment 2 | PC | | 2.00 | 14.43 | | 28.86 |
| 37 | RV03401000053 | Right floating wheel assembly | PC | | 15.00 | 40.17 | | 602.55 |
| 38 | RV01402040001 | V-Belt 65.5 | PC | | 20.00 | 14.82 | | 296.40 |
| 39 | DV03402010003 | INPUT GEAR | PC | | 15.00 | 4.90 | | 73.50 |
| 40 | DV01402010086 | SPLINE SHAFT BUSH | PC | | 10.00 | 1.74 | | 17.40 |
| 41 | DV01402040018 | Transmission Connect Seat Assembly | PC | | 5.00 | 57.89 | | 289.45 |
| 42 | DV01402080043 | NORMALLY ENGAGED GEAR(AF88-114) | PC | | 10.00 | 8.59 | | 85.90 |
| 43 | RV03402000047 | 1ST SHAFT(AF88-116) | PC | | 20.00 | 7.64 | | 152.80 |
| 44 | RV03402000048 | SHAFT-I SLIDING GEAR(AF88-117) | PC | | 2.00 | 20.34 | | 40.68 |
| 45 | DV01402010025 | I DRIVEN GEAR(AF88-125) | PC | | 10.00 | 4.90 | | 49.00 |
| 46 | DV01402010028 | III DRIVEN GEAR(AF88-126) | PC | | 30.00 | 4.65 | | 139.50 |
| 47 | DV01402010026 | II DRIVEN GEAR(AF88-127) | PC | | 10.00 | 4.83 | | 48.30 |
| 48 | DV01402010021 | II SHAFT(AF88-128) | PC | | 20.00 | 10.47 | | 209.40 |
| 49 | RV03402000043-ATT | SPACER BUSH | PC | | 5.00 | 0.52 | | 2.60 |

| | | | | | | | | |
|----|-----------------|--|----|--|--------|-------|--|--------|
| 50 | JBZQ4342-32-ATT | HEAVY SHAFT WITH ELASTIC RING | PC | | 20.00 | 0.23 | | 4.60 |
| 51 | DV01402010020 | III SHAFT BEARING BUSH | PC | | 30.00 | 0.79 | | 23.70 |
| 52 | DV01402010120 | Shaft Left Cover | PC | | 20.00 | 0.61 | | 12.20 |
| 53 | DV01402010104 | PLUG COVER | PC | | 20.00 | 0.54 | | 10.80 |
| 54 | DV01402010103 | O RING | PC | | 20.00 | 0.05 | | 1.00 |
| 55 | DV01402010029 | II SHAFT SPACER BUSH | PC | | 30.00 | 0.45 | | 13.50 |
| 56 | DV01402010075 | RETAINER RING OF III SHAFT | PC | | 30.00 | 0.15 | | 4.50 |
| 57 | DV01402010078 | BRAKE SPRING OUTER GASKET | PC | | 30.00 | 0.38 | | 11.40 |
| 58 | DV01402010097 | INTERNAL FRICTION PLATE(AF88-143)(JY45-0304) | PC | | 500.00 | 1.94 | | 970.00 |
| 59 | DV01402010096 | EXTERNAL FRICTION PLATE(AF88-142)(steel) | PC | | 200.00 | 0.58 | | 116.00 |
| 60 | DV01402010031 | SHAFT-III SLIDING GEAR(AF88-146) | PC | | 30.00 | 17.09 | | 512.70 |
| 61 | DV01402010033 | III SHAFT JAW(AF88-147) | PC | | 20.00 | 17.89 | | 357.80 |
| 62 | DV01402010030 | III SHAFT GEAR(AF88-149) | PC | | 10.00 | 10.66 | | 106.60 |
| 63 | GBT297-30206 | TapERED ROLLER BEARING | PC | | 30.00 | 3.94 | | 118.20 |
| 64 | GBT283-NJ2205E | COLUMN ROLLER BEARING | PC | | 30.00 | 18.80 | | 564.00 |
| 65 | GBT297-32306 | tapered roller bearing 32306 | PC | | 30.00 | 14.90 | | 447.00 |
| 66 | GBT297-30210 | CONE BEARING 30210(AF88-185) | PC | | 20.00 | 10.61 | | 212.20 |
| 67 | DV01402010042 | IV SHAFT GEAR(AF88-160) | PC | | 17.00 | 24.04 | | 408.68 |
| 68 | DV01402010110 | NEEDLE BEARING 35X45X20(AF88-161) | PC | | 60.00 | 0.53 | | 31.80 |
| 69 | DV01402010046 | SHAFT-IV COVER GASKET | PC | | 20.00 | 0.07 | | 1.40 |

| | | | | | | | | |
|----|----------------------|--|-----|--|-------|----------|--|----------|
| 70 | DV01402010041 | IV SHAFT (AF88-164) | PC | | 15.00 | 6.95 | | 104.25 |
| 71 | DV01402010045 | SHIM | PC | | 40.00 | 0.35 | | 14.00 |
| 72 | DV01402010051 | Left Axle Tube | PC | | 3.00 | 21.58 | | 64.74 |
| 73 | DV01402010052 | Right Axle Tube | PC | | 3.00 | 19.93 | | 59.79 |
| 74 | DV01402010036 | RIGHT BEARING SEAT(AF88-154) | PC | | 12.00 | 15.82 | | 189.84 |
| 75 | DV01402010037 | BEARING SEAT CUSHION(AF88-155) | PC | | 20.00 | 0.13 | | 2.60 |
| 76 | DV01402010035 | LEFT BEARING SEAT(AF88-156) | PC | | 15.00 | 15.82 | | 237.30 |
| 77 | GBT9877.1-FB20X42X10 | SEAL RING(AF88-172) | PC | | 60.00 | 0.24 | | 14.40 |
| 78 | GBT6171-M24x2-10-A3L | GBT6171-M24x2-10-A3L | PC | | 20.00 | 0.41 | | 8.20 |
| 79 | DV01402040028 | DV01402040028 | PC | | 5.00 | 0.83 | | 4.15 |
| 80 | DV01402010060 | OIL SEAL RING | PC | | 20.00 | 2.68 | | 53.60 |
| 81 | DV01302000125K | Horizontal Auger Installion(2nd) 88T | PC | | 15.00 | 36.82 | | 552.30 |
| 82 | | transportation cost from factory to Yangon | job | | 1.00 | 2,485.09 | | 2,485.09 |

Subtotal : 23,125.71
VAT : 0.00
Total Amount : 23,125.71

Purchaser : Khaing Swe Thin
Delivery Date :
Payment Terms : 70% down payment after confirm PO
30% upon arrival
Remarks : For Stock And Production

(Prepared By) Checked By Acknowledge By Approved By Checked By

Procurement DH / After Market Manager (BU Finance) (GM / AGM) After Sale
(Only Foreign PO)