


TOOLS DAMAGE REPORT FORM



Date : 6-Mar-24

Reason: Damage
 Lost

IC Section Name _____

Reconduction _____


Previous Handover Data

Doc. Refr. No. _____

Date : _____

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
	Heavy socket 27		King Tony		1	Damage

Photo attach of Damage Tools



Supervisor Analyze Commence

Track shoe bolts are tight, frequently used this socket.

Department Head Judgement/ Decision

Not safety & need to buy more quality tools.

Reported By

Hein Min Htet

 Mechanic

Checked By

Awng Myo Hwe

 Supervisor

Approved By


[Signature]

 Department Head

Cause of Damage

02-BRM-PDD-FRM-009-00

TOOLS DAMAGE REPORT FORM



Date : 6-Mar-25

Reason:

Damage
 Lost

Section Name

Reconduction


Previous Handover Data

Doc. Refr. No. :

Date :

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Pipe				1	Damage
2	Nozzle				1	Nozzle tip Closing
3	Oxygen Gate				1	Damage

Photo attach of Damage Tools



Supervisor Analyze Commence

Pipes are longtime used, Decayed and damaged.
 Nozzel tip is closing with piece of iron.
 Oxygen gate and connection can't fix loose oxygen.

Department Head Judgement/ Decision

Not safety and. don't used old parts.

Reported By

Mechanic

Nyi Nyi Htan

Checked By

Aung Myo Htwe
 Supervisor

Approved By

Department Head

Cause of Damage

Cause of Damage

- 1) Material weakness of Tools
- 2) Wrong operation

02-BRM-PDD-FRM-009-00