

COP Purchase Order

| | |
|--|--|
| Document No : PO-PRT-COP-2025-06-00004 | Vendor : HITACHI CONSTRUCTION MACHINERY ASIA & PACIFIC PTE.,LTD |
| Confirmation Date: | Contact Person : HITACHI CONSTRUCTION MACHINERY ASIA & PACIFIC PTE.,LTD |
| Order Deadline : 06/02/2025 13:39:31 | Phone No : 6660 5318 |
| Receipt Date : 06/02/2025 13:39:31 | Payment Term : |
| Currency : USD | Purchase Order : Stock Order Type |
| Shipping Method : Sea | Type : |
| Unit or Part : Spare Part | Address : HITACHI CONSTRUCTION MACHINERY APAC NO.2 PIONEER WALK 627856 SINGAPORE |
| Business Unit : COP | |

| No | Brand | Product Code | Description | UOM | Order Qty | Received Qty | Bill Qty | Price | Tax Rate | Discount | Amount |
|----|---------|--------------|--|-----|-----------|--------------|----------|--------|----------|----------|---------|
| 1 | | YA00004267 | [YA00004267] Engine Cotroller | PC | 10.0 | 0.0 | 0.0 | 401.18 | | 0.0 | 4011.8 |
| 2 | | 4614911 | [4614911] Motor; EC | PC | 5.0 | 0.0 | 0.0 | 343.38 | | 0.0 | 1716.9 |
| 3 | | 2049166 | [2049166] Shaft, Travel Oil Motor | PC | 5.0 | 0.0 | 0.0 | 206.11 | | 0.0 | 1030.55 |
| 4 | | 2050692 | [2050692] Shaft; Prop | PC | 10.0 | 0.0 | 0.0 | 235.78 | | 0.0 | 2357.8 |
| 5 | HITACHI | YA00029685 | [YA00029685] Harness; Wire | PC | 1.0 | 0.0 | 0.0 | 599.92 | | 0.0 | 599.92 |
| 6 | | 4648651 | [4648651] Strainer | PC | 20.0 | 0.0 | 0.0 | 14.81 | | 0.0 | 296.2 |
| 7 | | 4630525 | [4630525] Element; Filter, Hyd Pilot | PC | 50.0 | 0.0 | 0.0 | 16.65 | | 0.0 | 832.5 |
| 8 | | 4616864 | [4616864] Filter; Fuel | PC | 70.0 | 0.0 | 0.0 | 11.03 | | 0.0 | 772.1 |
| 9 | | 4612283 | [4612283] Belt; V (Air Conditioner) | PC | 30.0 | 0.0 | 0.0 | 10.32 | | 0.0 | 309.6 |
| 10 | HITACHI | 4201993 | [4201993] O-Ring | PC | 100.0 | 0.0 | 0.0 | 0.88 | | 0.0 | 88.0 |
| 11 | | YA00001495 | [YA00001495] Glass; Front Upper | PC | 6.0 | 0.0 | 0.0 | 133.13 | | 0.0 | 798.78 |
| 12 | | 4651654 | [4651654] Glass; Front Lower | PC | 2.0 | 0.0 | 0.0 | 57.07 | | 0.0 | 114.14 |
| 13 | | YA00001498 | [YA00001498] Glass; Left (Fix, Rear) | PC | 2.0 | 0.0 | 0.0 | 65.36 | | 0.0 | 130.72 |
| 14 | | YA00001499 | [YA00001499] Glass; Door (Fix, Lower) | PC | 3.0 | 0.0 | 0.0 | 79.21 | | 0.0 | 237.63 |
| 15 | | 9314145 | [9314145] Valve; Solenoid | PC | 10.0 | 0.0 | 0.0 | 48.45 | | 0.0 | 484.5 |
| 16 | | YA00041204 | [YA00041204] Valve; Relief (Swing Motor) | PC | 2.0 | 0.0 | 0.0 | 260.46 | | 0.0 | 520.92 |
| 17 | | 9312792 | [9312792] Valve Solenoid (Regulator; Pump) | PC | 3.0 | 0.0 | 0.0 | 187.12 | | 0.0 | 561.36 |
| 18 | HITACHI | YB00002028 | [YB00002028] Head; Unit Pump | PC | 3.0 | 0.0 | 0.0 | 409.39 | | 0.0 | 1228.17 |

| Brand | Product Code | Description | UOM | Order Qty | Received Qty | Bill Qty | Price | Tax Rate | Discount | Amount |
|-------|------------------|--|-----|-----------|--------------|----------|---------|----------|----------|---------|
| | YA00009267 | [YA00009267] Harness Wire (Main Pump) | PC | 2.0 | 0.0 | 0.0 | 94.11 | | 0.0 | 188.22 |
| 20 | ISUZU 8980028978 | [8980028978] Engine Harness | PC | 2.0 | 0.0 | 0.0 | 230.24 | | 0.0 | 460.48 |
| 21 | 4265372 | [4265372] Sensor; Revolution | PC | 5.0 | 0.0 | 0.0 | 31.27 | | 0.0 | 156.35 |
| 22 | ISUZU 1154158491 | [1154158491] Pipe; INJ No.3 | PC | 3.0 | 0.0 | 0.0 | 22.02 | | 0.0 | 66.06 |
| 23 | ISUZU 1154158501 | [1154158501] Pipe; INJ No.4 | PC | 3.0 | 0.0 | 0.0 | 22.02 | | 0.0 | 66.06 |
| 24 | ISUZU 1154158522 | [1154158522] Pipe; INJ No.6 | PC | 3.0 | 0.0 | 0.0 | 18.38 | | 0.0 | 55.14 |
| 25 | ISUZU 1878143440 | [1878143440] Gasket Kit; Engine | PC | 3.0 | 0.0 | 0.0 | 382.79 | | 0.0 | 1148.37 |
| 26 | ISUZU 8982404830 | [8982404830] RING SET; PISTON,STANDARD | PC | 12.0 | 0.0 | 0.0 | 20.18 | | 0.0 | 242.16 |
| 27 | 1115100741 | [1115100741] Metal Kit; Crankshaft (Std) | PC | 3.0 | 0.0 | 0.0 | 149.33 | | 0.0 | 447.99 |
| 28 | 9122716080 | [9122716080] Metal Set; Connecting Rod (STD) | PC | 18.0 | 0.0 | 0.0 | 25.05 | | 0.0 | 450.9 |
| 29 | ISUZU 1116800011 | [1116800011] Washer; Thrust, Crankshaft | PC | 6.0 | 0.0 | 0.0 | 16.83 | | 0.0 | 100.98 |
| 30 | 1156033960 | [1156033960] Pump Ass'y; Injection | PC | 1.0 | 0.0 | 0.0 | 1834.01 | | 0.0 | 1834.01 |
| 31 | YB60000205 | [YB60000205] Valve Pilot; Front Swing | PC | 1.0 | 0.0 | 0.0 | 230.93 | | 0.0 | 230.93 |
| 32 | 8982497240 | [8982497240] Switch; Oil Pressure Warning | PC | 2.0 | 0.0 | 0.0 | 27.69 | | 0.0 | 55.38 |
| 33 | YB00003778 | [YB00003778] Center Joint Seal Kit | PC | 20.0 | 0.0 | 0.0 | 45.66 | | 0.0 | 913.2 |
| 34 | YA60001374 | [YA60001374] Main Controller | PC | 2.0 | 0.0 | 0.0 | 800.89 | | 0.0 | 1601.78 |
| 35 | YA00048010 | [YA00048010] Controller;Aircon | PC | 1.0 | 0.0 | 0.0 | 207.85 | | 0.0 | 207.85 |
| 36 | 4197948 | [4197948] Tank; Water | PC | 2.0 | 0.0 | 0.0 | 37.23 | | 0.0 | 74.46 |
| 37 | 4671642 | [4671642] Box; Controller (Auto Fuel Filling Device) | PC | 1.0 | 0.0 | 0.0 | 604.61 | | 0.0 | 604.61 |
| 38 | XP00000008PS | [XP00000008PS] O-Ring Kit | PC | 10.0 | 0.0 | 0.0 | 84.63 | | 0.0 | 846.3 |
| 39 | XP00000001PS | [XP00000001PS] Kit; O-Ring | PC | 10.0 | 0.0 | 0.0 | 95.05 | | 0.0 | 950.5 |
| 40 | YD00012085 | [YD00012085] Solenoid | PC | 1.0 | 0.0 | 0.0 | 257.04 | | 0.0 | 257.04 |
| 41 | 4614657 | [4614657] Valve; Solenoid | PC | 1.0 | 0.0 | 0.0 | 106.9 | | 0.0 | 106.9 |
| 42 | 4613831 | [4613831] Seal; Oil (Travel Oil Motor) | PC | 10.0 | 0.0 | 0.0 | 17.12 | | 0.0 | 171.2 |
| 43 | 4396774 | [4396774] O-Ring | PC | 15.0 | 0.0 | 0.0 | 7.97 | | 0.0 | 119.55 |
| 44 | 4420958 | [4420958] O-Ring (Swing Oil Motor) | PC | 10.0 | 0.0 | 0.0 | 8.65 | | 0.0 | 86.5 |
| 45 | 4506415 | [4506415] O-Ring | PC | 25.0 | 0.0 | 0.0 | 1.06 | | 0.0 | 26.5 |

| Brand | Product Code | Description | UOM | Order Qty | Received Qty | Bill Qty | Price | Tax Rate | Discount | Amount |
|-------|--------------------|--|-----|-----------|--------------|----------|---------|----------|----------|---------|
| | 4426564 | [4426564] Cable; Control | PC | 3.0 | 0.0 | 0.0 | 99.12 | | 0.0 | 297.36 |
| 47 | 1037164 | [1037164] Gear; Ring | PC | 1.0 | 0.0 | 0.0 | 1688.24 | | 0.0 | 1688.24 |
| 48 | YB00000114 | [YB00000114] Coupling; Pump Device | PC | 1.0 | 0.0 | 0.0 | 227.95 | | 0.0 | 227.95 |
| 49 | 1025875 | [1025875] Carrier (3rd Stage); Travel Device | PC | 3.0 | 0.0 | 0.0 | 482.43 | | 0.0 | 1447.29 |
| 50 | 4438593 | [4438593] Bearing; Needle (Travel Device) | PC | 12.0 | 0.0 | 0.0 | 16.39 | | 0.0 | 196.68 |
| 51 | 4438592 | [4438592] Bearing; Needle | PC | 6.0 | 0.0 | 0.0 | 7.77 | | 0.0 | 46.62 |
| 52 | 4402086 | [4402086] Pin, Travel Device | PC | 10.0 | 0.0 | 0.0 | 18.96 | | 0.0 | 189.6 |
| 53 | 2050691 | [2050691] Carrier (1st Stage); Travel Device | PC | 2.0 | 0.0 | 0.0 | 147.06 | | 0.0 | 294.12 |
| 54 | 4406589 | [4406589] Bearing; Needle | PC | 12.0 | 0.0 | 0.0 | 5.55 | | 0.0 | 66.6 |
| 55 | HITACHI 4210853 | [4210853] Pin (Travel Device) | PC | 12.0 | 0.0 | 0.0 | 14.87 | | 0.0 | 178.44 |
| 56 | A811120 | [A811120] O-Ring | PC | 5.0 | 0.0 | 0.0 | 4.47 | | 0.0 | 22.35 |
| 57 | 4402481 | [4402481] Bearing; Roller, T-Mission (Swing) | PC | 3.0 | 0.0 | 0.0 | 330.75 | | 0.0 | 992.25 |
| 58 | 4667150 | [4667150] Bearing; Roller | PC | 2.0 | 0.0 | 0.0 | 152.93 | | 0.0 | 305.86 |
| 59 | 1031849 | [1031849] Carrier (Swing; Transmission) | PC | 1.0 | 0.0 | 0.0 | 272.93 | | 0.0 | 272.93 |
| 60 | 4488904 | [4488904] Pin (Swing Device) | PC | 2.0 | 0.0 | 0.0 | 47.73 | | 0.0 | 95.46 |
| 61 | 1031817 | [1031817] Carrier (Swing; Transmission) | PC | 1.0 | 0.0 | 0.0 | 210.64 | | 0.0 | 210.64 |
| 62 | HITACHI 4403371 | [4403371] Plate; Thrust | PC | 1.0 | 0.0 | 0.0 | 16.48 | | 0.0 | 16.48 |
| 63 | HITACHI 3102045 | [3102045] Gear; Planetary | PC | 3.0 | 0.0 | 0.0 | 70.87 | | 0.0 | 212.61 |
| 64 | 4403082 | [4403082] Plate; Thrust | PC | 6.0 | 0.0 | 0.0 | 8.92 | | 0.0 | 53.52 |
| 65 | 4336923 | [4336923] Pin | PC | 5.0 | 0.0 | 0.0 | 21.64 | | 0.0 | 108.2 |
| 66 | HITACHI 4352398 | [4352398] Bushing (Link A) | PC | 9.0 | 0.0 | 0.0 | 27.33 | | 0.0 | 245.97 |
| 67 | HITACHI 3088573 | [3088573] Pin, Frame | PC | 3.0 | 0.0 | 0.0 | 64.01 | | 0.0 | 192.03 |
| 68 | 9246436 | [9246436] Sleeve Ass'y | PC | 56.0 | 0.0 | 0.0 | 20.5 | | 0.0 | 1148.0 |
| 69 | 0788809 | [0788809] Plate; Valve, Swing Oil Motor | PC | 3.0 | 0.0 | 0.0 | 169.06 | | 0.0 | 507.18 |
| 70 | 0788816 | [0788816] Plate; Friction (Swing Motor) | PC | 5.0 | 0.0 | 0.0 | 43.61 | | 0.0 | 218.05 |
| 71 | 0788817 | [0788817] Plate (Swing Motor) | PC | 10.0 | 0.0 | 0.0 | 25.84 | | 0.0 | 258.4 |
| 72 | 0788813 | [0788813] Seal, Shaft (Swing Motor) | PC | 3.0 | 0.0 | 0.0 | 14.42 | | 0.0 | 43.26 |
| 73 | 0788811 | [0788811] Bearing; Roller, Swing Oil Motor | PC | 3.0 | 0.0 | 0.0 | 92.96 | | 0.0 | 278.88 |
| 74 | HITACHI YB00004086 | [YB00004086] CARRIER; PLANETARY | PC | 1.0 | 0.0 | 0.0 | 1043.86 | | 0.0 | 1043.86 |
| 75 | HITACHI YB00002306 | [YB00002306] Shaft; Travel Oil Motor | PC | 1.0 | 0.0 | 0.0 | 87.37 | | 0.0 | 87.37 |

| | Brand | Product Code | Description | UOM | Order Qty | Received Qty | Bill Qty | Price | Tax Rate | Discount | Amount |
|----|---------|--------------|--|-----|-----------|--------------|----------|--------|----------|----------|--------|
| | HITACHI | YB00001390 | [YB00001390] Shaft; Propeller | PC | 1.0 | 0.0 | 0.0 | 358.69 | | 0.0 | 358.69 |
| 77 | | 8981197900 | [8981197900] Sensor; Pressure | PC | 3.0 | 0.0 | 0.0 | 91.37 | | 0.0 | 274.11 |
| 78 | | 8973061131 | [8973061131] Sensor; Tachometer | PC | 1.0 | 0.0 | 0.0 | 30.31 | | 0.0 | 30.31 |
| 79 | | YA00001497 | [YA00001497] Glass; Operator Seat Back | PC | 3.0 | 0.0 | 0.0 | 66.09 | | 0.0 | 198.27 |
| 80 | | 8970728231 | [8970728231] Seal; Oil, Crankshaft, RR | PC | 10.0 | 0.0 | 0.0 | 22.88 | | 0.0 | 228.8 |
| 81 | ISUZU | 8972242040 | [8972242040] Hose; Water Pipe | PC | 3.0 | 0.0 | 0.0 | 9.27 | | 0.0 | 27.81 |
| 82 | | 1137700700 | [1137700700] Thermostat (82C) | PC | 3.0 | 0.0 | 0.0 | 38.51 | | 0.0 | 115.53 |
| 83 | | 2034607 | [2034607] Cover; Center Joint | PC | 1.0 | 0.0 | 0.0 | 34.67 | | 0.0 | 34.67 |

Subtotal : 39,775.40 \$
Commercial Tax : 0.00 \$
Total Amount : 39,775.40 \$

Note: FPO/HITACHI/2025/5/0001 For Inventory Stock With HMAP

COP-PRT-PO-25050012

Prepared By



PIC

Approved By



Inventory PIC

Checked By

F&A PIC

Approved By



GM/AGM


Aung Han Win.
29/06/2025.


27/06/2025
Amnlon

CP SO Seq: 5000046759 / COP-PRT-PO-25050012 - Message (HTML)

FILE MESSAGE ADOBE PDF

Ignore X Meeting
 Delete Reply Forward All More
 Reply Reply Forward All More
 Reply & Delete
 Team Email
 FRD
 To Manager Done
 Create New

Move Move
 OneNote
 Actions
 Unread Up
 Mark Categorize Follow
 Translate Select

Find Find
 Related-
 Zoom
 Zoom

Quick Steps Respond
 Delete

Mon 6/2/2025 1:01 PM
 Chen, Shijia (HMAP) <chen.shijia.ca@hitachi-kenki.com> on behalf of DL-KENKI-DL-KENKI-HMAP-sales-orders <sggp-hm-gp-sales-orders@hitachi-kenki.com>
 CP SO Seq: 5000046759 / COP-PRT-PO-25050012
 To: Jessie, Mok (HMAP); anbu.nang
 Cc: sithum.than; aungthu.win; Lai, Ernest (HMAP); hmunulakhang@umgroups.com; Nan Myint Cherry Aung; theadmin.thu1@umgroups.com; aungthu.win; Low, Margo (HMAP); DL-KENKI-DL-KENKI-HMAP-sales-orders@hitachi-kenki.com

You replied to this message on 6/2/2025 2:01 PM.

Message 5000046759 COP-PRT-PO-25050012 (CP).pdf (203 KB)

Order has been processed, please find order confirmation as attached.

1) Please note that 4192631RHS was suspended to 4616864.
 We have created line item for 4616864 instead.
 Please take note of the price difference and kindly resend new PO.
 Do let us know if there is any concern.

| No. | Brand | Part Description | Part Number | Order Qty | Unit Price (USD/Ks) if need | Amount (USD/Ks) if need |
|-----|---------|------------------|-------------|-----------|-----------------------------|-------------------------|
| 8 | HITACHI | Filter, Fuel | 4192631RHS | 70 | \$ 48.24 | \$ 3,376.80 |

L V Customer PIN Supply P/N Product name Inventory # Reference number Note Quantity Unit Delivery remarks Unit price Charac... Net amount

| | | | | | | | | | | |
|---|--|---------|---------|--|--|---------|-------|-------|-------|--------|
| 8 | | 4616864 | 4616864 | | | 70.00 e | 70.00 | 15.54 | 29.00 | 772.10 |
|---|--|---------|---------|--|--|---------|-------|-------|-------|--------|

IC Part IC Part No JV Description Avail Qty Qty / Lot Part Prohibition Part Bulletin No. Caution Unit Price(USD)

See more about DL-KENKI-DL-KENKI-HMAP-sales-orders

INVENTORY PURCHASE ORDER



| | |
|---------------|-------------------------|
| Proposal No. | FPO/HITACHI/2025/S/0001 |
| Proposal Date | 14-May-2025 |
| Attn: | |

| No. | Brand | Part Description | Part Number | Order Qty | On Hand Stock | Outstanding PO | 1yrs Sale, 2024 | Unit Price (USD/Ks) if need | Amount (USD/Ks) if need | Machine Information | Remarks |
|-----|---------|---|-------------|-----------|---------------|----------------|-----------------|-----------------------------|-------------------------|---------------------|---------|
| | | | | | | | | | | MC Model | |
| 1 | HITACHI | Engine Cotroller | YA00004267 | 10 | 2 | 0 | 10 | \$ 401.18 | \$ 4,011.80 | ZK210LCH-5G | |
| 2 | HITACHI | Motor; EC | 4614911 | 5 | 6 | 0 | 7 | \$ 343.38 | \$ 1,716.90 | ZK210LCH-5G | |
| 3 | HITACHI | Shaft, Travel Oil Motor | 2049166 | 5 | 7 | 0 | 9 | \$ 206.11 | \$ 1,030.55 | ZK210LCH-5G | |
| 4 | HITACHI | Shaft; Prop | 2050692 | 10 | 6 | 0 | 9 | \$ 235.78 | \$ 2,357.80 | ZK210LCH-5G | |
| 5 | HITACHI | Harness; Wire Cab | YA00029685 | 1 | 2 | 0 | 1 | \$ 599.92 | \$ 599.92 | ZK210LCH-5G | |
| 6 | HITACHI | Strainer | 4648651 | 20 | 15 | 50 | 61 | \$ 14.81 | \$ 296.20 | ZK210LCH-5G | |
| 7 | HITACHI | Element; Filter, Hyd Pilot | 4630525 | 50 | 89 | 20 | 177 | \$ 16.65 | \$ 832.50 | ZK210LCH-5G | |
| 8 | HITACHI | Filter; Fuel | 4616864 | 70 | 1 | 0 | 38 | \$ 11.03 | \$ 772.10 | ZK350LCH-5G | |
| 9 | HITACHI | Belt; V (Air Conditioner) | 4612283 | 30 | 18 | 0 | 40 | \$ 10.32 | \$ 309.60 | ZK210LCH-5G | |
| 10 | HITACHI | O-Ring | 4201993 | 100 | 17 | 0 | 72 | \$ 0.88 | \$ 88.00 | ZK All Models | |
| 11 | HITACHI | Glass; Front Upper | YA00001495 | 6 | 0 | 0 | 10 | \$ 133.13 | \$ 798.78 | ZK210LCH-5G | |
| 12 | HITACHI | Glass; Front Lower | 4651654 | 2 | 3 | 0 | 2 | \$ 57.07 | \$ 114.14 | ZK210LCH-5G | |
| 13 | HITACHI | Glass; Left (Fix, Rear) | YA00001498 | 2 | 2 | 0 | 2 | \$ 65.36 | \$ 130.72 | ZK210LCH-5G | |
| 14 | HITACHI | Glass; Door (Fix, Lower) | YA00001499 | 3 | 0 | 0 | 1 | \$ 79.21 | \$ 237.63 | ZK210LCH-5G | |
| 15 | HITACHI | Valve; Solenoid | 9314145 | 10 | 1 | 0 | 11 | \$ 48.45 | \$ 484.50 | ZK210LCH-5G | |
| 16 | HITACHI | Valve; Relief (Swing Motor) | YA00041204 | 2 | 0 | 0 | 2 | \$ 260.46 | \$ 520.92 | ZK210LCH-5G | |
| 17 | HITACHI | Valve Solenoid (Regulator; Pump) | 9312792 | 3 | 2 | 0 | 2 | \$ 187.12 | \$ 561.36 | ZK210LCH-5G | |
| 18 | HITACHI | Head; Unit Pump | YB00002028 | 3 | 0 | 0 | 4 | \$ 409.39 | \$ 1,228.17 | ZK210LCH-5G | |
| 19 | HITACHI | Head; Unit Pump | YA00009267 | 2 | 1 | 0 | 2 | \$ 94.11 | \$ 188.22 | ZK210LCH-5G | |
| 20 | HITACHI | Harness Wire (Main Pump) | 8980028978 | 2 | 0 | 0 | 0 | \$ 230.24 | \$ 460.48 | 4NK1 | |
| 21 | ISUZU | Engine Harness | 4265372 | 5 | 1 | 0 | 4 | \$ 31.27 | \$ 156.35 | ZK210LCH-5G | |
| 22 | HITACHI | Sensor; Revolution | 1154158491 | 3 | 0 | 0 | 1 | \$ 22.02 | \$ 66.06 | 6BG1 | |
| 23 | ISUZU | Pipe; INJ No.3 | 1154158501 | 3 | 0 | 0 | 1 | \$ 22.02 | \$ 66.06 | 6BG1 | |
| 24 | ISUZU | Pipe; INJ No.4 | 1154158522 | 3 | 0 | 0 | 1 | \$ 18.38 | \$ 55.14 | 6BG1 | |
| 25 | ISUZU | Pipe; INJ No.6 | 1878143440 | 3 | 0 | 4 | 6 | \$ 382.79 | \$ 1,148.37 | 6BG1 | |
| 26 | ISUZU | Gasket Kit; Engine | 8982404830 | 12 | 2 | 0 | 4 | \$ 20.18 | \$ 242.16 | 6BG1 | |
| 27 | ISUZU | RING SET; PISTON, STANDARD | 1115100741 | 3 | 0 | 0 | 5 | \$ 149.33 | \$ 447.99 | 6BG1 | |
| | | Metal Kit, CRANKSHAFT, STANDARD (Main Bearings) | | | | | | | | | |

| | | | | | | | | | |
|---------|---------|--------------|----|-----|-----|-----|-------|-----|--------|
| 4651654 | 4651654 | Glass; Front | PC | 2.0 | 0.0 | 0.0 | 57.07 | 0.0 | 114.14 |
|---------|---------|--------------|----|-----|-----|-----|-------|-----|--------|

| | | | | | | | | | | | |
|----|---------|--|--------------|----|----|---|----|-------------|----|----------|---|
| 30 | ISUZU | Metal Set; Connecting Rod (STD) | 9122716080 | 18 | 0 | 0 | 12 | \$ 25.05 | \$ | 450.90 | 68G1 |
| 31 | ISUZU | Washer; Thrust, Crankshaft | 1116800011 | 6 | 0 | 0 | 2 | \$ 16.83 | \$ | 100.98 | 68G1 |
| 32 | ISUZU | Injection Pump | 1156033960 | 1 | 0 | 0 | 1 | \$ 1,834.01 | \$ | 1,834.01 | 68G1 |
| 33 | HITACHI | Valve Pilot; Front Swing | YB60000205 | 1 | 0 | 0 | 0 | \$ 230.93 | \$ | 230.93 | ZK210LCH-5G/ZK210LCH-5G |
| 34 | HITACHI | Center Joint Seal Kit | YB00003778 | 20 | 32 | 0 | 41 | \$ 45.66 | \$ | 913.20 | ZK210LCH-5G |
| 35 | HITACHI | Main Controller | YA60001374 | 2 | 1 | 0 | 4 | \$ 800.89 | \$ | 1,601.78 | ZK210LCH-5G |
| 36 | HITACHI | Controller:Alrcon | YA00048010 | 1 | 0 | 0 | 1 | \$ 207.85 | \$ | 207.85 | ZK210LCH-5G |
| 37 | HITACHI | Tank; Water | 4197948 | 2 | 0 | 0 | 2 | \$ 37.23 | \$ | 74.46 | ZK210LCH-5G |
| 38 | HITACHI | Box; Controller (Auto Fuel Filling Device) | 4671642 | 1 | 0 | 0 | 1 | \$ 604.61 | \$ | 604.61 | ZK210LCH-5G |
| 39 | HITACHI | O-Ring Kit | XP00000008PS | 10 | 20 | 0 | 27 | \$ 84.63 | \$ | 846.30 | ZK210LCH-5G/ZK210LCH-5G/ZK210LCH-5G/ZK210LCH-5G |
| 40 | HITACHI | O-Ring Kit | XP00000001PS | 10 | 11 | 0 | 17 | \$ 95.05 | \$ | 950.50 | ZK210LCH-5G/ZK210LCH-5G/ZK210LCH-5G/ZK210LCH-5G |
| 41 | HITACHI | Solenoid | YD00012085 | 1 | 1 | 0 | 1 | \$ 257.04 | \$ | 257.04 | ZK55U-5A |
| 42 | HITACHI | Valve; Solenoid | 4614657 | 1 | 0 | 0 | 1 | \$ 106.90 | \$ | 106.90 | ZK55U-5A |
| 43 | HITACHI | Seal; Oil (Travel Oil Motor) | 4613831 | 10 | 6 | 0 | 12 | \$ 17.12 | \$ | 171.20 | ZK210LCH-5G |
| 44 | HITACHI | O-Ring | 4396774 | 15 | 5 | 0 | 12 | \$ 7.97 | \$ | 119.55 | ZK210LCH-5G |
| 45 | HITACHI | O-Ring (Swing Oil Motor) | 4420958 | 10 | 8 | 0 | 11 | \$ 8.65 | \$ | 86.50 | ZK210LCH-5G |
| 46 | HITACHI | O-Ring | 4506415 | 25 | 4 | 0 | 16 | \$ 1.06 | \$ | 26.50 | ZK210LCH-5G |
| 47 | HITACHI | Cable; Control | 4426564 | 3 | 5 | 0 | 6 | \$ 99.12 | \$ | 297.36 | ZK210LCH-5G |
| 48 | HITACHI | Gear; Ring | 1037164 | 1 | 0 | 0 | 0 | \$ 1,688.24 | \$ | 1,688.24 | ZK210LCH-5G |
| 49 | HITACHI | Coupling; Pump Device | YB00000114 | 1 | 1 | 0 | 1 | \$ 227.95 | \$ | 227.95 | ZK210LCH-5G |
| 50 | HITACHI | Carrier (3rd Stage); Travel Device | 1025875 | 3 | 0 | 0 | 5 | \$ 482.43 | \$ | 1,447.29 | ZK210LCH-5G |
| 51 | HITACHI | Bearing; Needle (Travel Device) | 4438593 | 12 | 0 | 0 | 1 | \$ 16.39 | \$ | 196.68 | ZK210LCH-5G |
| 52 | HITACHI | Bearing; Needle | 4438592 | 6 | 10 | 0 | 21 | \$ 7.77 | \$ | 46.62 | ZK210LCH-5G |
| 53 | HITACHI | Pin, Travel Device | 4402086 | 10 | 1 | 0 | 6 | \$ 18.96 | \$ | 189.60 | ZK210LCH-5G |
| 54 | HITACHI | Carrier (1st Stage); Travel Device | 2050691 | 2 | 1 | 0 | 5 | \$ 147.06 | \$ | 294.12 | ZK210LCH-3F,ZK210LCH-5G |
| 55 | HITACHI | Bearing; Needle | 4406589 | 12 | 0 | 0 | 54 | \$ 5.55 | \$ | 66.60 | ZK250LCH-3F,ZK210LCH-5G |
| 56 | HITACHI | Pin (Travel Device) | 4210853 | 12 | 0 | 0 | 0 | \$ 14.87 | \$ | 178.44 | ZK210LCH-5G |
| 57 | HITACHI | O-Ring | A811120 | 5 | 0 | 0 | 1 | \$ 4.47 | \$ | 22.35 | ZK210LCH-5G |
| 58 | HITACHI | Bearing; Roller, T-Mission (Swing) | 4402481 | 3 | 0 | 0 | 1 | \$ 330.75 | \$ | 992.25 | ZK210LCH-5G |
| 59 | HITACHI | Bearing; Roller | 4667150 | 2 | 1 | 0 | 1 | \$ 152.93 | \$ | 305.86 | ZK210LCH-3F,ZK210-5 |
| 60 | HITACHI | Carrier (Swing; Transmission) | 1031849 | 1 | 1 | 0 | 0 | \$ 272.93 | \$ | 272.93 | ZK210-3,ZK210-5 |
| 61 | HITACHI | Pin (Swing Device) | 4488904 | 2 | 1 | 0 | 0 | \$ 47.73 | \$ | 95.46 | ZK210LCH-5G/ZK250LCH-5G/ZK210LCH-3F |
| 62 | HITACHI | Carrier (Swing; Transmission) | 1031817 | 1 | 1 | 0 | 0 | \$ 210.64 | \$ | 210.64 | ZK210-3,ZK210-5 |
| 63 | HITACHI | Plate; Thrust | 4403371 | 1 | 0 | 0 | 0 | \$ 16.48 | \$ | 16.48 | ZK210LCH-5G |
| 64 | HITACHI | Gear; Planetary | 3102045 | 3 | 0 | 0 | 0 | \$ 70.87 | \$ | 212.61 | ZK210LCH-5G |
| 65 | HITACHI | Plate; Thrust | 4403082 | 6 | 0 | 0 | 0 | \$ 8.92 | \$ | 53.52 | ZK210LCH-5G |

| | | | | | | | | | | | | |
|----|---------|---|------------|-----|----|---|----|-------------|----|-----------|-------------|--|
| 67 | HITACHI | Pin | 4336923 | 5 | 1 | 0 | 0 | \$ 21.64 | \$ | 108.20 | ZK210LCH-5G | |
| | HITACHI | Bushing (Link A) | 4352398 | 9 | 0 | 0 | 13 | \$ 27.33 | \$ | 245.97 | ZK210LCH-5G | |
| | HITACHI | Pin, Frame | 3088573 | 3 | 0 | 0 | 0 | \$ 64.01 | \$ | 192.03 | ZK210LCH-5G | |
| 68 | HITACHI | Sleeve Ass'y | 9246436 | 56 | 14 | 0 | 80 | \$ 20.50 | \$ | 1,148.00 | ZK210LCH-5G | |
| 69 | HITACHI | Plate; Valve Swing Motor | 0788809 | 3 | 0 | 4 | 1 | \$ 169.06 | \$ | 507.18 | ZK210LCH-5G | |
| 70 | HITACHI | Plate; Friction (Swing Motor) | 0788816 | 5 | 8 | 0 | 3 | \$ 43.61 | \$ | 218.05 | ZK210LCH-5G | |
| 71 | HITACHI | Plate (Swing Motor) | 0788817 | 10 | 4 | 0 | 6 | \$ 25.84 | \$ | 258.40 | ZK210LCH-5G | |
| 72 | HITACHI | Seal, Shaft (Swing Motor) | 0788813 | 3 | 3 | 0 | 0 | \$ 14.42 | \$ | 43.26 | ZK210LCH-5G | |
| 73 | HITACHI | Bearing; Roller, Swing Oil Motor | 0788811 | 3 | 1 | 0 | 2 | \$ 92.96 | \$ | 278.88 | ZK210LCH-5G | |
| 74 | HITACHI | CARRIER; PLANETARY | YB00004086 | 1 | 0 | 0 | 0 | \$ 1,043.86 | \$ | 1,043.86 | ZK280LC-5G | |
| 75 | HITACHI | Shaft; Travel Oil Motor | YB00002306 | 1 | 0 | 0 | 0 | \$ 87.37 | \$ | 87.37 | ZK280LC-5G | |
| 76 | HITACHI | Shaft; Propeller | YB00001390 | 1 | 0 | 0 | 0 | \$ 358.69 | \$ | 358.69 | ZK280LC-5G | |
| 77 | ISUZU | Engine Oil Pressure Sensor | 8981197900 | 3 | 2 | 0 | 0 | \$ 91.37 | \$ | 274.11 | 4HK1 | |
| 78 | ISUZU | Sensor; Tachometer (Crank Speed Sensor) | 8973061131 | 1 | 2 | 0 | 0 | \$ 30.31 | \$ | 30.31 | 4HK1 | |
| 79 | ISUZU | Glass; Operator Seat Back | YA00001497 | 3 | 2 | 0 | 4 | \$ 66.09 | \$ | 198.27 | ZK210LCH-5G | |
| 80 | ISUZU | Seal Oil Crankshaft Rear | 8970728231 | 10 | 5 | 0 | 10 | \$ 22.88 | \$ | 228.80 | 68G1 | |
| 81 | ISUZU | Hose; Water Pipe | 8972242040 | 3 | 0 | 5 | 2 | \$ 9.27 | \$ | 27.81 | 68G1 | |
| 82 | ISUZU | Thermostat (82C) | 1137700700 | 3 | 0 | 0 | 1 | \$ 38.51 | \$ | 115.53 | 48G1/58G1 | |
| 83 | HITACHI | Cover; Center Joint | 2034607 | 1 | 6 | 0 | 5 | \$ 34.67 | \$ | 34.67 | ZK210LCH-5G | |
| | | | | 714 | | | | | \$ | 18,775.40 | | |

Requested By

Name- Zin Thu Nang

Sign-

Inventory Control

Approved By

Name- Si Thu Min Thein

Sign-

Part DH

8/16/2025

Acknowledged By

Name- Si Thu Min Thein

Sign-

Aftersale Manager

Acknowledged By

Name- Aung Thu Win

Sign-

02-COP-PRT-FRM-002-03