



PWINTHTOO SAN CO.,LTD

Invoice SI-PRT-PHK-CE1-2023-09-00398

Invoice Date:
09/29/2023

Due Date:
10/29/2023

Source:
SO-PRT-PHK-CE1-2023-09-00464

Description	Quantity	Unit Price	Taxes	Amount
[15011490] Overhaul Kit	1.00 PC	4,762.99	5%	\$ 4,762.99
[21739130-CEI] Exhaust Valve	6.00 PC	78.28	5%	\$ 469.68
[20459962-CEI] Valve Seat, Inlet (Engine Head)	6.00 PC	21.14	5%	\$ 126.84
[20405897-CEI] Valve Guide, Cyl: head	12.00 PC	19.10	5%	\$ 229.20
[11700348] O-Ring, Valve Seal	12.00 PC	3.13	5%	\$ 37.56
[21141948-CEI] Main Bearing (STD=85.00mm), Crankshaft	7.00 PC	46.54	5%	\$ 325.78
[20766790-CEI] Big End Bearing, Crankshaft (STD68, 00MM)	6.00 PC	45.87	5%	\$ 275.22
[21141955-CEI] Raceway Washer (STD=29Mm), Crankshaft	2.00 PC	41.20	5%	\$ 82.40
[21896344] Inlet Valve, Engine Head	6.00 PC	73.16	5%	\$ 438.96

PHK COUNTER
PHK/INV/CEQ/2023/09/0467
PHK-BSO-PRT-2023-09-0037
(21-9-23)

Untaxed Amount	\$ 6,748.63
Taxes	\$ 337.43
Total	\$ 7,086.06

Please use the following communication for your payment : **SI-PRT-PHK-CE1-2023-09-00398**

Payment terms: 30 Days

PHK COUNTER
PHK/INV/CEQ/2023/09/0467
PHK-BSO-PRT-2023-09-0037
(21-9-23)