

ADVANCE PAYMENT FORM

Requestor Name : Thandar Soe(2)	Budget Type : Include Budget
Department Name :	Payment Type : Advance Payment
Payment Date : 2025-05-28	Advance Due Date : 06/06/2025
Payment Voucher : ADV-COP-2025-05-00034	Prepared By : COP_BudgetDataEntry
No	Superior Approved : F&AManagerCOP
Payment Method : Cash/Bank	By
Payment Amount : 1000000.0	Last Approved By : Aye Min Htun
Currency : MMK	
Exchange Rate : 4,440.0	

No.	Description	Department	Paid Amount	Remark
1	Advanced Pay For Need to Machine Repair Emergency (on time) for Track Link Dismounting and Cutter For ZX280LC-5GX1U#410007 (Repossessed Machine) For Transportation Issue in Jungle because of Machine is Breakdown Condition During Repossessed action way . Issue By - Thandar Soe , Issue Amount - 1,000,000 MMK .	Service Department(COP)	1,000,000.00	Advanced Pay For Need to Machine Repair Emergency (on time) for Track Link Dismounting and Cutter For ZX280LC-5GX1U#410007 (Repossessed Machine) For Transportation Issue in Jungle because of Machine is Breakdown Condition During Repossessed action way . Issue By - Thandar Soe . Issue Amount - 1,000,000 MMK

Expense Total	1,000,000.00 K
Amount Remain	1,000,000.00 K

Note: _____

Hlaing

Paid By
Name : Su Su Hlaing
NRC No : _____
Date : 28/05/25

Thandar

Received By
Name : Thandar Min Thei
NRC No : 121 (Pamambon) 104708
Date : 28.5.25.

No. 152, Hlaingtharya Industrial Zone (4)
Min Gyi Mahar Min Street, Hlaingtharya, Yangon

ADVANCE REQUEST FORM

Requestor Name : Thandar Soe(2)

Budget Type : Include Budget

Department Name :

Payment Type : Advance Payment

Request Date : 2025-05-23

Advance Due Date : 06/06/2025

Payment Voucher : ADV-COP-2025-05-00034

Prepared By : COP_BudgetDataEntry

No

Superior Approved : F&AManagerCOP

Payment Method : Cash/Bank

By

Payment Amount : 1000000.0

Last Approved By : COP_BudgetDataEntry

Currency : MMK

Exchange Rate : 4,440.0

No.	Description	Department	Request Amount	Remark
1	Advanced Pay For Need to Machine Repair Emergency (on time) for Track Link Dismounting and Cutter For ZX280LC-5GX1U#410007 (Repossessed Machine) For Transportation Issue in Jungle because of Machine is Breakdown Condition During Repossessed action way . Issue By - Thandar Soe , Issue Amount - 1,000,000 MMK .	Service Department(COP)	1,000,000.00	Advanced Pay For Need to Machine Repair Emergency (on time) for Track Link Dismounting and Cutter For ZX280LC-5GX1U#410007 (Repossessed Machine) For Transportation Issue in Jungle because of Machine is Breakdown Condition During Repossessed action way . Issue By - Thandar Soe , Issue Amount - 1,000,000 MMK .

Expense Total 1,000,000.00 K
Amount Remain 1,000,000.00 K

Note:

BLN Trip < Measuring Job Site > for 280LC-5-5GX1U#410007.

<p>Superior Check By  Name : Sai Noh Ko NRC No : - Date : 26/05/25 Remark : -</p>	<p>F&A  Name : Tin Zax Hlaing NRC No : - Date : 26/05/25 Remark : -</p>	<p>GMVACM  Name : Aung Hlaing Win NRC No : - Date : 26/05/25 Remark : -</p>	<p>COO  Name : Aye Min Htoon NRC No : - Date : 26/05/25 Remark : -</p>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------







