





ADVANCE CLEAR VOUCHER

Requestor Name : Phyu Phyu Win(5)	Budget Type : Exclude Budget
Department Name:	Payment Type : Advance Clearing
Request Date : 2025-07-10	Advance No : UBG-CE1-2025-04-00034
Payment Voucher : AC-CE1-2025-07-00006	Prepared By : CE1_BudgetDataEntry
No	Superior Approved : CE1_ServiceDH
Payment Method : Cash/Bank	By
Payment Amount : 728000.0	Last Approved By : CE1_ServiceDH
Currency : MMK	
Exchange Rate : 4,510.0	

No.	Description	Department	Request Amount	Remark
1	Advance clear for TA charges for HML branch support job. Customer - Daw Ni Ni Myint (EC210BP#74771), Problem - Engine Overhaul. PIC - Nay Lin Naing	Service(CE1)	728,000.00	

Expense Total	728,000.00 K
Advance Total	300,000.00 K
Additional	428,000.00 K

Note:

	 Superior Check By Name : <u>Aung Ko Mon</u>	 F&A Name : <u>Saw Nlon Hlaing</u>	 GM/AGM Name : <u>Min Thee Ya</u>	 COO Date : <u>10/07/2025</u> Name : <u>Aye Min Htoon</u>
Name	Name	Name	Name	Name
NRC No	NRC No	NRC No	NRC No	NRC No
Date	Date	Date	Date	Date
Remark	Remark	Remark	Remark	Remark


 Phyu Phyu Win



TRAVELLING REPORT

Date : 27.4.2025.....

Report To	Aeng ko Min, Min Thu Ya, Zaw Min Myat	
Employee Name	Nay Lin Naing	
Position	Tech-support	
Department	Service	
Business	CE 1	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	28.4.2025 (5:00 PM)	6.6.2025 (4:30 PM)
Total Days	39 days	
Trip Information	1. From Yane To MDY	
	2. From MDY To HML	
	3. From HML To MDY	
Purpose For Travelling	For HML BR support job. Customer. Zaw Ni Ni Myint (EC2108P# 74731) Problem. Engine overhaul.	
Travel Date	Activities	Remark
28.4.25	Go to MDY. (
29.4.25	Preparing for special tools at MDY.	
30.4.25	Go to HML.	
1.5.25	Waiting for HML service to come back from job site	
2.5.25	Go to Lay Shi.	
3.5.25	Arrival to Lay Shi. Go to job site.	
4.5.25	Engine block cleaning	
5.5.25	Engine block measuring	
6.5.25	connecting measuring	
7.5.25	Engine block & components cleaning	
8.5.25	crankshaft, connecti & piston installation	
9.5.25	Flywheel, oil pump, & oil sump installation	

Reported by
 Sign :
 Name : NLN
 Position : Tech-support

Checked by
 Sign :
 Name : Min Thu Ya
 Position :

Approved by
 Sign :
 Name : Aung Mye Aung
 Position :
 16/07/2025
 (COO)
 Aung Mye Aung
 10/7/25.

(DH/AGM/GM)

(COO)

05-CHL-HRM-FRM-064-01

Engine Overhauling - 39 days.
 Travelling - 16 days -
 23 days (OVH)

10. Radiator & CAC cleaning (without disassembling)
11. Engine head & other accessories installation
12. Fuel components installation
13. Sending engine to break down machine.
14. Engine mounting, radiator & CAC installation
15. main pump room cleaning & installation
16. cover & accessories installation
17. Fan, coolant pump & feed pump installation
18. Hydraulic & coolant filling / preparing for test run
19. Test run (low idle)
20. Test run (low idle)
21. Test run (High idle)
22. Machine allocation (test run about 1hr)
23. Waiting for the operator (there was bad weather at lay Shi)
24. Machine test run with load (1 & half hours)
25. Test run with full load (45 min) / Overheat because of clogged radiator
26. Dismounting radiator
27. Send the radiator & go back to lay Shi
28. Discussing with customer to repair or buy new radiator
29. Waiting for the car because of bad weather
30. Waiting for the car (bad weather)
31. Waiting for the car (bad weather)
1. Waiting for the car (bad weather)
2. Go back to HML
3. Send the radiator to local workshop
4. Go and check the radiator (It was clogged)
5. Knowledge sharing to service team (Basic Hydraulic & Electric)
6. Follow up radiator condition (It would take much time to clean fully opened).
7. Go back to MDY.
- 8.

ZR-3400

Handwritten Burmese text, possibly a name or company name.

From (၄) Mandalay

Transportation (၄) Contact (၄)
Nay Lin Hsing 0979895

Seat(s) (ခုံနံပါတ်များ)
24

Class/Type Bus No (ကားနံပါတ်)
Sagat 12

Booking Reference Status
5045-8373 CONFIRMED

Departure (ခရီးစဉ်) Date/Time
Apr 28, 8:00 PM Aung Myethazan Bus

Cancelled Time
Apr 28, 7:44 PM

Passengers 1
Total 5,000

Check in 30 min before the departure time
No refund after the purchase

Contact Phone: YGN 092050907
MGN 092050918, PGN 092050917, Sagat 12 Bus
TPT 0995232415



No 589-592,Bo Aung Kyaw Street,Yangon-Pathcin High Way Road,Hlaing Thar Yar Township, Yangon, Myanmar

Print Date : 10-Jul-2025

Taxi (Bus,Motorcycle,3-wheel etc...) Charges Form

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	State	Remark
1	2025-06-27	Construction Equipment 1	Service	Nay Lin Naing	For NAS branch support job. Customer - Ko Myint Thu (EC210DL#281192), Problem - Engine Overhaul	08:00	Aungmyingalar	Hlaingtharyar	20,000	20,000	GA Manager Approved	
2	2025-04-28	Construction Equipment 1	Service	Nay Lin Naing	For HML branch support job. Customer - Daw Ni Ni Myint (EC210BP#74771), Problem - Engine Overhaul	05:00	Hlaingtharyar	Aungmyingalar	20,000	20,000	GA Manager Approved	
3	2025-04-30	Construction Equipment 1	Service	Nay Lin Naing	For HML branch support job. Customer - Daw Ni Ni Myint (EC210BP#74771), Problem - Engine Overhaul	09:00	Mandalay industrial zone	Mandalay Airport	40,000	40,000	GA Manager Approved	
4	2025-06-06	Construction Equipment 1	Service	Nay Lin Naing	For HML branch support job. Customer - Daw Ni Ni Myint (EC210BP#74771), Problem - Engine Overhaul	04:30	Mandalay Airport	Mandalay Office	40,000	40,000	GA Manager Approved	