

TOOLS DAMAGE REPORT FORM



Chrysanthemum wealth
အမှတ်အသားများ

Date : 18-12-2024

Reason:

Damage
 Lost

PIC Section Name Production


Previous Handover Data

Doc. Refr. No. : _____

Date : _____

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Meter	DM200	-	China	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

We have four section, as Engine, Power Train, BOS and Machining. We would like to separate this meter for only maintenance PIC to finish job in time.

Department Head Judgement/ Decision

Use this meter for maintenance and checking Electric power cases.

For Reported By

Samyathrin

Checked By

Theiraculatt

Approved By

WinAung

.....*Samyathrin*.....
Mechanic

.....*Theiraculatt*.....
Supervisor

.....*WinAung*.....
Department Head

Myint Thein & Brother = 100,000 ~ 150,000 = 09-666888119

Hkun Lin = 130,000/- = 09-448228921

Cause of Damage

02-BRM-PDD-FRM-009-00



chrysanthemum wealth
ကမ္ဘာ့အကျိုးစီးပွား

TOOLS DAMAGE REPORT FORM



Date : 18-12-2024

Reason: Damage
 Lost

PIC Section Name Machining & Fabrication


Previous Handover Data

Doc. Refr. No. : _____

Date : _____

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Measuring Tape	-	-	China	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

Base on the usage and life time, the ruler dimension can't read clearly.

Department Head Judgement/ Decision

For Bucket and other dimension process, we want a new measuring Meter.

For Reported By
Thun
.....Sumeethun.....
Mechanic

Checked By
[Signature]
.....The Zawlat.....
Supervisor

Approved By
[Signature]
.....Win Aung.....
Department Head

Myint Thin & Brother = 15,000/- ~ 20,000/-

Cause of Damage

02-BRM-PDD-FRM-009-00

TOOLS DAMAGE REPORT FORM

anthem wealth

Date : 18-12-2024

Reason:

Damage
 Lost

PIC Section Name

Production


Previous Handover Data

Doc. Refr. No. :

Date :

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Micrometer	0-25	Miyutoyo	-	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

For accurate and quality measurement, we need the 0-25 mm micrometer for all measuring sections.

Department Head Judgement/ Decision

All overhaul jobs concern and use this range micrometer to know have limit or not.

For Reported By

Thiu
 Su Myat Hnin
 Mechanic

Checked By

Teet Zaw Latt
 Supervisor

Approved By

Win Aung
 Department Head

Emin Company ⇒ Brand ⇒ Miyutoyo ⇒ 120,000/- ⇒ 09-452641600

Khin Maung Oo ⇒ Miyutoyo ⇒ 80,000/- ⇒ 09-797974200

02-BRM-PDD-FRM-009-00

Cause of Damage

TOOLS REQUEST FORM



Date: _____

Request Section Recon (Production)
 Country Maker _____
 Brand _____

Types of Tools

- Common Tools
- Measuring Tools
- Installation Tools
- Special Tools

Applicable for _____

Back Ground History

A grease gun is essential for filling grease for unit machine (Especially, now sold out machines).

Purpose of Request

To fill the grease in machine.

Required Raw Material (if the tools is made in Local)

No	Tools Name	Dimension	Qty	Unit	Remark
1.	Grease Gun		1	pc	

Requested By
Mechanic

Sign:

Name Hein Min Htet

Checked By
Section Head

Sign:

Name Aung Mya Khin

Approved By
Production Manager

Sign:

Name U Win Aung

Received By
Admin

Sign:

Name Ayein Shwe Zow

Ngwe Zin Yaw => China => 40000 / ~ 59000 / - 09 - 775522995

02-BRM-PDD-FRM-010-01