



CASH ADVANCE REQUEST FORM

Date : 8 / 11 / 2023  
 BU/BR/Division : Reman  
 Department : Production  
 Advance Issue : 604000 Kyats / 604000 \$in USD

Yes  Budgeted Title and Amount : Machine Repair  
 No  Reasons for :

Required For: To buy damage tools and new tool for m/f

မှတ်ချက်။  
 (၁) ကြိုတင်ငွေများကို သာမန်အားဖြင့် ထပ်ယူသည့်နေ့မှ (၁၀) ရက်အတွင်း ပြန်လည် တရားရှင်းရမည်။  
 (Advance must be cleared within 10 days from issue date)  
 (၂) အဆင့်ဆင့်သက်ဆိုင်ရာတာဝန်ရှိလူကြီးမင်းများအားလုံး သေချာစွာစစ်ဆေးစစ်ဆေးတွက်ချက်ပြီးထားသော ငွေပမာဏဖြစ်ရပါမည်။  
 (The amount requested must be properly calculated, checked and verified by respective authorized person)  
 (၃) ထုတ်ယူငွေနှင့် ပတ်သက်၍ အမှားအယွင်း၊ လိမ်လည်မှု နှင့် အလွဲသုံးစားမှု တစ်စုံတစ်ရာ ရှိခဲ့ပါက သက်ဆိုင်ရာ တာဝန်ရှိစစ်ဆေးအတည်ပြုသူက အပြည် အဝ ပြန်လည်ရရှိအောင် တာဝန်ယူ ဆောင်ရွက်ပေးရမည်။  
 (If there is errors, frauds or misappropriation, the authorized person must take full responsibility to recover the loss)

Request By : *Shwe Sin*  
 Checked By : *Ncing Tun Lin*  
 Checked By : *Zo Ni Shwe Aung Aung Hein Win*  
 Approved By : *[Signature]*  
 Approved By : *[Signature]*  
 Date: 8/11/2023

Shwe Sin Requester  
 Ncing Tun Lin Mgr/DH  
 Zo Ni Shwe Aung Aung Hein Win Finance & Account GM/AGM/COO CMC/CEO/Chairwoman

13/11/2023  
 Amikom  
 04-CFD-CAS-FRM-001-03

Date: 31.10.23

Request Section Welding section  
Country Maker \_\_\_\_\_  
Brand \_\_\_\_\_

**Types of Tools**

- Common Tools
- Measuring Tools
- Installation Tools
- Special Tools

Applicable for welding  
(Cast iron)

**Back Ground History**

When doing the welding, welding smell is evocation. At this time welder is inhale its smell. So, welder is unhealthy.

**Purpose of Request**

Welder need to prevent <sup>use</sup> welding smell inhale by safety tool.


**Required Raw Material ( if the tools is made in Local)**

It never used/required in Reman.  
Cast iron welding have problem is big cause of smell. So, He want to buy/Apply their cover (3pcs)

No	Tools Name	Dimension	Qty	Unit	Remark
<del>1</del>	<del>Gaming glass filter Mask</del>	<del>ABW</del>	<del>3</del>	<del>pcs</del>	<del>Need to gaming process safety eyes cover.</del> Need to filter Mask to prevent welding smor.

Requested By Mechanic Sign: <u>[Signature]</u> Name: <u>A.T. Hen</u>	Checked By Section Head Sign: <u>[Signature]</u> Name: <u>M.M.H.</u>	Approved By Production Manager Sign: <u>[Signature]</u> Name: <u>NTTL</u>	Received By Admin Sign: <u>[Signature]</u> Name: <u>Amy Hen Utm.</u>
-------------------------------------------------------------------------------	-------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------

# TOOLS DAMAGE REPORT FORM



Physanthemum wealth

Date : 27-Oct-23

PIC Section Name Machining


Reason:  Damage  
 Lost

Previous Handover Data

Doc. Refr. No. : \_\_\_\_\_ Date \_\_\_\_\_

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Wire extension		-	-	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

Welding area has extension wire cable insulator (teaver) is so many crack, can't safety. Usage time is over 5 year. So, need to replace it.

Department Head Judgement/ Decision

That 5 year. Already used. So, need to change new one.

Reported By

*[Signature]*

Mechanic

Checked By

*[Signature]*  
Mys. Man. Hbe

Supervisor

Approved By

*[Signature]*  
6.11.23

Department Head


11.3.2022

02-BRM-PDD-FRM-009-00

Cause of Damage

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6) Consume life of Tools
- 7) Poor maintenance

# TOOLS DAMAGE REPORT FORM



Chrysanthemum wealth  
အမှတ်အသား

Date : 27. Oct - 23

PIC Section Name Machining


Reason:  
 Damage  
 Lost

**Previous Handover Data**

Doc. Refr. No. : \_\_\_\_\_ Date \_\_\_\_\_

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Collect set		-	-	1	

**Photo attach of Damage Tools**



**Supervisor Analyze Commence**

Milling mlc have M140 collect set. we use over 10 years.  
 Now, collect hole is bigger, so, can't tight drilling or boring tool.  
 need to replace it.

**Department Head Judgement/ Decision**

Over 10 years. used to <sup>service</sup> ~~use~~ annual the machine. so, need to buy with new.

Reported By

Mechanic

Checked By

M. P. H.

Supervisor

Approved By

6/11/23

Department Head

02-BRM-PDD-FRM-009-00

**Cause of Damage**

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6) Consume life of Tools
- 7) Poor maintenance

# TOOLS DAMAGE REPORT FORM

Fluoranthemum wealth  
 ၂၀၁၅ ခုနှစ်



PIC Section Name Machining

Date : 27-Oct-23

Reason:  Damage  
 Lost

Previous Handover Data

Doc. Refr. No. : \_\_\_\_\_

Date 27-Oct-23

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Grinding glass		-	-	5	

Photo attach of Damage Tools



Supervisor Analyze Commence

Mirror cover is misty. So, can't see clear. Need to replace it.

Department Head Judgement/ Decision

Grinding processes have small particles out to glasses while grinding. So, this can't use long time, we will replace it in (three to six) months.

Reported By

*[Signature]*

Mechanic

Checked By

*[Signature]*

Supervisor

Approved By

*[Signature]* 6-11-23

Department Head

PIC Name -


02-BRM-PDD-FRM-009-00

Cause of Damage

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6)  Consume life of Tools
- 7) Poor maintenance

11.3.2022

# TOOLS DAMAGE REPORT FORM



Date : 27-oct-23

Reason:

Damage  
 Lost

PIC Section Name

Machining


Previous Handover Data

Doc. Refr. No. :

Date

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Limit Switch		-	-	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

Milling m/c have limit switch cover is crack. Limit bar is break out, so, need to repair it. (Motor brake limit switch)

Department Head Judgement/ Decision

Ald Repair <sup>current</sup> cost not ok. This limit switch never change since arrival time, so we need to change with new one.

Reported By

*[Signature]*

Mechanic

Checked By

*[Signature]*

Supervisor

Approved By

*[Signature]* 28/11/23

Department Head

02-BRM-PDD-FRM-009-00

Cause of Damage

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6) Consume life of Tools
- 7) Poor maintenance



# TOOLS DAMAGE REPORT FORM



Prosperity wealth  
ပေးရန် ကြိုးပမ်းပါမိန့်

Date : 27-Oct-23

PIC Section Name Machining

Reason:  Damage  
 Lost

**Previous Handover Data**

Doc. Refr. No. : \_\_\_\_\_

Date 27-Oct-23

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Wending handle		-	-	1	

**Photo attach of Damage Tools**



**Supervisor Analyze Commence**

So many jobs doing welding process, welding handle has crack and welding rod tighten area is burn. So, can't use it.

**Department Head Judgement/ Decision**

Life time depend on work (3 PCs / month) . So they request (2 pcs) for consumable purchase our stock.

Reported By

*[Signature]*

Mechanic

Checked By

*[Signature]*  
Myo Min Htoo

Supervisor

Approved By

*[Signature]*  
6.11.23

Department Head

purchase Date (11-3-23).


02-BRM-PDD-FRM-009-00

**Cause of Damage**

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6)  Consume life of Tools
- 7) Poor maintenance



# TOOLS DAMAGE REPORT FORM



panthemum wealth  
Engineering Solutions

Date : 27 - Oct - 23

PIC Section Name

Machining

Reason:

- Damage  
 Lost


previous Handover Data

Doc. Refr. No. :

Date

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Tape		-	-	1	

Photo attach of Damage Tools



Supervisor Analyze Commence

Measuring Tape is break out. So, can't use. need to replace it.

Department Head Judgement/ Decision

Measuring tool for measuring length, wide, high onto on. that tool will be crack/damage with with

Reported By

*[Signature]*

Mechanic

Checked By

*[Signature]*

Supervisor

Approved By

*[Signature]* 21.11.23

Department Head


Cause of Damage

- 1) Material weakness of Tools <sup>1</sup>
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- ~~6) Consume life of Tools~~
- 7) Poor maintenance

( 5 - Jul - 23 )

02-BRM-PDD-FRM-009-00

# TOOLS DAMAGE REPORT FORM



Chrysanthemum wealth

Date : 27-06-23

PIC Section Name

Machining

Reason:

- Damage
- Lost

**Previous Handover Data**

Doc. Refr. No. :

Date

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Triangle ruler 160/260		-	-	1	

**Photo attach of Damage Tools**



**Supervisor Analyze Commence**

When using long time, angle join area is loose. so, can't measure go/L.

**Department Head Judgement/ Decision**

Crack of the weld on mold near go/L. That can't repair cause of go/L different to zero section. So, can we request new one. This tool is long time used. in machining section.

Reported By

*[Signature]*

Mechanic

Checked By

*[Signature]*  
Mrs. Man...  
Supervisor

Approved By

*[Signature]*  
6.10.23  
Department Head

PIC Name - ?

02-BRM-PDD-FRM-009-00

**Cause of Damage**

11.8.2022

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6) Consume life of Tools
- 7) Poor maintenance

# TOOLS DAMAGE REPORT FORM

PIC Section Name Machining

Date : 27-Oct-23


Reason:  Damage  
 Lost

**Previous Handover Data**

Doc. Refr. No. : \_\_\_\_\_ Date 27/10/23

No	Name of Tools	Code of Tools	Brand	Country Made	Qty	Damage or Lost problem Description
1	Limit Switch		-	-	1	

**Photo attach of Damage Tools**



**Supervisor Analyze Commence**

Milling m/c have limit switch cover is crack and limit bar is break part. So, need to replace it. (Table stop limit switch).

**Department Head Judgement/ Decision**

10 years over. used the machine at arrival long, so our team already repair and apply. Now, new steel to change with new one.

Reported By

*[Signature]*

Mechanic

Checked By

.....

Supervisor

Approved By

*[Signature]*  
6-11-23

Department Head

02-BRM-PDD-FRM-009-00


**Cause of Damage**

- 1) Material weakness of Tools
- 2) Wrong operation
- 3) Wrong application
- 4) Improper storage/ keeping
- 5) Careless of user
- 6) Consume life of Tools
- 7) Poor maintenance




**Ko Aungko Ko**

last seen recently



Damage tool long for M/F-604000

11:57 AM ✓✓



11:57 AM ✓✓

PT approve 12:18 PM

**Canceled Call**

➔ 12:18 PM



Shwe Sin  
Album

approve 12:25 PM



Shwe Sin  
Photo

Approve 12:26 PM



Shwe Sin  
Album

Approve 12:26 PM

