

# Job Order Information

**Status:** Job Finish

**Job Order Type:** Inquire

**Job Order Number:**  
CE3/JR/25/01/0045

**Inquire Number:**  
CE3/INQ/25/01/0046

**Open Date Time:**  
01/23/2025 13:30:38

**Close Date Time:**

**Customer Name:** ASIA  
CONCRETE PRODUCT  
CO.,LTD

**Job Classification:**  
Machine test run and  
calibration

**Phone:** 09977119358

**Standard Hour:** 72

**Machine Name:** ZYJ260B-  
II(S00127)

**Job Type:** Field

**Problem:** Machine  
Calibration

**Job Site Distance:**  
16.8655764, 96.0524757

# Service Information

**Date Request:**  
01/23/2025

**Charges:** Charges

**Technical Note:**

**Spare Parts Note:**

**Tools:**

**Priority:**

# Job Assign

**Mechanic Leader:** Hein  
Thiha Soe

**Assign Date:** 01/23/2025

**Mechanic:** Nyi Htet Ko

**Schedule Date Time:**  
01/23/2025 09:04:38


# Overall Checking

Checking Date	Machine Hour	Machine Km	Note

---

01/24/2025      0.0      0.0  
08:16:40

---



## Service Report

---

Report Date Time	Status	Report
01/24/2025	Job Finish	Go to job site Heineken Company Firstly waiting customer and Operator for discuss of the machine. Andthen check the machine visually. Check the hydraulic pressure among then we found oil Leakage. We adjustment pressure All Ok. Customer relation is Good at .

---



## Job Finish

**Finish Date Time:**  
01/24/2025 14:37:02

**Customer Sign:**

**Closing Note:** Finished  
**Customer Name:** ASIA  
CONCRETE PRODUCT  
CO.,LTD

**NRC:**

**Phone:** 09977119358

# Invoicing

**Invoice Date:** 02/07/2025

**Invoice Sign:**

**Invoice Amount:** 87.527

**Is Paid:**

**Received Date:**

02/06/2025

**Remark:**

Cash/400,000MMK/4570