



# ချော့ခွ ( P.K.R )

## စက်သုံးဆီအရောင်းဆိုင်၊ ဘားအံမြို့

ဝယ်ယူသူ/ယာဉ်အမှတ်၊ \_\_\_\_\_

နေ့စွဲ၊ 3.5. 2025

စဉ်	အမျိုးအစား	အရေအတွက်	ဈေးနှုန်း	ကျသင့်ငွေ	မှတ်ချက်
	၇၃	၄.၃၇ ခဲ	၃၇၃၀	၁၆၀၀၀	
	ပေါင်း			၁၆၀၀၀	

ထောင်စီ

- Ph; 09-429773931, 09-886421498

HPN Br  
ဆိုင်ကယ်

MON-58W  
22985

*Shwe eky*

ရောင်းချသူလက်မှတ်၊

Age



### TRIP CAR USED FORM

BU/BR/DIV : MC  
 Driver Name : Thura Min  
 Car User Name : Thura Min  
 Trip Title : အိတ်အိတ်အိတ်. After Sale Service (Stock - Cargo - 56814)  
 Trip Location : မင်း  
 Car No. : MCN-580V 22985  
 Car Type : Motorcycle (Honda)  
 Estimate Date : 4-day  
 Participant :

Date	Start Kilo	End Kilo
2.5.2025	မင်းထွန်းဝင်း အိတ်အိတ်အိတ်အိတ်	
3.5.2025	မင်းထွန်း(ဒေါ်) အိတ်အိတ်အိတ်အိတ် (ကပ်)	
4.5.2025	မင်းထွန်း(ဒေါ်) အိတ်အိတ်အိတ်အိတ်	
5.5.2025	မင်းထွန်း(ဒေါ်) အိတ်အိတ်အိတ်အိတ်	

Request By

Requester

Checked By

Related GM/AGM

Acknowledge By

GAV Head

Approved By

CAM GM/AGM/COO

05-CHL-GAV-FRM-015-01



No.589-592,Bo Aung Kyaw Street,Yangon-Pathein High Way Road.Hlaing Thar Yar Township. Yangon, Myanmar.

Print Date : 16-May-2025

**Taxi (Bus, Motorcycle, 3-wheel etc...) Charges Form**

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	State	Remark
1	2025-05-02	Motorcycle (Yangon)	Service	Thura Min	After Sale Service	06:30	UD Hlaing Thar Yar	Aung Mingalar Bus Stop	28,000	28,000	GA Manager Approved	For Plantation Stock (still HPN BR)
2	2025-05-06	Motorcycle (Yangon)	Service	Thura Min	After Sale Service	16:30	Aung Mingalar Bus Stop	UD Hlaing Thar Yar	28,000	28,000	GA Manager Approved	Go back home

56000

Toe Chae Bus Stop (Hlaing Th...)

47 min - 19.3 km

Aung Mingalar Highway Bus S...

Mayangon

Kyu Sann Village

You

GroMops

**Taxi**  
 Est. 1 min away • 8.4  
 Taxi with affordable, upfront fixed fares

**K528,500**

Near Yangon-Pathwin Highway

39 min - 20.8 km

Aung Mingalar Highway Bus S...

Mayangon

Kyu Sann Village

You

GroMops

**Taxi**  
 Est. 3 mins away • 8.4  
 Taxi with affordable, upfront fixed fares

**K528,700**

## Trip Summary

Yangon	May 02, 8:00 AM
Hpa-An	May 02, 4:00 PM

Arrival times provided are estimates and may be subject to change. \*

Bus Operator	Shwe Mandalar
Bus Type	(Scania) Standard ✓
Number of Seats	1
Seat No.	16

## Notices by Shwe Mandalar

- Please Bring Your NRC Card
- Foreigner Not Allow

## Traveller Information

Name	Thu Ya Min
Phone	09754909362
Email	thuyaminumgmfy2002@gmail.com

## Special Request to Shwe Mandalar

None

Total Amount

MMK 21,000 ✓

## Booking Number

3832-6508



Scan the QR code to verify and access further details.

## Shwe Mandalar Hotlines

YGN - 092228735, 09420720058,  
POL - 098303945, MWD -  
09785001750, Monywa - 07128227,  
MDY - 092028322, 091006424, NPT -  
06726286, TGI - 081208032, Bagan -  
0949600845, Meiktila - 06424306

Thank you for booking with us on [MMBusticket](#) . Hotline: 09 777 111 811



**Trip Summary**

 Hpa-An May 06, 8:00 AM  
Yangon May 06, 3:00 PM

Arrival times provided are estimates and may be subject to change. \*

Bus Operator Shwe Myanmar  
Bus Type Standard ✓  
Number of Seats 1^  
Seat No. 9

**Notices by Shwe Myanmar**

- Foreigner Not Allow
- NRC+Letter of Endorsement from ward+Letter of Endorsement from Police

**Traveller Information**

Name Thu Ya Min  
Phone 09754909362  
Email thuyaminumgmfy2002@gmail.com

**Special Request to Shwe Myanmar**

ထောင်စိဘုန်းကြီးကျောင်းဘေးက ယာဉ်ရုံ ရှေ့ကနေ စီးပါမည်

Total Amount MMK 15,000 ✓

**Booking Number**

6249-7019



Scan the QR code to verify and access further details.

**Shwe Myanmar Hotlines**

YGN-09255 330 055, 09255 949  
988,09444 428 700, Hpann-09 255  
330 033, 09 497 805 00

Thank you for booking with us on [MMBusticket](#) . Hotline: 09 777 111 811





# SERVICE REPORT



Job Order No MC-VIN-SR-75005026  
 Customer Name UMG Motors  
 Machine Location Hpa An Branch  
 Machine Model Cargo (Red)  
 Machine Sr.No MBX0000WBVH506814  
 Engine Sr.No .....  
 Houe Meter or) Km 3 km  
 Job Site Distance .....  
 Application .....  
 Number of Trip .....

	Date	Time
Customer Call Date	30.4.2025	4:00 PM
Confirm with Customer	1.5.2025	6:00 PM
Go to Job Site Time	2.5.2025	6:00 AM
Arrival Job Site Time	2.5.2025	4:40 PM
Job Start Time	2.5.2025	4:50 PM
Job Finish Time	5.5.2025	6:30 PM
Go Back from Site	6.5.2025	7:30 AM
Arrival Office Time	6.5.2025	5:30 PM
Job Delay Date&Time		
Reason of Job Delay		

Customer Call Problem Inspection & Repair

Cause of Problem Engine can't start (Battery voltage is low, rear tube is damage)

Service Action  
 - checked the current condition of vehicle (engine oil level, gear oil level, DC cable, Stop cable, clutch cable, reverse cable, lever cable, gear cable, fuel pipe, tyre, frame, door, wiper system, fuse, paint windshield, brake system, seat, steering system, light system, ignition system and etc).  
 - Battery voltage is low, rear tire is flat and other condition are good

Failure Causal Part

No	Part Description	Part No	Qty	Remark

Service Charges

Customer Sign ..... Service Person Sign *[Signature]*  
 Customer Name ..... Service Person Name IRM

Checked By Name: <u>Thura Min</u> Sign: <u><i>[Signature]</i></u> Service Man	Acknowledge By Name: <u>Saw Elsay Wah</u> Sign: <u><i>[Signature]</i></u> Service SH	Approved By Name: <u><i>[Signature]</i></u> Sign: <u><i>[Signature]</i></u> Service DH
--	---	---

02-BMC-ASD-FRM-004-01

- removed battery, tire and go to the battery charge shop, battery charge shop is closed, so return back and keep the battery at Hpa-An Br.
- And then go to the tire repair shop, analyze the wheel, inner tube is damage, can't use it according tire repair shop's suggestion.
- informed the MCBU about inner tube, requested to send inner tube for Cargo (814) red.
- And checked spare tire, spare tire psi is low, so refill the spare tire, it is ok.
- test with other battery to crank engine, it can crank the engine, wait idle for engine operation (5min).
- checking engine oil and gear oil leakage, it is ok.
- next day, go to the battery charge shop, charge the battery.
- after charged, take back to the vehicle and installed the battery.
- testing for engine crank, charging the battery, it is ok.
- checked again engine operation, it is ok.
- checked head light system, brake light system, it is not ok.
- checked wire harness, switch (LH, RH), brake switch.
- switch (RH) and brake switch are abnormal, so repaired them, it is ok.
- next day, received the inner tube, go to the tire repair shop, installed to the rear wheel, take back to the vehicle, installed the rear wheel to the vehicle.
- test drive the vehicle, take video, photo for vehicle testing (final).
- After that, cleaned the vehicle.
- job was finished.



MC BU & Aftersales Div  
20 members, 3 online

Ko Min Paing Phyo  
Dear Sayar, Ko Aung Hein Win ,

Please kindly approve to go Hpan BR to make inspection and delivery process to Kyaikto Plantation for Cargo-1 unit. 🙏  
Employee- Thura Min  
Go to job site date - 2-May-2025 (by bus)  
Estimated budget - 2 Lakhs (MMK)

Best Regard,  
Min Paing Phyo.



3 16:02

Aung Hein Win

Ko Min Paing Phyo  
Dear Sayar, Ko Aung Hein Win , Please kindly approve t...  
How is estimated lead time ?



16:04

Ko Min Paing Phyo

Aung Hein Win  
How is estimated lead time ?



Yes,we estimate 4 day. 🙏

16:06

Aung Hein Win

Please proceed

16:07



Ko Min Paing Phyo

Thanks Ko Aung Hein Win. 🙏

16:11



THS  
Forwarded from  
👤 THS

Dear All,

I would like to say "Goodbye" to all of you. Today is my last working day in UMG .

Thank you very much to you all of your Corporation & Supporting to me. During this 4.3 years, I got so many experiences and I learned a lot from all of you.



All of my duties & responsibility handover to Ko

GIF Message

