






# TRAVELLING REPORT

Date : .....

Report To	COO	
Employee Name	Nay Hsun Win	
Position	SH	
Department	Service	
Business	ATT-BU	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	25.12.24 8:30 am	11.25 8:00am
Total Days		
Trip Information	1. From ATT-BU (YGN) To MTL Branch	
	2. From ..... To .....	
	3. From ..... To .....	
Purpose For Travelling	Hydraulic oil leakage from four wheel shaft seal.	
Travel Date	Activities	Remark
25.12.24	Going to Job site from ATT BU (YGN)	
26.12.24	Our Service team go to Job site. And then, firstly visual checked and all oil level check, we test run the machine, we found the oil leakage from four wheel shaft seal and Gear Fork shaft seal.	
27.12.24	Our Service team firstly visual check and	

Reported by  
 Sign :   
 Name : Nay Hsun Win  
 Position : SH

Checked by  
 Sign :   
 Name :  
 Position :  
 (DH/AGM/GM)

Approved by  
 Sign :   
 Name :  
 Position :  
 (COO)

05-CHL-HRM-FRM-064-01