



## Concrete Equipment

### Good Receipt

Customer Name :  
Address :  
Phone :

GR No : BCE-GR-24100005  
GR Date : 2024-10-10 16:00:50  
Related No :

| No | Description                        | Part Number      | From Location | To Location | Qty  | UOM |
|----|------------------------------------|------------------|---------------|-------------|------|-----|
| 1  | Travel Motor Assembly<br>For ME220 | 730250000484-CNC | Service       | CNR_Part    | 1.00 | PC  |

**Note** : ME220, SH3003, Customer - U Zaw Zaw Latt(HML BR)  
Right Travel Function is slow & it can't operate sometime.  
got service warranty from Sunward supplier.  
PLO(This Parts Arrived by BU Return arrived on 10.10.2024 Checked by (YYK,SLM,HLZ)

Prepared By

Approved By

Validated By

Related By

BU DH

HO WHS/BU WHS