



### TRAVEL ADVANCE CLEAR FORM

Cash Advance				
Employee Name	Ang Myaw Myant	Estimated Date of Travel	4.11.24 10:00am to 5.11.24 8:30pm	
Position Rank	SH	Total Day	20 day	
BU/BR/DIV, Dept	AGI	Destination	MS BU SO Jenu Phye Job site	
Purpose	MT 804-4075, Customer - A Wan Nang, PSM abandoned (L, R), near one, winning.			
Travelling Permit				
Arrival Place				
Actual Date & Time of Travel				
Total Day				
HR Name				
HR Sign				
BOH/Authorized Person Name				
BOH/Authorized Person				
Advance Clear				
Actual Date & Time of Travel		Total Day		
Departure Date & Time		Arrival Date & Time		
Date	Description	Total Amount		
		Kyats	USD	
4.11.24 8:00am to 5.11.24 8:30pm	Ang Myaw Myant (15000 x 20)	300,000		
	Express charges	12000		
	Labour charges	45000		
	Uge Sine	12000		
	Tonei charges	32000		
<b>Total Expense (Kyats/USD)</b>		<b>497,000</b>		
<b>Cash Advance (Kyats/USD)</b>		<b>100,000</b>		
<b>Balance Refund/Additional (Kyats/USD)</b>		<b>397,000</b>		
Job Report Status				
Authorization	Name	Position	Date	Sign
Prepared By	Ngom Ngom	Sm Staff	11.12.24	Ng
Approved By Dept Head	Ko Ang Myaw Thu	Sr SH		
Approved By GM/AGM/COO	Ko Maung Maung	GM		
Acknowledged by related Superior for Job Report				
HR Check & Approved	Zin Mor Wor			
Cash Received				
Remark				

04-CFD-CAS-FRM-006-02

# ရတနာ

## အဆင့်မြင့်ခရီးသည် ဖွဲ့စည်းရေး

ရန်ကုန်ဂိတ်တည်နေရာ - အမှတ် (၁/၂၇)၊ ကျိုက်လတ်လမ်း၊ လှိုင်သာယာ (ဒဂုံဧရာ)။

မြန်အောင်-ကြာင်း-ဘက်ရဲ-တွင်းကောက်-ပြည်-ဟင်္သာတ-ပုသိမ်-မကွေး-ရန်ကုန်

ဘက်ရဲ-ကြာင်း-မြန်အောင်-ဟင်္သာတ-စနေဖြူ-မအူပင်-ကျိုက်လတ်-ဗဟု-ရန်ကုန်

မည် အောင်ကျော်စွာ ခရီးစဉ် ..... ထိုင်ခုံအမှတ် ..... ရက်စွဲ ၂၀၂၄.၀၅.၂၅ ထွက်ချိန် ..... သင့်ငွေ ၄၀၀၀

- ရန်ကုန်ဂိတ် - 09-790711534, 09-683020730, 09-777984616, 09-777984168, 09-777983155,
- မြန်အောင်ပင်မဂိတ် - 09-756553168, 09-682351770, 09-422523752, 09-785111300
- ကြိုခင်းဂိတ်ဟောင်း - 09-798026130, 09-691634144 ကြိုခင်းဂိတ်သစ် - 09-766605310, 09-670710766
- ဘက်ရဲဂိတ် - 09-422506633, 09-957775435, မဲဇလီကုန်း - 09-778837237, 09-779730641
- ဟင်္သာတဂိတ် - 09-441455500, 09-255231255, ထူးကြီးဂိတ် - 09-777437156, 09-790225915
- ဧရာပုံဂိတ် - 09-766605838, 09-670732866
- ပုသိမ်ဂိတ် - 09-422445854, 09-791393670
- ပြည်ဂိတ် - 09-793511224, 09-452335934
- မကွေးဂိတ် - 09-777785488, 09,794569488
- မင်းဘူးဂိတ် - 09-796033128 မဒါန်းဂိတ် - 09-799927065

မှတ်ချက်။ ။ ယာဉ်ထွက်ပိမံနစ်(၃၀)ကြိုတင်အရောက်လာရမည်။ ဝယ်ပြီးလက်မှတ်ငွေပြန်မအမ်းပါ။ လက်မှတ်ဝယ်ယူပါက သွားမည်ရက်၊ အချိန်၊ ခရီးစဉ်အား သေချာစွာစိစစ်ပြီးမှ ဝယ်ယူပါရန်။  
တန်ဆာပေးဆောင်ခြင်းမရှိသော ကုန်ပစ္စည်းများအတွက်၊ မိမိတကာဝန်သာဖြစ်သည်။ တန်ဆာပေးဆောင်သောပစ္စည်းပျောက်ဆုံးပါက တန်ဆာခင်း(၁၀)သက်ပေးလျော်မည်။

3			
4			
5			
6			
7			
8	Paid		
9			
10			
11			
12	PIC - AKM		
13			
14			
15			
16			
17			

45000

Issued by \_\_\_\_\_ Approved by \_\_\_\_\_

Sign : \_\_\_\_\_

Name : \_\_\_\_\_

GM/GM) (ACOO/COO/MD/VCMD)

02-ATT-FNA-FRM-002-0

မှတ်ချက်။ ။ ကျောဘက်ပါစည်းကမ်းချက်များကိုလက်ခံ  
သဘောတူပါသဖြင့် အထက်ပါပစ္စည်းများကိုပေးပို့ပါသည်။

ပေးပို့သူအမည် -----  
လက်မှတ် -----

Total Amount/ စုစုပေါင်း: \_\_\_\_\_

Advance/ စရံငွေ: \_\_\_\_\_

Balance/ လက်ကျန်ငွေ: \_\_\_\_\_

# ရတနာ

မေ့

သံသ

## အဆင့်မြင့်ခရီးသည် မို့ဆောင်ရေး

ရန်ကုန်ဂိတ်တည်နေရာ - အမှတ် (၁ / ၂၇) ကျိုက်လတ်လမ်း၊ လှိုင်သာယာ (ဒဂုံဧရာ) ။

အောင်-ကြံ့ခင်း-ဘက်ရဲ-ကွင်းကောက်-ပြည်-ဟင်္သာတ-ပုသိမ်-မကွေး-ရန်ကုန်

ဘက်ရဲ-ကြံ့ခင်း-မြန်အောင်-ဟင်္သာတ-ခနုဖြူ-မအူပင်-ကျိုက်လတ်-ဈာပုံ-ရန်ကုန်

ည့် အောင်ကျော်ဝင်းခရီးစဉ် ခနုဖြူ... ထိုင်ခုံအမှတ်... အလယ်... ၁... ရက်စွဲ ၄... ၁၁... ထွက်ချိန် ၁၁... ၃၆ သင့်ငွေ ၆၀၀၀

ရန်ကုန်ဂိတ် - 09-790711534, 09-683020730, 09-777984616, 09-777984168, 09-777983155,

မြန်အောင် ပင်မဂိတ် - 09-756553168, 09-682351770, 09-422523752, 09-785111300

ကြံ့ခင်းဂိတ်ဟောင်း - 09-798026130, 09-691634144 ကြံ့ခင်းဂိတ်သစ် - 09-766605310, 09-670710766

ဘက်ရဲဂိတ် - 09-422506633, 09-957775435, မဲဇလီကုန်း - 09-778837237, 09-779730641

ဟင်္သာတဂိတ် - 09-441455500, 09-255231255, ထူးကြီးဂိတ် - 09-777437156, 09-790225915

ဈာပုံဂိတ် - 09-766605838, 09-670732866

ပုသိမ်ဂိတ် - 09-422445854, 09-791393670

ပြည်ဂိတ် - 09-793511224, 09-452335934

မကွေးဂိတ် - 09-777785488, 09-794569488

မင်းဘူးဂိတ် - 09-796033128 ပဒေါင်းဂိတ် - 09-799927065

မှတ်ချက်။ ။ ယာဉ်မထွက်မီ မိနစ် (၃၀) ကြိုတင်အရောက်လာရမည်။ ဝယ်ပြီးလက်မှတ်ထုပြန်မအမ်းပါ။ လက်မှတ်ဝယ်ယူပါက သွားမည့်ရက်၊ အချိန်၊ ခရီးစဉ်အား သေချာစွာ စိစစ်ပြီးမှ ဝယ်ယူပါရန်။ တန်ဆာပေးဆောင်ခြင်း မရှိသော ကုန်ပစ္စည်းများ အတွက်၊ မိမိတာဝန်သာ ဖြစ်သည်။ တန်ဆာပေးဆောင်သော ပစ္စည်းပျောက်ဆုံးပါက တန်ဆာခမ်း (၁၀) ဆသာလေးလျော်မည်။

# အသင့်ဖြင့်ခရီးသည် ပို့ဆောင်ရေး

အောင်-ကြမ်း-အင်ပင်-ထူးကြီး-မဲလီကုန်း-အင်ပူ-မြို့ကွင်း-ဝတ္တိ-တလုထွေး-ဟင်္သာတ-လွန်း-ခနဲဖြူ-ရန်ကင်း(ဒဂုံရော)။

အောင်-ကြမ်း-ဘက်ရဲ-အုတ်ပုံ-မျှင်ပါးတောင်-ဘန်ဘွေးကုန်း-ကွင်းကောက်-ခြောက်ရွာ-မြို့ကွင်း-ဟင်္သာတ-ရန်ကင်း(ဒဂုံရော)။

အောင်-ကြမ်း-ဟင်္သာတ-ရန်ကင်း(ဒဂုံရော)-သထုံ-ဘားအံ-မြဝတီ-မော်လမြိုင်-မုဒုံ-သံဖြူရောင်-ရေး-ကျိုက်ခရိုင်-ကြမ်းကြီး

ယာဉ်အမှတ် ----- နေ့စွဲ ----- အမှတ်စဉ် **30.11.2024**  
 ပေးပို့သူအမည် ----- ဖုန်း ----- လိပ်စာ -----  
 လက်ခံမည့်သူအမည် ----- ဖုန်း ----- လိပ်စာ -----

No. စဉ်	Particulars အမျိုးအမည်	Quantity ဦးရေ	Unit Price နှုန်း	Amount သင့်ငွေ
1	ကိုရော့ကော့ကော့			၇၀၀၀
2				
3				
4				
5				
6				
7				
8				
9				
10				
11	Paid			
12				
13				
14				
15				
16				
17				
12	PTC - ATM			

Total Amount/ စုစုပေါင်း:

Advance/ စရံငွေ:

Balance/ လက်ကျန်ငွေ:

မှတ်ချက်။ ကျောဘက်ပါစည်းကမ်းချက်များကိုလက်ခံ  
 သဘောတူပါသဖြင့် အထက်ပါပစ္စည်းများကိုပေးပို့ပါသည်။  
 ပေးပို့သူအမည် -----  
 လက်မှတ် -----





# GENERAL EXPENSE CLAIM FORM



BU/BR/DIV Name :

Department Name :

No.	Date	PIC Name	Description	Category (Customer (Or) Operation)	Cost (MMK)	Remark
1	14.11.24	A Law Htet	labour charges	Cash	15000	
2	15.11.24	n	n	n	15000	
3	16.11.24	n	n	n	15000	
<b>Total General Expense</b>					<b>45000</b>	

Requested by

Approved by

Checked by

Approved by

Approved by

Sign :

Sign :

Sign :

Sign :

Sign :

Name :

Nyein Nyein

Name :

Name :

Name :

Name :

(Requester)

(Department Head)

(Finance & Account)

(OM/AGM/GM)

(ACOO/COO/MD/VCMD)

02-ATT-FNA-FRM-002-01

ကုန်စည်များ

၂၂ နေရာတွင် ကုန်စည်များ ကုန်စည်များ  
H.11.2024 မှ 16.11.2024 ကို  
၂၂၇၅၀၀၀ ကုန်စည်များ ကုန်စည်များ  
၂၂၅၀၀၀၀ ၊ ၂၂၇၅၀၀၀၀ ကုန်စည်များ  
၂၂၅၀၀၀၀ ၊ ကုန်စည်များ ကုန်စည်များ  
၂၂၅၀၀၀၀

U Zaw Htet  
09.779 526447,  
09.782 424 988

- 14.11.2024 - Right Axle Installation
- 15.11.2024 - PTO Abnormal sound
- 16.11.2024 - PTO Abnormal sound

FC

Date \_\_\_\_\_

Page \_\_\_\_\_

အကြောင်းအရာ။

။ နေ့စားတွေ ဂဏ်ခံတွေ ဂဏ်ခံပို့ပေး  
 14.11.2024 မှ 16.11.2024 အထိ  
 ၂၃၇ ရက်စာ ဂျာနယ်ရေးတာ တစ်ရက်ပျမ်း  
 (15000) ၊ ၂၃၇ ရက်စာ ဂျာနယ်ရေးတာ ဂျာ  
 (၂၅၀၀၀) ၊ ဂျာနယ်ရေးတာ ဂဏ်ခံပို့  
 ပေးခဲ့ပါ။

U Zaw Htet

09. 779 586447,

09. 782 4241982

Date And Time

8:00pm

Ar. Kheung Village

ing stocks,

mark

- 14.11.2024 - Right Axle Installation
- 15.11.2024 - PTO Abnormal sound
- 16.11.2024 - PTO Abnormal sound

FC

# TRAVELLING REPORT

Date : .....

Report To		
Employee Name		Aung Myaw Myint
Position		Section Head
Department		Production
Business		APP
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	4.11.2024, 10:30 am	30.11.2024, 8:00 pm
Total Days		
Trip Information	1. From Yangon.....To Dada Phay, Yawca Railway Village	
	2. From Dada Phay, Yawca Railway Village To Yangon.....	
	3. From .....To .....	
Purpose For Travelling		P70 abnormal, left & right rear axle, spinning shock, Rotator, hydraulic function abnormal
Travel Date	Activities	Remark
4.11.2024	- Go to Job site, Dada Phay Township, Yawca Railway Village	
5.11.2024	- M7804 Tractor inspected and tested run, found P70 abnormal sound at 540 rpm, Left & right Rear axle bearing abnormal, Hydraulic function abnormal.	
6.11.2024	- Removed Rotator, Drained hydraulic oil and transmission oil. And removed auxiliary valve & distributor with pipe. Removed control valve, and pipe, Lift housing cover lift housing bolt. And dismounted lift housing.	

Reported by

Checked by

Approved by

Sign :

Name : Aung Myaw Myint

Position : Section Head

Sign :

Name :

Position :

(DH/AGM/GM)

Sign :

Name :

Position :

(COO)

05-CHL-HRM-FRM-064-01

7.11.2024

- Found PTO bearing Damage, Gear Damage, Damage, PTO gear Drive shaft Damage. So to removed shaft for Reduction gear shaft. But cannot leave shaft because of shaft & bearing damage.

8.11.2024

- We decided to cut the shaft with grides so we requested grides from APB BU, we striked the shaft by 10lb hammer by removing seal and to lift housing & gearbox housing over. The gear shaft moved 3 inches so we can't need to cut with grides.

9.11.2024

- We cut the shaft with grides. And striked the shaft by axes placed, found bearing and shaft fitting. We replaced drive shaft, bearing, reduction gears and PTO output shaft bearing. And mounted the shaft but ~~disassemble~~ we need to removed axle because of Axle bearing need to replaced.

10.11.2024

- Removed left wheel bolt, wheel, axle stand, axle bolt, axle, And disassemble axle, axle shaft and bearing. Found bearing 6314, 52213. We strike 6314 bearing. but cannot leave. So we pressed with hydraulic jacks at Daddalaga.

11.11.2024

- We cleaned and assembled the left rear axle. And mounted the left rear axle. but rear axle need more strike because of 52213 bearing with load.

12.11.2024

- We mounted left axle, axle bolt and wheel. And installed other accessories. Left axle and wheel mounted. It was OK.

13.11.2024

- We Dismounted right wheel, bolt, wheel, axle stand, axle bolt and axle. And disassembled axle, axle shaft and bearing. We pressed with hydraulic jacks.

14.11.2024

- Cleaned and assembled right rear axle.

15.11.2024

- Mounted right axle & wheel and other accessories.

Staff



# TRAVELLING REPORT

Date : .....

Report To		
Employee Name	Aung Kyaw Myint	
Position	Section Head	
Department	Production	
Business	ATP	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	14.11.2024, 10:30am	30.11.2024, 8:00pm
Total Days		
Trip Information	1. From ...Yangon.....To Dadda Phya, Yasa Kalay...	
	2. From Dadda Phya, Yasa Kalay.....To Yangon.....	
	3. From .....To .....	
Purpose For Travelling	PTO abnormal, Left & right rear axle, wiring stuck, Rotavator, hydraulic function abnormal	
Travel Date	Activities	Remark
16.11.2024	We disassembled and cleaned Hydraulic control valve. And mounted lift housing, hydraulic control valve, oscillating valve and pipe. And filled hydraulic oil, gear oil.	
17.11.2024	We tested hydraulic function and PTO function. Hydraulic function OK. But PTO cannot work. Because of PTO coupling mixed with PTO shaft. So we need to installed PTO coupling	
18.11.2024.	We removed gearbox cover, PTO cover and lift housing. And its cover. Painted oil.	

Reported by  
 Sign :   
 Name : Aung Kyaw Myint  
 Position : Section Head

Checked by  
 Sign :  
 Name :  
 Position :

Approved by  
 Sign :  
 Name :  
 Position :

(DH/AGM/GM)

(COO)

05-CHL-HRM-FRM-064-01

- 19.11.2024 - We mounted PTO drive shaft, lift housing and lift housing cover. And installed other accessories. And filled transmission oil and hydraulic gear oil.
- 20.11.2024 - Tested run the hydraulic function, PTO gear box function on field.
- 21.11.2024 - Standby and wait the tractor by on field with load.
- 22.11.2024 - Wiring shock about key switch and start motor. We need to replaced motor and key switch.
- 23.11.2024 - We installed key switch and start motor. And installed front lamp.
- 24.11.2024 - Standby and tested run with load on field.
- 25.11.2024 - Rotavator drive gear damage. So we replaced rotavator drive gears and filled oil.
- 26.11.2024 - PTO clutch plate cannot work with load. So we adjusted clutch plate.
- 27.11.2024 - Hydraulic function cannot work because of this function caused sag slowly down when we tested. We removed control valve and disassemble and cleaned control valve. And installed its accessories.
- 28.11.2024 - Hydraulic function testing, but it was not ok. So we need to change hydraulic lift cylinders.
- 29.11.2024 - Hydraulic lift cylinder removed and replaced it. And tested run the tractor. It was good.
- 30.11.2024 - Rotavator blade oil seal damage so we replaced oil seal. And release of Yangon.

Print Date : 11-Dec-2024

Taxi (Bus,Motorcycle,3-wheel etc...) Charges Form

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	State	Remark
1	2024-11-04	Agriculture Tractor & Truck	Production	Aung Kyaw Myint(3)		14:30	ခန့်မြို့	ရှာကလေး	10,000	10,000	GA Manager Approved	Job Site ,ATT BU To Danu Phyu,MT804-4075, Customer -U Win Naing, Problem- PTO function abnormal, Rear axle abnormal (L,R)
2	2024-11-30	Agriculture Tractor & Truck	Production	Aung Kyaw Myint(3)		17:30	ရှာကလေး	ခန့်မြို့	10,000	10,000	GA Manager Approved	
3	2024-11-30	Agriculture Tractor & Truck	Production	Aung Kyaw Myint(3)		20:30	ဆုံစရာကလေးတိုက်	တို့ခါး	12,000	12,000	GA Manager Approved	

