



mandalaymyanmar.com.mm

From (မှ) Mandalay

To (သို့) Yangon

Traveler (ခရီးသည်) Nay Win Myint

Contact (စန့်ဆက်ဖော်) 09 64656535

Seat (ခရီးခုံ) 31

Class Type (နည်းစဉ်) (Business Class)
Ticket Reference (စီစဉ်စာရင်း) 5163-166

Bus No. (ဘတ်စ်ကားနံပါတ်) 1 E-15
Status (အခြေအနေ) CONFIRMED

Departure (ထွက်ခွာ) Oct 04, 7:30 AM

Gate (ဂိတ်) Chan Mya Si we Pyi Bus Terminal

Special Request (အထူးတောင်းဆိုချက်)

Printed Time : Oct 04, 7:16 AM

Passengers Total

31,000

NOTE: Passport is necessary to travel
ခရီးထွက်ခွာရန် ပို့ဆောင်ခွင့် ပြုစုရမည်

check in 30 min before the departure time.
ထွက်ခွာရန် 30 မိနစ် အတိုင်း အစီအစဉ်ပြုစုရန် လိုအပ်ပါသည်။

Each passenger is allowed one carry on luggage.
တစ်ဦးချင်းစီ ခရီးထွက်ခွာရန် အတိုင်း အစီအစဉ်ပြုစုရန် လိုအပ်ပါသည်။

No refund will be issued after the departure.
ထွက်ခွာရန် အပြီးပြုစုပြီးနောက် အစီအစဉ်ပြုစုရန် လိုအပ်ပါသည်။

ထွက်ခွာရန် အစီအစဉ်ပြုစုရန် အတိုင်း အစီအစဉ်ပြုစုရန် လိုအပ်ပါသည်။
ထွက်ခွာရန် အစီအစဉ်ပြုစုရန် အတိုင်း အစီအစဉ်ပြုစုရန် လိုအပ်ပါသည်။

Contact Phone : CallCenter 09772 810
998, YGN 0950201821, 1st Flr 0951251277, Mekkha 01 788
885557, MDY 09702651511, Madan 094 9291900, PCC 09
Pakkeku 09 7733 45 666, Myingyan 09 771 9680
78, Nagway 09 2510 83 930, Tatkone 094480 12 560

My



No.589-592,Bo Aung Kyaw Street,Yangon-Pathein High Way Road,Hlaing Thar Yar Township, Yangon, Myanmar.

Print Date : 11-Oct-2024

Taxi (Bus, Motorcycle, 3-wheel etc...) Charges Form

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	State	Remark
1	2024-10-04	Renewable Energy	Service	Nay Win Myint(2)	Come back HO YGN	06:00	MDY BR	Mandalay Highway	10,000	10,000	GA Manager Approved	Inspection & installation in MDY
2	2024-10-04	Renewable Energy	Service	Nay Win Myint(2)	Come back HO YGN	17:45	Aungmyingalar highway	Ahlon	20,000	20,000	GA Manager Approved	Inspection & installation in MDY



TRAVELLING REPORT


Date : 2.10.24

Report To	Aung Ko Ko Oo	
Employee Name	Aby Win Myant	
Position	Mechanic Helper	
Department	Service	
Business	RE BU	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	(30.8.24) 1.10.24	4.10.24
Total Days		
Trip Information	1. From MDY To YGO	
	2. From To	
	3. From To	
Purpose For Travelling	Installation & Inspection.	
Travel Date	Activities	Remark
1.10.24.	Check MDY Branch / Stock.	
2.10.24	Went to Daw B. E. Mon 18kw Solar System site for check w/ifi error. It repair w/ifi reconfiguration. It was ok.	
3.10.24.	Went to Kyaukse Kay Thida 12kw Solar system for Inspection Battery charge Firmware upgrade.	
4.10.24	Come Back Yangon HO. Because a lot of job in HO & PIC are not have.	


Reported by

Checked by

Approved by

Sign : 
 Name : Aby Win Myant
 Position : Mechanic Helper

Sign : 
 Name : Aung Ko Ko Oo
 Position : ADH

Sign : 
 Name : U Aye Mon Htoon
 Position :

(DH/AGM/GM)

(COO)

05-CHL-HRM-FRM-064-01