





- Physical Photo of Evidence
 - Service job report completed


DIESEL PURCHASE REQUEST FORM


Date : 29.3.25


No.	BU/DIV	Description	Qty	Measure	Remark
1.	CE3 BU	Diesel	2	Drum	For Pre-delivery Inspection, Stock Maintenance And Repossess Inspection & Repair For Ready To Sale.

Requested By
 Sign : 
 Name : Thiri Mon
 Position : Admin


Checked By
 Sign : 
 Name : Ye Min Kyaw
 Position : DH


Acknowledged By
 Sign : 
 Name : Zayon Aung
 Position : GM/AGM


Approved By
 Sign : 
 Name : Aye Min Htoon
 Position : COO

CFD
Checked By
 Sign : 
 Name : Zin Mar Thawng

CAM
Checked By
 Sign : 
 Name : Myat Thee Zau

IA
Checked By
 Sign : 
 Name : Min Zau

IA
Approved By
 Sign : 
 Name : Aye Min Htoon

CAM
Acknowledged By
 Sign : 
 Name : Aye Min Htoon

Checked By
 Min Nu Shwe
 CE3 FBA

* Diesel usage balance sheet form of confirmed by: of service job report and management sign
 * PDI usage report of confirmed by: of service job report and management sign
 * Service job report of start hr & end hr, Diesel usage liter per hr, confirmed by physical photo evidence of date of job

05-CHL-GAV-FRM-016-01