

**CONSTRUCTION EQUIPMENT 1  
Good Receipt**

Customer Name :  
Address :  
Phone :

GR No : CE1-GR-25030018  
GR Date : 2025-03-19 15:20:01  
Related No :

No	Description	Part Number	From Location	To Location	Qty	UOM	
1	Sensor,Expansion Tank	21271982-E	Office Use	CEQ_Parts	1.00	PC	31.50\$
2	Filler Cap, Expansion Tank	3979593-E	Office Use	CEQ_Parts	1.00	PC	20.41\$
3	Pressure Cap, Expansion Tank	1674083-E	Office Use	CEQ_Parts	1.00	PC	21.32\$


**Note** : We will separate Good Receipt & Sell because 17411510 Expansion Tank from Damage part EC210BP.We've receive from the Cap, Filter Cap and Sensor will be replaced.

Prepared By



Related By


Approved By

  
 BU DH

Validated By

HO WHS/BU WHS

# Damage Photo for CE1 Parts

No	Product Code	Trim	Product Name	Qty	Pprice	Total	Photo	Remark
1	17411510	17411510	Expension Tank, Cooling System	1	140.63	140.63		အဖုံးနားမှ ပဲ့နေသောကြောင့် Damage ပြုလုပ်ပါသည်။ Coolant Level Sensor ကိုတော့ အဝင်ပြန်သွင်းပါမည်။ နည်းကိုက်ဆင်သွင်းပါ မည်။

Prepared By  
S'part Admin  
Zaw Myo

Checked By  
S'part DH  
Aye Theingi Myint

Anknowledge By  
F&A Head  
Moh Moh Khaing

Anknowledge By  
GM/OM  
Min Thu Ya

Approved By  
GM(After Sale Division)  
Aung Hein Win

Approved By  
COO(After Sale Division)  
Aye Min Htoon


- စာရင်းပုံစံ sensor

[Products](#)
[Parts](#)
[Service](#)
[Diagnostics](#)
[Reman parts](#)
[Standard parts](#)
[Basic Facts](#)
[New order 1](#)
[Add to order](#)
[Machine card](#)
[Show in Parts](#)
[Assembly instructions](#)
[OEM recipes](#)

SN: 
[Part catalog](#)
[General Foreword](#)
[Order window](#)
[Machine card](#)
[Hose recipes](#)
[Mail](#)
[Hose Recipes](#)

Excavators  
 EC2108 LC Volvo

- 20460 EC2108 LC Volvo
- Tree search:
- GENERAL
  - ENGINE WITH MOUNTING AN
  - ENGINE
  - LUBRICATING SYSTEM
  - FUEL SYSTEM
  - INLET SYSTEM: EXHAUST
  - COOLING SYSTEM
  - 261/100 Cooling system E
  - 261/110 Cooling system E
  - 261/300 Radiator 828612
  - 261/320 Radiator 828698
  - 262/100 Water pump and
  - 263/100 Belt transmission
  - 263/300 Cooling fan mou
  - SYSTEM: WARNING SYS
  - VER TRANSMISSION



Part	Descriptions	Q1	Q2	Q3	Q4	Q5	PS	Kit	STD	Option(s)	Remark
1	VOE17411510 Expansion tank	1									
	VOE17411509 -Expansion tank	1									CS
2	VOE21271982 -Sensor	1	✓								
3	VOE3979593 -Filler cap	1	✓								SE2603 COOLANT LEVEL
4	VOE1674083 -Cap	1	✓								

dle | User: MA75674 | English

[Search](#)
[Home](#)
[Print](#)
[Zoom](#)

UMG LOGISTICS  
No. 588,592, Boangkyaw street,  
Yangon-Patethi Night way road, Hialng Thar Yar  
Tsp.  
Myanmar

Responsible : Win Toe

Numbers : CE1-GIA-25030049

Documents : 2025-03-19 08:15:59

No	Product Code	Product Name	Qty	Source Location	To Location
1	17411510 ✓	Expension Tank, Cooling System	1.0000 PC ✓	WH03/Stock/A-2/3.2	Office Use

Notes :


We need to make good issue for this part to make scrap. We've receive from the Cap, Filter Cap and Sensor will be replaced. Already approve from management.

Prepared by

Zaw Myo

BU PIC (Name)

Validated by



WHS PIC (Name)

Win Toe  
19.3.2025

Delivery by



WHS PIC

Win Toe  
19.3.25


Received by



Receiver

Zaw Myo  
(19.03.2025)


Prepared By  


Check By  


Acknowledged By  


Received By

Date: 21.3.2025 To Zone 5



Prepared By  
*[Signature]*

Damage Part ⇒ 1 Pc  
Check By *[Signature]*

Acknowledged By  
*[Signature]*

Received