







TRAVEL ADVANCE CLEAR FORM

Cash Advance				
Employee Name	Pyaw (Phyo) Soe		Estimated Date of Travel	8.1.25 to 12.1.25
Position Rank	STDP, STDP		Total Day	10 days
BU/BR/DIV, Dept	RE Service		Destination	
Purpose	To install 10kw Solar System in Mudo			
Travelling Permit				
Arrival Place	- MLM - Mudo			
Actual Date & Time of Travel	8.1.25 to 12.1.25			
Total Day	10 days ✓			
HR Name	Khanzer Wyo			
HR Sign	Telegram Approved			
BOH/Authorized Person Name	Myo Hbke Aung			
BOH/Authorized Person	Telegram Approved			
Advance Clear				
Actual Date & Time of Travel	8.1.25 to 12.1.25		Total Day	10 days
Departure Date & Time	8.1.25		Arrival Date & Time	12.1.25
Date	Description	Total Amount		
		Kyats	USD	
8.1.25 to 12.1.25	TCharges (10 x 80,000) For 2 Person KOS, APT	800,000		
Total Expense (Kyats/USD)		800,000		
Cash Advance (Kyats/USD)		500,000		
Balance Refund/Additional (Kyats/USD)		300,000		
Job Report Status				
Authorization	Name	Position	Date	Sign
Prepared By	E. Thwe Phyo	Admin	20.1.25	Thwe
Approved By Dept Head	Aung Ko Ko	ADH	3.2.25	A.K.
Approved By GM/AGM/COO	Phyo Thu	AGM	5.2.25	Telegram Approved.
Acknowledged by related Superior for Job Report	Aung Hein Win	GM	5.2.25	
HR Check & Approved	Aye'n E'e Khin	HR.	5.2.25	
Cash Received				
Remark				

04-CFD-CAS-FRM-006-02

- STDP service lead time for 10 kVA 5 to 7 days.
- Actual 5 days + traveling, 3 days + other job (MLM) 2 days.
- ∴ Proper lead time. ✗ (pass)





TRAVELLING REPORT

Date: 5.1.25

Report To	Aung Ro Ro Co	
Employer Name	Ryau Aung Soc, Aung Phye Co	
Position	STDP	
Department	Service	
Business	EE	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	8.1.25 10:00	12.1.25
Total Days	1 day	
Trip Information	1. From VGO To Bagan	
	2. From MLM - Mudo To MLM	
	3. From Bagan To VGO	
Purpose For Travelling	To install 10 KW solar system, extension battery & inspection.	
Travel Date	Activities	Remark
	The daily reports attached by below.	

Reported by

Sign :
Name : Ryau Aung Soc.
Position : STDP

Checked by

Sign :
Name : Aung Ro Ro Co
Position : GM

(DH/AGM/GM)

Approved by

Sign :
Name : U Aye Mon Htoon.
Position :

(COO)

5/2/25

05-CHL-HRM-FRM-064-01

	Date	Status	Job Types/Number
1	3.1.25	Attend	Went to Bilin from Yangon Beilin Customer U Danu Site The wall is not finished yet. Battery installation has not been done. Only the rack has been installed.
2	4.1.25	Holiday	Today at Bilin customer U DaNu (Thoo Ka Paw Motel) site , Set up additional HV battery system. Then adjust the setting in the battery control box and test it works normal. Made Charging the only additional battery to equal the first one with solar. After fully charge , the two batterie's control box is normal and it is ok. Then testing loads with solar and battery. It is ok. Finally , explained to the customer how to use the system and wrote service report. Then we finished the job.
3	5.1.25	Holiday	Went to MLM Branch from Bilin Branch. And then went to Mudon. -Bought the needed accessories for Installation.
4	6.1.25	Attend	Bought the needed accessories for 10kW solar system at Mudon. Set up inverter(10kW off Grid), Battery-2units (51.2V 280Ah), AC/DC breaker boxes.
5	7.1.25	Attend	Installed L feet and solar rails for 16units of solar panels. Set up the solar cable for Solar 2 string.
6	8.1.25	Attend	Installed 16units of solar panels on the roof top at Mudon Monastery. Installed the earthing system.
7	9.1.25	Attend	Tested load with solar and battery at Mudon monastery. Came back to MLM Branch from Mudon. 9.1.2025. Take the 2units of battery (300Ah) from the high way bus station to Branch.
8	10.1.25	Attend	Did Morning exercise at Mawlamyine branch. Went to U Aung Thein (cold storage) site , replaced new 300Ah battery @2units and made charging with solar and Epc to equalize the battery SOC% .It's not all finished yet.
9	11.1.25	Attend	Did Morning exercise at Mawlamyine branch. Went to customer U Aung Thein (Cold storage) site , monitor the battery input and output balance. It is convenient to charge the battery with EpC & solar without using a load. There is a slight gap between the input and output of the new 2 batteries and the old ones. A few hours later, the input and output of the 2 new ones are also the same as the old ones.
10	12.1.25	Holiday	Came back to Bilin from MLM Branch. Replaced the bms communication cable at Htoo Ka Paw Motel(U Da Nu -Bilin). Came back to Ygn from the Bilin.


PM

98



Ko Phyo Thu (GM)

last seen recently



ကိုကြီးရှင့်။ Kyaw Naing Soe, Aung Phyo Thu သွားခဲ့တဲ့ U Danu battery 8kW extension, Ashin Thaw Par Ka 10kW Solar system installation and U Aung Thein battery troubleshooting TA Charges clear form မှာ ကိုကြီး approved လေးလိုချင်လို့ပါရှင့်ကိုကြီး။

2:40 PM ✓



TA_Charges_for_Ashin_Thaw_Par_Ka_10kW_S...

2.3 MB PDF

2:40 PM ✓



Ei Thwe Phyo

ကိုကြီးရှင့်။ Kyaw Naing Soe, Aung Phyo...

Okay

2:41 PM



Message

