




### TRAVEL ADVANCE CLEAR FORM

Cash Advance				
Employee Name	Nay Hlon Win	Estimated Date of Travel	25.12.24 7:00am to 1.1.25 7:00am	
Position Rank	SHO	Total Day	7 x 1/2	
BU/BR/DIV, Dept	MS BU	Destination	MS BU to Myanmar - U	
Purpose	Of 75-44123, Customer Service in and oil leakage, wash & seal, engine repair contract.			
Travelling Permit				
Arrival Place				
Actual Date & Time of Travel				
Total Day				
HR Name				
HR Sign	[Signature]			
BOH/Authorized Person Name				
BOH/Authorized Person	[Signature]			
Advance Clear				
Actual Date & Time of Travel		Total Day		
Departure Date & Time		Arrival Date & Time		
Date	Description	Total Amount		
		Kyats	USD	
25.12.24 7:00am to 1.1.25 7:00am	Nay Hlon Win (7 x 15000) + 7500	112500		
	Express charges	5900		
	Taxes charges	50000		
	misc	5000		
<b>Total Expense (Kyats/USD)</b>		<b>226500</b>		
<b>Cash Advance (Kyats/USD)</b>		<b>200,000</b>		
<b>Balance Refund/Additional (Kyats/USD)</b>		<b>26500</b>		
Job Report Status				
Authorization	Name	Position	Date	Sign
Prepared By	Nay Hlon Win	Staff	20.1.25	[Signature]
Approved By Dept Head	Ho Myint Moe Aung	DI		
Approved By GM/AGM/COO	Ho Maeng Maeng	GM		
Acknowledged by related Superior for Job Report				
HR Check & Approved				
Cash Received				
Remark				

19148

# ပရိယတ္န

## အဆင့်မြင့်ခရီးသည်ပို့ဆောင်ရေး



ရန်ကုန် ↔ မိတ္ထီလာ ↔ ဝမ်းတွင်း ↔ ကုမဲ ↔ ကျောက်ဆည် ↔ မန္တလေး

အမည် (Name)

*Nay Tun Win.*

ရက်စွဲ (Date)

*31. 12. 24*

သင့်ငွေ (Amount)

*30000/-*

ယာဉ်ထွက်ချိန် (Time)

*6:30 PM.*

ခုံနံပါတ် (Seat No.)

*14*

ခရီးစဉ် (Travel)

*Yangon.*

▶ ယာဉ်မထွက်မီနစ် (၃၀) ကြို တင်အရောက်လာရမည်။ ▶ ဝယ်ပြီးလက်မှတ်ငွေပြန်မအမ်းပါ။ ▶ ယာဉ်ပေါ်တွင် မူးယစ်သောက်စားခြင်းမပြုရပါ။

From (မှ)  
Yangon

To (သို့)  
Meiktila

09-43187538

Traveller (ခရီးသည်)  
YGN to MTL

Contact (ဖုန်းနံပါတ်)  
09442977521

၂၄

Seat(s) (ခုံနံပါတ်များ)  
27

IM-1863

Class/Type

Bus No.(ကားနံပါတ်)

ရိုးရိုး - Scania

သင့်ငွေ

၅၀၀၀

Booking Reference  
2504-8602

Status  
CONFIRMED

Departure (ထွက်ခွာ)  
Dec 25, 8:00 AM

Gate (ဝိတ်)  
Aung Mingalar Bus  
Terminal

Special Request (မှတ်ချက်)  
Job

Printed Time :Dec 25, 7:09 AM

Passengers  
Total

1  
29,000

NRC or Passport is necessary to travel  
\*မှတ်ပုံတင် ဝါမှ စီးနင်းပွင့် ပြုပါမည်\*

Check-in 30 min before the departure time.  
ကားမထွက်မီ မိနစ် 30 ငြိတင်ရောက်ရှိရန် လိုအပ်ပါသည်။

Each passenger is allowed one carry-on luggage.  
ခရီးသည်တစ်ဦး တစ်ဆူအိတ်တစ်ခုအခမဲ့ယူခွင့်ရှိပါသည်။

No refund will be issued after the departure.  
ကားထွက်ချိန်မှစပြီး ရောက်ရှိလာသောအခါ မလှမ်းပါ။

ဝတ်ပြုလက်မှတ်ဖြန့်ဖြူး မခံနိုင်ပါ။ မိမိနှင့် အတူပါလာသော ဗွေ  
ညွှန်းများ မိမိနှင့် တပ်တည်း တားရှိပါ။ ရောက်ချိန်တွင် တာဝန်ပေး  
ယပါ။

Contact Phone. CallCenter-09772 889  
998, YGN-095020181, NPT-09251251277, Meiktila-09788  
885587.MDY-09402651991, Eagan-09429291000, POL-09  
Pakkoku-09 7733 45 666, Myingyan-09 771 9680  
78, Magway-09 2560 83 936, Tatkone-094480 12 556

စုစုပေါင်း	၅၀၀၀
ခရီးငွေ	
ကျန်ငွေ	





No.589-592,Bo Aung Kyaw Street,Yangon-Pathein High Way Road,Hlaing Thar Yar Township, Yangon, Myanmar.

Print Date : 06-Jan-2025


Taxi (Bus,Motorcycle,3-wheel etc...) Charges Form

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	State	Remark
1	2024-12-25	Agriculture Tractor & Truck	Service	Nay Htun Win	ATT BU To Meikhtila Job site.	07:00	တိုင်း ဘု	ပေးအပ်	25,000	25,000	GA Manager Approved	
2	2025-01-01	Agriculture Tractor & Truck	Service	Nay Htun Win	Meikhtila To ATT BU	07:00	ပေးအပ်	တိုင်း ဘု	25,000	25,000	GA Manager Approved	

# TRAVELLING REPORT

Date : .....

Report To	COO	
Employee Name	Nay Htan Win	
Position	SH	
Department	Service	
Business	ATT-BU	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	25.12.24 8:30 am	11.25 8:00am
Total Days		
Trip Information	1. From ATT-BU (YGN) To MTL Branch	
	2. From ..... To .....	
	3. From ..... To .....	
Purpose For Travelling	Hydraulic oil leakage from Four wheel shaft seal.	
Travel Date	Activities	Remark
25.12.24	Going to Job site from ATTBU (YGN)	
26.12.24	Our service team go to job site. And then, firstly visual checked and all oil level check. we test run the machine, we found the oil leakage from four wheel shaft seal and Gear fork shaft seal.	
27.12.24	Our service team firstly visual check and	

**Reported by**  
 Sign :   
 Name : Nay Htan Win  
 Position : SH

**Checked by**  
 Sign :  
 Name :  
 Position :

**Approved by**  
 Sign :  
 Name :  
 Position :

(DH/AGM/GM)

(COO)

# TRAVELLING REPORT

drained the hydraulic oil (10W80)  
And then, we dismounted the Four wheel  
shaft seal and Gear Fork shaft seal.  
We replace the new one Gear Fork  
shaft seal and Four wheel shaft  
seal. And then, we fill the hydraulic  
oil and test run the machine with  
load about 8 hour. It's OK.

28.12.24, monitoring

29.12.24. we cleaning the Fuel tank and Fuel  
line. Test run the machine. It's OK.

30.12.24 monitoring

31.12.24 Go back from Job site to YGN CATT-BU

\* AS. 10R | 24 | 12 | 1255

\* AS. 10R | 24 | 12 | 1256

\* AS. 10R | 25 | 01 | 0006



Ko Aye Min Htoon

last seen recently



December 19

Hi ဆရာ

Field Job Advance

Customer=Daw Tin Tin Sint

Model=DF75

S/N=44123

W/NW=Warranty

Problem=Oil leakage from 4WD shaft, Gear Fork, Engine hunting,

Safety function

Location=Meikhtilar

Assign=Nay Tun Win

Estimate Day=7 Day

(23.12.24 to 29.12.24)

Field Job Advance=200000/- ခန့် ထုတ် ယူ ခွင့်ပြုပါ ဆရာ

MTL service က ရှေ့ထိန်းထားတဲ့ စက် တစ်စီး ကို Contract နဲ့ ပြင်နေ လို့ မအား လို့ ပါ

Warranty စက် ဆို တော့ ပြင်ပီးရင် စောင့် ကြည့် ဖို့ လဲ ရှိနေ လို့ပါ BU ကပဲ တိုက်ရိုက် သွား မလို့ပါ ဆရာ

2:27 PM ✓✓

December 20

Aung Kyaw Thu

Hi ဆရာ Field Job Advance Customer=Daw...

Please proceed to go to MHL by advance MMK 200,000.

8:20 AM



Message

