



No. 589-592, New Tha Ka Ta (1), Bo Aung Kyaw Street,
Hlaing Thar Yar Township, Yangon, Myanmar.

Print Date : 23-Oct-2024

Vehicle Repair Information Listing

No.	Vehicle No	Repair Date	Referenced Code	Responsible Person	Repair Information	Advance					Actual Repaired Information		Actual					
						Amount	Status	Acknowledge By	Approve By	Voucher No.	Cash Down	Credit	Amount	Status	Acknowledge By	Approve By	Voucher No.	
1	4D/8341 Hatch Back (4x2)(R)	08-Oct-2024	MCS/R/14885	Seint Seint Thu	Car under check , inner check , outer check , break check, Hardcot check,hard ball check , car shockbar check and car the whole materials patrs checking	0	✓					Car under check , inner check , outer check , break check, Hardcot check,hard ball check , car shockbar check and car the whole materials patrs checking Ko Htay Workshop No(363) Tabinshwehtee Road, 1 Htake bustop nerar Ph/09-975111400	50,000	✓				

Aung Thiha Myo
(GIA)

Swe Swe Win
(HR/DH)

Seint Seint Thu
(AGM)

အခွဲနှင့် ညီမျှား



ကားပစ်ရှော့၊ ကားအောက်ပိုင်း၊ ကားဆေးမှုတ် နှင့် ကားဘော်ဒီအလုပ်ရုံ

အမှတ် (၃၆၃)၊ တပင်ရွှေထီးလမ်း၊ (၁)ထိပ်မှတ်တိုင်အနီး၊ လှိုင်သာယာ။

Ph: 09 - 975111400, 09-261660757, 09-73100223

အမည် ၄.၀ - ၈၈၄၁ နေ့စွဲ ၈.၁၀.၂၄

နေရပ်

စဉ်	အမျိုးအမည်	ဦးရေ	နှုန်း	သင့်ငွေ
1	ရွှေရောင် ဒေကန်ဖွင့် - ဖက်ဖက်			
2	မြောက်ကန် စစ်ဆေး			50000
3	အရှင်စစ်ဆေး			2
4	ဧည့် အရှင်စစ်ဆေး			
5	ဟောင်းကော စစ်ဆေး			
6	ရောင် အရှင်စစ်ဆေး			
7	ဟောင်းကော စစ်ဆေး			
8				
9				
10				
11				
12				

Pa'd
Aung
8.10.24

လက်မှတ် *Aung*

3062

စုစုပေါင်းသင့်ငွေ -	50000
စရံငွေ -	
ကျန်ငွေ -	

Aung Thika myo CGA staff