

ခေါင်းယာဉ်ပုံ


စက်ကရိယာ နှင့် တာဘိုပြုပြင်ရောင်းဝယ်ရေး

အမှတ်(၂၈) စလင်းလမ်း၊ ကြည့်မြင်တိုင်၊ ရန်ကုန်မြို့။

ဆွီဒစ် မဂ်

၀၉-၄၄၃၁၃၆၅၇၆
 ၀၉-၂၅၀၆၇၁၅၆၈

အမည် U.M.G ----- အပ်သည့်နေ့စွဲ -----
 နေရပ် ----- ရမည့်နေ့စွဲ 29.6.2024 -----

အမှတ်စဉ်	အကြောင်းအရာ	သင့်ငွေ-ကျပ်	အပ်ထားသည့်ပစ္စည်းများ သို့မဟုတ် မှတ်ချက်
	Volvo 1641 Turbo repair skat set and Ex Turbine wheel. Replasing Charger. Customer - Ocean Blue Model - TFD1641GE SR. no - 2016105013	2,500,000  2,500,000	

အပ်ထည့်ပစ္စည်းများကို(၃)လကျော်လွန်ပါက တာဝန်ယူလိမ့်မည်မဟုတ်ပါ။

အလုပ်အပ်သူ -----

အလုပ်လက်ခံသူ -----

Date-20.8.2024

အကြောင်းအရာ။ ။Turbo repairing အတွက်ပြုပြင်ငွေပေးခြင်း။

Customer -Ocean Blue

Model-TAD1641GE

Series.no-2016105013

အထက်ပါစက် turbo repairing အတွက် ကျွန်တော်များ Winning Way Co.,Ltd မှ customer ထံသို့ငွေ စက်turbo ပြုပြင်ခ 2500000ks တိတိကို customer ဆီသို့ပေးခဲ့ပါသည်။



(လက်ခံရရှိသူလက်မှတ်)

အမည်- မမိစောမွန် .

ဖုန်းနံပါတ်- ၀၇-၇၈၄၈၃၅၃၅၆ .



(တာဝန်ခံလက်မှတ်)

အမည်- ဇာနည်မြိုင်

ဖုန်းနံပါတ်-၀၇-၇၇၇၈၃၅၂၆၆

To Manager
 Done
 Create New

Move
 Rules
 OneNote

Unread/Read
 Categorize
 Follow Up

Address Book
 Filter Email

Send/Receive All Folders
 Send/Receive

Steps Move Tags Find Send/Receive

Reply
 Reply All
 Forward



Fri 8/2/2024 2:58 PM

Chua Eric <eric.chua@volvo.com>

RE: Ocean blue air filter crack warranty claim

To: Min Khant Kyaw

Cc: tint.naing@umgroups.com; 'mimi.ko1'; soehtet.tin@umgroups.com; 'Chit Pon Su'; Tan Agnes; Onn Mazlan

Hi Kyaw,

As mentioned in Argus I already approved for the air filter and turbo claim. For the repair works of the turb do add it in due to no stock and urgency for it to be in operational.

But do note that any failure of the repair turbo and lead to other component damage will not be cover by Volvo warranty, this will be bear by Wining Way.

Come back with a revise draft UCHP total cost for my pre-approval, if not this claim will not be approve till I agreed the said amount.

Regards,
Eric

From: Min Khant Kyaw <minkhant.kyaw5@umgroups.com>

Sent: Friday, August 2, 2024 4:23 PM

To: Chua Eric <eric.chua@volvo.com>; Tan Agnes <agnes.tan@volvo.com>; Onn Mazlan

Chua Eric RE: Ocean blue air filter crack warranty claim



Claim job

Save claim job Release claim job Delete claim job <Select> New claim job

Information

Status Ready for crediting **Parts delivery date** 26/04/2024 **Follow up code** 147 **Force claim job**
Claim job type Parts **Parts operating hours** 84 Approval required by B4 MU SM/AM...
Scenario code 04 | Parts **Part age** 2 **Case source** A - Argus case
Case no. 1-18206351061

Main operation	Causal part	Func. group	New part
2550-03-00-05 Turbo charger - replace	21702911 AIR FILTER INSERT	2562	3837221 TURBOCHARGER

Summary	Net(EUR)	Hours	Approved	Rejected	Rejected code	Description
Labour	17.00	1.7	17.00	0.00		
Material	2 807.72		2 807.72	0.00		
Travel expenses	79.50		79.50	0.00		
Other costs	0.00		0.00	0.00		
Grand total	2 904.22		2 904.22	0.00		

Note to business partner

Any Argus case ?
 Please update case.
 Please input Argus number in the claim.

Claim job

Save claim job Release claim job Delete claim job <Select> New claim job

Header 1

Repair header information

Warranty district	1062	Repair order no.	
Business partner	525211	Repair date	17/06/2024
Reference no.	112	Registration date	24/06/2024
Type of concern	Warranty		

Claim job information Labour Material Travel expenses Other costs Remarks Attachment History

Information

Status	Ready for crediting	Parts delivery date	26/04/2024	Follow up code	147	Force claim job	<input type="checkbox"/>
Claim job type	Parts	Parts operating hours	84	Approval required by B4 MU SM/AM...			
Scenario code	04 Parts	Part age	2	Case source	A - Argus case		
				Case no.	1-18206351061		

Main operation	Causal part	Func. group	New part
2550-03-00-05 Turbo charger - replace	21702911 AIR FILTER INSERT	2562	3837221 TURBOCHARGER

Summary	Net(EUR)	Hours	Approved	Rejected	Rejected code	Description
Labour	17.00	1.7	17.00	0.00		
Material	2 807.72		2 807.72	0.00		