



# PARTS REMOVING REQUEST FORM



Requested Date	24.2.25	Part Take Out Date	24.2.25
Requested By	Sandi Aung	PIC To Take Out The Parts	Kaung Htet Lwin
Requested Branch	MDY BR	Service Person	Kaung Htet Lwin
Reason of Request	customer urgent		

**From**

Customer Name	ko naing	Component Name	sete ECU
Machine Model	Selena	Component Part No.	39100 - AFAM - 9100
Machine Serial No.	RL9S1P52AMT-6000025	Component Serial No.	39100 - AFAM - 9100

**For**

Customer Name	ko naing	Component Name	ECU
Machine Model	Selena	Component Part No.	39100 - AFAM - 9100
Machine Serial No.	1	Component Serial No.	39100 - AFAM - 9100
Warranty Part No.		Warranty Part Serial No.	

No.	Part Description	Part No.	Qty	Remark
1.	ECU	39100-AFAM-9100	1pc	only ECU

Plan To Return Back The Parts	we will return aftershipment.
-------------------------------	-------------------------------

Part Return Date		Return Part installation Date	
Employee Name		Return Part installation PIC	

Status of part installation after return :
--

Requested By		Acknowledged By		Approved By		Acknowledged By		Received By	
OUT	IN	OUT	IN	OUT	IN	OUT	IN	OUT	IN
Sandi		M...		24.2.25		Sandi		Sandi	

Name : Sandi Aung      Name : M...      Name : Phyo Koko      Name : Chit Senko      Name : Sandi Aung  
 Designation : s'part Admin      Designation : DH.      Designation :      Designation :      Designation :

02-BMC-SLS-FRM-012-00



# SERVICE REPORT



Job Order No MC-YGANI-JR-2502096  
 Customer Name UMG Motors  
 Machine Location UD  
 Machine Model Sdena  
 Machine Sr.No RL991GJJJBKA800025  
 Engine Sr.No VZ91P52QMJ-G1000025  
 Houe Meter or) Km 2km  
 Job Site Distance .....

	Date	Time
Customer Call Date		
Confirm with Customer		
Go to Job Site Time		
Arrival Job Site Time		
Job Start Time	24.2.2025	8:30 AM
Job Finish Time	24.2.2025	9:00 AM
Go Back from Site		
Arrival Office Time		
Job Delay Date&Time		
Reason of Job Delay		

Customer Call Problem

Disassembly

Cause of Problem

Disassembly

Service Action

- checked current condition of vehicle (electrical system, ~~FF~~ sensors)
- removed the ECU.
- other parts are complete.
- job was finished.

Failure Causal Part

No	Part Description	Part No	Qty	Remark

Service Charges

Customer Sign .....

Service Person Sign

Customer Name .....

Service Person Name KHL

Checked By

Acknowledge By

Approved By

Name: KHL

Name: Paw Ekay Wah

Name:

Sign:

Sign:

Sign:

Service Man

Service SH

Service DH

02-BMC-ASD-FRM-004-01