

Print Date : 21-Oct-2024

Vehicle Repair Information Listing

No.	Vehicle No	Repair Date	Referenced Code	Responsible Person	Repair Information	Advance			Voucher No.	Actual Repaired Information	Credit	Actual		
						Amount	Status	Approval				Amount	Status	Approval
1	2U/3938 VAN(4x2) (R)	23-Aug-2024	MCS/R/146 92	Kaung Myat Thu (10)	Car door repairing & painting & car seat cover & car front bumper & other accessories rust place	200,000	✓					150,000	✓	

S. Chit Pon Su

S. Chit Pon Su

Sae Lae Nandar-Tam.

Phyo Win Nyein

Phyo

Phyo

No. 589-592, New Tha Ka Ta (1), Bo Aung Kyaw Street,
Hlaing Thar Yar Township, Yangon, Myanmar.





No.589-592,Bo Aung Kyaw Street,Yangon-Pathwin High Way Road,Hlaing Thar Yar Township, Yangon, Myanmar

Print Date : 06-Sep-2024

Repair Advance

Vehicle No	Car Type	Holding Business	Department	Request Date	Car User Name	Workshop Name	In Charge Person	BTH allow /Not allow	Repair condition and Quotation	Status	Advance Repair Chgs	Remarks
21/3938	Van(4x2)	Power Generator	Technical Support	2024-08-23	Saw Pyae Oo	Ko Zaw Min(UD)	Saw Pyae Oo	Allow	ကားရဘန်ကားသံချေးကိတ် ဖြည့်ပုံ၊ ကားတံခါးသံချေး ခုတ် ပြုပြင်ပုံ၊ ကားနားကိုင်ဆောင်မှု၊ ကားနားကိုင်ခံစားမှု ခါးကိုင်ဆောင်မှု၊ ကားထိုင်ခုံရုပ်လဲရန်	GA Manager	200,000	Approve

S. Chit Ron Su

S. Chit Ron Su

S. Chit Ron Su

S. Chit Ron Su

S. Chit Ron Su