




No 589-592,Bo Aung Kyaw Street,Yangon-Pathein High Way Road,Hlaing Thar Yar Township, Yangon, Myanmar

Print Date : 22-Oct-2024

Taxi (Bus,Motorcycle,3-wheel etc...) Charges Form

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	State	Remark
1	2024-09-27	Power Generator	Service	Han Oo Zaw (2)	Go to Taunggyi BR machine repair	03:00	Hlaing Tharyar	Aung Mingalar	22,600	22,600	GA Manager Approved	Grab Tax



TRAVELLING REPORT

Date : 28.10.24

Report To	COO	
Employee Name	Han Do Zaw	
Position	Junior Mechanic	
Department	Service	
Business	PU	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	27.9.24	11.10.24
Total Days	15days	
Trip Information	1. From YAN To TAI	
	2. From To	
	3. From To	
Purpose For Travelling	TAI BR Support (machine repair).	
Travel Date	Activities	Remark
27.9.24 ~ 28.9.24 29.9.24 ~ 11.10.24	Go to Taunggyi BR ① Customer - Asia Myanmar Co., Ltd Model - MC-110TS (18100450) Problem - Inspection and engine disassembly Alternator servicing ② customer - Thein Yandayar Model - MW-33PS2 Problem - Engine can't ③ Customer - Champion Purified Model - APD110C Problem - Regular service ④ Customer - Cafe Zaunggyi Model - MC 658S Problem - Alternator servicing	
		next => job details attached

Reported by
 Sign :
 Name : Chit Pon Su
 Position : SH

Checked by
 Sign :
 Name : Thint Naing
 Position : DH

Approved by
 Sign :
 Name :
 Position :

(DH/AGM/GM)

(COO)

05-CHL-HRM-FRM-064-01

TGI BR Support Job Record

No	Date	JR.NO	Customer	Model	Problem	Remark
1	9/29/2024	PSG/JR/24/09/1242	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Inspection and engine disassembly	✓
2	9/30/2024	PSG/JR/24/09/1242	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Main alternator dismantled and main stator cleaning	✓
3	10/1/2024	PSG/JR/24/09/1242	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Main rotor, exciter stator cleaning and oil sump dismantled	✓
4	10/2/2024	PSG/JR/24/09/1242	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Fuel tank cleaning and engine under side cleaning	✓
5	10/3/2024	PSG/JR/24/10/1360	Thein Yandanar	MW 33PS1	Engine can't crank	✓ Pass.
6	10/4/2024	PSG/JR/24/09/1242	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Engine cleaning and crank shaft seal change	✓
7	10/5/2024	PSG/JR/24/10/1279	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Valve adjustment	✓
8	10/6/2024	PSG/JR/24/10/1279	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	oil sump installation	✓ Pass.
9	10/7/2024	PSG/JR/24/10/1287	Champion Purified Drinking	APD 110 C	Regular service	
10	10/7/2024	PSG/JR/24/10/1286	CAFE ZAWGYI	MC 65 BS	Inspection test run	
11	10/8/2024	PSG/JR/24/10/1289	CAFE ZAWGYI	MC 65 BS	Main alternator remounted	
12	10/9/2024	PSG/JR/24/10/1297	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Test run	
13	10/10/2024	PSG/JR/24/10/1309	CAFE ZAWGYI	MC 65 BS	Test run	
14	10/11/2024	PSG/JR/24/10/1313	Asia Myanmar Co.,Ltd	MC-110TS(18100450)	Wire line checking and repair	

Asia Myanmar. - Alternator dismantling, dis; , cleaning,
 Engine valve lapping adjustment.
 Fuel tank cleaning, engine parts cleaning.
 Testing,
 Wire line checking. } 9-days.

Cafe Zawgyi - alternator servicing.
 Test run. } 3days.

TGI BR Support Job (Revenue)

No	Customer	Model	Problem	Amount	Remark
1	CAFE ZAWGYI	MC 65 BS	Alternator servicing	1400000	
2	Asia Myanmar	MC-110TS(18100450)	Minor Overhaul & alternator servicing	2000000	
3	Thein Yandanar	MW 33PS1	Engine can't crank	60000	
4	Champion Purified Drink	APD 110 C	Regular service	80000	
Total (MMK)				3540000	