



# SERVICE REPORT

UMG

Job Order No MC-YGN-JR-2502070  
 Customer Name LIMA Motor  
 Machine Location UD showroom  
 Machine Model Selena  
 Machine Sr.No R195KJJBKAS00148, 182,  
 Engine Sr.No 208  
 Houe Meter or) Km 1km  
 Job Site Distance .....  
 Application .....  
 Number of Trip .....

	Date	Time
Customer Call Date		
Confirm with Customer		
Go to Job Site Time		
Arrival Job Site Time		
Job Start Time	15.2.25	8:30 AM
Job Finish Time	15.2.25	2:30 PM
Go Back from Site		
Arrival Office Time		
Job Delay Date&Time		
Reason of Job Delay		

Customer Call Problem

Inspection and Repair

Cause of Problem

Service Action

- checked covers and painting (engine, engine oil, gear, oil, brake system, wheel, exhaust, electrical system, tool kits, rear mirror, absorber, display, air cleaner, engine sound):
- Motorcycle kicking.
- Job was finished.

Failure Causal Part

No	Part Description	Part No	Qty	Remark

Service Charges

Customer Sign .....

Service Person Sign [Signature]

Customer Name .....

Service Person Name Thura Min

Checked By  
 Name: Thura Min  
 Sign: [Signature]  
 Service Man

Acknowledge By  
 Name: Saw Elsay Wah  
 Sign: [Signature]  
 Service SH

Approved By  
 Name: [Signature]  
 Sign:  
 Service DH

Remark  
 OT in UD



# MC BU Team Members

19 members, 2 online



Pinned Message  
Photo




သူရမင်းပွမ္ဂ မနက်ဖြန် OTဆင်းလိုက်ပါအုန်း ညီ ဆိုင်ကယ် သုံးစီးကို final စစ်ပေးထားပါ။ 🍷🍷 16:30 ✓

February 15

သူရမင်းပွမ္ဂ  
ဟုကဲ့ပါ



08:40



OTပါဗျာ



08:45

Ko Chit San Ko

admin

Saturday Reminder



Business is All About Relationshin.



Message

