


## Damage Photo for CE1 Parts

No	Product Code	Trim	Product Name	Qty	Pprice	Total	Photo	Remark
1	20766790	20766790	Big End Bearing, Crankshaft	3	22.75	68.25		<p>ဘယ်ဘယ်ဖြစ်နေပါသည်                      သုံးစရပါ Supplier ဆီမှ                      Credit Note(3003940)                      ရပြီးဖြစ်ပါသည်</p>

Prepared By  
SPart Admin  
Zaw Myo

Checked By  
Spart DH  
Aye Theingyi Myint

Anknowledge By  
F&A Head  
Myat Min Thaw

Anknowledge By  
GM/OM  
Wutt Ye Aung  
Aung Kyaw Thu

Approved By  
GM(After Sale Division)  
Aung Hein Win

Approved By  
COO(After Sale Division)  
Aye Mla Htoon

12/19/2021

16/05/2021