



Taunggyi Branch
No 85, Union Main Road, Oo Mhin Loop, Taung Lay Lone Vil-lage, Taunggyi Tsp, South Shan State. Taunggyi
Tel :
Fax:

PAYMENT VOUCHER

Voucher No. : TGY-PV-2025-04-0039

Cashier : _____

Voucher Date : 2025-04-10

To : _____

Currency : MMK

Applicant _____ Adm. Manager _____ GM _____

No	Description	Purpose	Subtotal
1	PAY TO SAW YAN NAING MOE & NAING MIN ZAW TA CHARGES FOR SRV JOB GO TO TIGYPT CUSTOMER EDEN ENERGY (12.3.25) & (2.4.25) = KS 60000/-	Admin - Employee Travelling Expenses - Local Trip-TGY	60000.00
Total			60,000.00

Total in Words : _____

Note : PAY TO SAW YAN NAING MOE & NAING MIN ZAW TA CHARGES FOR SRV JOB GO TO TIGYPT CUSTOMER EDEN ENERGY (12.3.25) & (2.4.25) = KS 60000/-

Date : _____ Name/NRC No : _____ Signature : _____

Date : 10.4.2025

BU/BR/Division : Saunggyi Branch

Department : SRV

Issue Amount : 60,000,000 Kyats / USD

Budget include (or) Not :

Yes Budgeted Title and Amount :

No Reasons for :

Required For:
TA Charges for SRV Job, Tigypt (12.3.2025) / Eden Energy
TA Charges for SRV Job, Tigypt (2.4.2025) / Eden Energy.

မှတ်ချက်။
(၁) အဆင့်ဆင့်သက်ဆိုင်ရာတာဝန်ရှိလူကြီးမင်းများအားလုံး သေချာစွာစစ်ဆေးစစ်ဆေးတွက်ချက်ပြီးထားသော ငွေပမာဏဖြစ်ရပါမည်။
(The amount requested must be properly calculated, checked and verified by respective authorized person)
(၂) ထုတ်ယူငွေနှင့် ပတ်သက်၍ အမှားအယွင်း၊ လိမ်လည်မှု နှင့် အလွဲသုံးစားမှု တစ်စုံတစ်ရာ ရှိခဲ့ပါက၊ သက်ဆိုင်ရာ တာဝန်ရှိစစ်ဆေးအတည်ပြုသူက အပြည့် အဝ ပြန်လည်ရရှိအောင် တာဝန်ယူ ဆောင်ရွက်ပေးရမည်
(If there is errors, frauds or misappropriation, the authorized person must take full responsibility to recover the loss)

Request By: Saw Yan Nang Moe
Checked By: Mgr/DH
Checked By: Finance & Account
Approved By: GM/AGM/COO
Approved By: CMC/CEO/Chairwoman

SERVICE REPORT

Order No. 76713012610310103
 Customer Name Ealen Energy
 Machine Location Tgypt
 Machine Model 2X350LAL-F6
 Machine SR.No. 0153502
 Engine Brand ISUZU
 Engine Model 6HK1
 Engine Sr.No. 985131
 Hour Meter (or) Km 2682.9h
 Job Site Distance Over 40 miles
 Application Mining
 Number of Trip 1

Customer Call Date	Date	Time
	12.3.25	3:00
Confirm with Customer		3:30
Go to Job Site Time		4:00
Arrival Job Site Time		10:15
Job Start Time		11:30
Job Finish Time		5:30
Go Back From Site		5:30
Arrival Office Time		11:45
Job Delay Date & Time		
Reason of Job Delay		

Customer Call Problem

Regular service

Cause of Problem

Service Action

Our service team go to job site and checked around the machine. Dismounted fuel filters, engine oil filter & change new we drained old engine oil and we filled new engine oil. we drained swing motor old oil and we filled new oil swing motor. Test run the machine. It normal. Job was finished.

Failure Causal Part

No.	Part Description	Part No	Qty	Remark

*Cash On Service Work Done (ဝက်ပြင်ခ ကျသင့်စေရအား ပြင်ဆင်ပေးရန်အတွက်)

*In case must settle within 7days (အကြောင်းချိုးကြောင့် ချက်ချင်း ငွေပေးချုပ်ငြိမ်း (၇)ရက်အတွင်း ပေးချရမည်)

Customer Sign

[Signature]

Service Person Sign

[Signature]

Customer Name

Service Person Name

SYMM, NING

Name/Sign: <i>[Signature]</i>	Comment
Service Dept: Head	Comment
Name/Sign:	Branch Operation Head

Redo	
Excessive Visit	
STD Job Time (HR)	
Actual Job Time (HR)	
% to STD Time	
Customer Comment	

SERVICE REPORT

No. 1651R125103102
 Customer Name Edco energy
 Site Location Tigapt
 Machine Model 285501CH-561
 Machine SR No. 0053601
 Engine Brand ISUZU
 Engine Model 6HK1
 Engine Sr.No. 984129
 Hour Meter (or) Km 2675.1h
 Job Site Distance Over 40 miles
 Application Mining
 Number of Trip 1

Customer Call Date	Date	Time
Confirm with Customer	12-3-25	8:00
Go to Job Site Time		8:30
Arrival Job Site Time		9:00
Job Start Time		10:15
Job Finish Time		11:30
Go Back From Site		5:30
Arrival Office Time		6:30
Job Delay Date & Time		7:45
Reason of Job Delay		

Customer Call Problem Regular service

Cause of Problem

Service Action
 Our service teams go to job site and checked around the machine. Discarded fuel filters, engine oil filter and change new, the drained old engine oil and we filled new engine oil. we drained swing motor old oil and we filled new oil swing motor. Test run the machine. get normal. Job was finished.

No	Part Description	Part No.	Qty	Remark

*Cash On Service Work Done(စက်ပြင်မှု ကုသငွေများအား ပြင်ဆင်ပေးရန်အတွက်)
 *In case must settle within 7days (အကြောင်းအမျိုးမျိုးကြောင့် ချက်ချင်းငွေပေးချင်ပါက (၇)ရက်အတွင်း ပေးချေရမည်။)

Customer Sign CCa. Service Person Sign [Signature]
 Customer Name _____ Service Person Name SUM, NAY

Comment	Redo
Name Sign : <u>[Signature]</u> Service Dept. Head <u>[Signature]</u> Name Sign : <u>[Signature]</u> Branch Operation Head <u>[Signature]</u>	Excessive Visit STD Job Time (HR) Actual Job Time (HR) % to STD Time Customer Comment



SERVICE REPORT

Customer Name: တယ်ကီအီစီစီစီ
 Phone No: 95-9-2510316100
 Job Location: Eden Energy
 Machine Model: Tiggo
 Machine SR No: P235001
 Engine Brand: 2300D1
 Engine Model: YAMAHA
 Engine St. No: D37
 Hour Meter (or) Km: 12817061
 Job Site Distance: 2472.0 km
 Application: Over 40 miles
 Number of Trip: Mining

Date	Time
12.3.25	8:00
	8:30
	9:00
	11:15
	11:30
	5:30
	5:30
	5:45

Customer Call Problem: Regular service

Cause of Problem: _____

Service Action: Our service team go to job site and checked around the machine, we drained old engine oil. Dismounted fuel filter, meter separator, pre-filter and engine oil filter it change new. we filled new engine oil. Test run the machine it normal. Job was finished.

Failure Causal Part	Part Description	Part No.	Qty	Remark

*Cash On Service Work Done (တပ်ပြင်မှု ကုသငွေများအား ပြင်ဆင်ပေးရန်အတွက် ချက်ချင်းပေးဆွဲရပါမည်)
 *In case must settle within 7days (အကြောင်းပေးချက်ချင်းပေးဆွဲရန်အတွက် ၇ရက်အတွင်း ပေးဆွဲရပါမည်)

Customer Sign: (Signature) Service Person Sign: (Signature)
 Customer Name: _____ Service Person Name: SHAN LAY

Name Sign: _____ Service Dept Head: _____ Name Sign: _____ Branch Operation Head: _____	Redo	
	Excessive Visit	
	STD Job Time (HR)	
	Actual Job Time (HR)	
	% to STD Time	
Comment	Customer Comment	



SERVICE REPORT

Job No: TCY/SR/D5/04/0128
 Customer Name: Edan Energy
 Service Location: Thagapt
 Machine Model: FC 520 DL
 Machine SR No: 211243
 Engine Brand: Volvo
 Engine Model: D8F
 Engine S/N: DJEECB
 Hour Meter (or) Km: 2816.1
 Job Site Distance: over kilometer
 Application: ced mining
 Number of Trip: 1

	Date	Time
Customer Call Date	24.02.25	8:00 AM
Confirm with Customer	24.02.25	8:20 PM
Go to Job Site Time	4.4.2025	8:30 AM
Arrival Job Site Time	4.4.2025	11:00 AM
Job Start Time	4.4.2025	12:10 PM
Job Finish Time	4.4.2025	1:00 PM
Go Back From Site	4.4.2025	5:30 PM
Arrival Office Time	4.4.2025	8:00 PM
Job Delay Date & Time		
Reason of Job Delay		

Customer Call Problem: Regular service

Cause of Problem: Regular service.

Service Action: Fistly, we go to the job site and checked around the machine and checked engine oil level, coolant level, fan belt tension conditions and battery. And then, we changed old engine oil and changed engine oil filter and diesel filters. And then, we refilled new engine oil and checked engine oil level, we test-run the machine. All was normal - Job was finished.

Failure Causal Part

No	Part Description	Part No.	Qty	Remark

* Cash On Service Work Done (စက်ပြင်မှု ကျခံငွေများအား ပြင်ဆင်စီ ချက်ချင်းပေးဆွဲရန်။)
 * In case must settle within 7days (အကြောင်းအချိုးကြောင့် ချက်ချင်း ငွေပေးချင်ပါက (၇)ရက်အတွင်း ပေးချရမည်။)

Customer Sign: [Signature] Service Person Sign: [Signature]
 Customer Name: [Name] Service Person Name: [Name]

Name Sign: <u>[Signature]</u> Service Dept Head	Comment	Redo	
		Excessive Visit	
Name Sign: <u>[Signature]</u> Branch Operation Head	Comment	STD Job Time (HR)	
		Actual Job Time (HR)	
		% to STD Time	
		Customer Comment	



SERVICE REPORT

TOL/SR/25/04/0130
 Eden Energy
 figure
 2x350 LCA-SG
 S3601
 G-HK1 TSU ZU
 G-HK1
 924121
 30640.5 hr
 EVER 40 ml(03)
 coal mining
 15

Customer Call Date	Date	Time
2-4-2025	2-4-2025	8:20 AM
2-4-2025	2-4-2025	8:20 PM
4-4-2025	4-4-2025	8:30 AM
4-4-2025	4-4-2025	11:00 AM
4-4-2025	4-4-2025	1:10 PM
4-4-2025	4-4-2025	3:00 PM
4-4-2025	4-4-2025	5:30 PM
4-4-2025	4-4-2025	8:00 PM
Job Delay Date & Time		
Reason of Job Delay		

Customer Call Problem

Regular Service.

Cause of Problem

Regular Service

Service Action

Firstly, we go to the job site and checked around the machine and checked engine oil level, extend level, fan belt tension and air cleaner. And then, we drained old engine oil and hydraulic oil. And we changed engine oil filter, fuel filter and hydraulic filter. And then, we refilled new engine oil and hydraulic oil and checked level. we test our the machine All was normal. Job was finished.

Failure Causal Part

No	Part Description	Part No.	Qty	Remark

*Cash On Service Work Done (စက်ပြင်ခ ကျသင့်ငွေများအား ပြင်ဆင်ပြီး ချက်ချင်းပေးဆွဲရပါမည်။)

*In case must settle within 7 days (အကြောင်းချိုးကြောင့် ချက်ချင်း ငွေပေးချုပ်ငြိမိက (၇)ရက်အတွင်း ပေးချရမည်။)

Customer Sign

Uchi

Service Person Sign

[Signature]

Customer Name

Service Person Name

SAN/THZ

Comment

Redo

Name Sign :

Excessive Visit

Service Dept. Head

STD Job Time (HR)

Comment

Actual Job Time (HR)

% to STD Time

Customer Comment

Name Sign:

[Signature]

Branch Operation Head



SERVICE REPORT

Job Order No. TCY/ML/25709(0131
 Customer Name Edon Exports
 Machine Location Dump
 Machine Model EX350LCU-SQ
 Machine SR No. 53002
 Engine Brand ISUZU
 Engine Model GHK1
 Engine Sr.No. 905171
 Hour Meter (or) Km 3089 h
 Job Site Distance 2000 AC miles
 Application cell mining
 Number of Trip 1

Customer Call Date	Date	Time
24-02-2025	24-02-2025	9:00 PM
Confirm with Customer	24-02-2025	3:20 PM
Go to Job Site Time	24-02-2025	0:30 AM
Arrival Job Site Time	24-02-2025	11:00 AM
Job Start Time		3:10 PM
Job Finish Time		5:20 PM
Go Back From Site		5:30 PM
Arrival Office Time	24-02-2025	9:00 PM
Job Delay Date & Time		
Reason of Job Delay		

Customer Call Problem

Regular service

Cause of Problem

Regular service

Service Action

In fact, we go to the job site and checked around the machine and checked engine oil level, accent level, fan belt tensions and air cleaners. Then we changed old engine oil and hydraulic oil. And we changed engine oil filter, fuel filters and hydraulic oil filters. And then we installed new engine oil and hydraulic oil and checked level, we test run the machine. All was normal. Job was finished.

Failure Causal Part

No	Part Description	Part No	Qty	Remark

*Cash On Service Work Done (စက်ပြုငွေ ကုသငွေများ: ပြင်ဆင်: ချက်ချင်းသွင်းရန်။)

*In case must settle within 7days (အကြောင်းချိုးပြီးကြာ ၇ ရက်အတွင်း သေချာရမည်။)

Customer Sign

Uda

Service Person Sign

[Signature]

Customer Name

Service Person Name

RYAN H THZ

Comment	
Name Sign :	<i>[Signature]</i>
Service Dept: Head	<i>[Signature]</i>
Name Sign :	<i>[Signature]</i>
Branch Operation Head	<i>[Signature]</i>

Re-do	
Excessive Visit	
STD Job Time (HR)	
Actual Job Time (HR)	
% to STD Time	
Customer Comment	



SERVICE REPORT

Job Order No. ၇၆၂၅၂၃/၂၅/၀၂/၀၂၄
 Customer Name Edon Energy
 Machine Location Mying
 Machine Model LC-350PL
 Machine SR No. 23001
 Engine Brand VOLVO
 Engine Model D2F
 Engine St. No. 12217069
 Hour Meter (or) Km 236423
 Job Site Distance ၁၂၀-၄၀ မိုင်
 Application Construction
 Number of Trip 1

Customer Call Date	Date	Time
2-4-2025	2-4-2025	3:00 PM
Confirm with Customer	2-4-2025	5:28 PM
Go to Job Site Time	4-4-2025	6:30 AM
Arrival Job Site Time	4-4-2025	11:00 AM
Job Start Time	4-4-2025	11:10 AM
Job Finish Time	4-4-2025	12:00 PM
Go Back From Site	4-4-2025	5:30 PM
Arrival Office Time	4-4-2025	6:00 AM
Job Delay Date & Time		
Reason of Job Delay		

Customer Call Problem Regular Service
 Cause of Problem Regular service

Service Action Firstly, we go to the job site and checked around the machine and checked engine oil level, coolant level, fan belt, tension and air-cleans. And then, we drained old engine oil and changed engine oil filter and fuel-filter. And we refilled the new engine oil and checked engine oil level, we test run the machine. All was normal. Job was finished.

Failure Causal Part

No.	Part Description	Part No.	Qty	Remark

*Cash On Service Work Done(စစ်ပြင်ခ ကျသင့်ချေပေးသော ပြင်ဆင်မှု ချက်ချင်းပေးဆွဲရန်)
 *In case must settle within 7days (ခေကြာသီရိပျိုးကြွင့် ချက်ချင်း ငွေပေးချုပ်ငြိမ်း (၇)ရက်အတွင်း ပေးချေရမည်)

Customer Sign [Signature] Service Person Sign [Signature]
 Customer Name U Aun Service Person Name STANLEY HZ

Comment	Rebo
Name Sign: <u>[Signature]</u>	Excessive Visit
Service Dept: <u>Liquid</u>	STD Job Time (HR)
Operation Head Sign: <u>[Signature]</u>	Actual Job Time (HR)
	% to STD Time
	Customer Comment

Order No. _____
 Customer Name _____
 Machine Location _____

