



TRAVEL ADVANCE CLEAR FORM

Cash Advance		Aung Phyo Thu		
Employee Name	Aung Phyo Thu	Estimated Date of Travel	20.3.25 to 4.4.25	
Position Rank	STDP	Total Day	16 days	
BU/BR/DIV. Dept	Service	Destination		
Purpose	To install 12kw & 5kw Solar System installation. Inspection.			
Travelling Permit	Inspection - help earthquake.			
Arrival Place				
Actual Date & Time of Travel	20.3.25 to 4.4.25			
Total Day	16 days			
HR Name	Thint Thint Thu			
HR Sign				
BOH/Authorized Person Name	Aung Myo Swe			
BOH/Authorized Person				
Advance Clear				
Actual Date & Time of Travel	20.3.25 to 4.4.25		Total Day	16 days
Departure Date & Time	20.3.25		Arrival Date & Time	4.4.25
Date	Description	Total Amount		
		Kyats	USD	
20.3.25 to 4.4.25	T/Charges (16 days x 30,000) for 2 person Aung Phyo Thu, Aung Phyo Kyaw	48,000/-		
	Transportation Charges	38,000/-		
	Bus ticket	58,000/-		
	Cycle fuel	29,000/-		
	Taxi charges	30,000/-		
Total Expense (Kyats/USD)		635,000/-		
Cash Advance (Kyats/USD)		1,200,000/-		
Balance Refund/Additional (Kyats/USD)		565,000/-		
Job Report Status				
Authorization	Name	Position	Date	Sign
Prepared By	Ei Thwe Phyo	Admin.	22.4.25	
Approved By Dept Head	Aung Ro Ro Co	ADH	24.4.25	
Approved By GM/AGM/COO	Phyo Thu	AGM		
Acknowledged by related Superior for Job Report	U Aye Mbn Htoon			
HR Check & Approved	Nyein Ei Ei Khaing	HR.	28.4.25	
Cash Received				
Remark				

04-CFD-CAS-FRM-006-02

ကြယ်

ကာလက်မှတ် အရောင်းဌာန
ရန်ကုန်-မန္တလေး။ဝမ်းတွင်းမြို့

09-776560519 / 09-445077377 / 09-2165616

လက်ခံသူအမည် ... ကျော်ဖြူသူ
ဖော်ပြသူအမည် ရက်စွဲ၊ ၇.၆.၂၀၂၀

စဉ်	အမျိုးအမည်	ဦးရေ	နှုန်း	သင့်ငွေ(ကျပ်)
	ကုန်	၁		၂၀၀၀
	စာအုပ်အားဖြင့်	၁		
				၂၀၀၀

လက်မှတ် -----

- (၁) ဥပဒေနှင့်မလွတ်ကင်းသောပစ္စည်းများလက်ပံပါ။
- (၂) ပစ္စည်းများရောက်ရှိပါက(၇)ရက်အတွင်းထုတ်ယူမှုမရှိလျှင်တာဝန်ယူပါ။
- (၃) တန်ဖိုးအပစ္စည်းပျက်စီးပျောက်ဆုံးပါကတန်ဖိုး(၁၀)ဆသာပေးလျက်ပါမည်။

မန္တလေး


mandalarnn.com.mt

အောင်ဖြိုးသူ 09981568557

မန္တလေး၊ ရန်ကုန် (အောင်မင်္ဂလာ) - ကျောက်ဆည် (ဝမ်းတွင်း စိန်
ခြယ်) 1388471

Ref#9327-8347(21 ကော်ရောင်းစည်းဝင်ရပ်ဘူးဝ) Mar 23,

1:55 PM | ရှင်း = 15.000 | ကြွေး = 0 | တို့ = 0



၁။ ကုန်ပစ္စည်း ပျောက်ဆုံးပါက ဟန်ဆာ၏ (၁၀) ရာခိုင်နှုန်း ပေးပေးလျှော်ပါမည်။
၂။ ကုန်ပစ္စည်းတို့ စိမ့်ကျိုးစွဲ ပျက်စီးပျက်စီးလာပါက အလှူငွေပေးပို့ရန် မရယူ။
ကုန်ပစ္စည်းများ အား လုံခြုံစေရန်အတွက် ကျွန်ုပ်တို့၏ ကြိုးပမ်းပေးကြပါရန်နှင့် ပျက်စီးပါ
က တာဝန်မယူပါ။


မုဒုံကုမ္ပဏီ

mudula.com.mm

၂၀၂၁, ၂၀၂၂, ၂၀၂၃, ၂၀၂၄

မုဒုံကုမ္ပဏီ(ပတ်ဘလစ်)လီမိတက် (A-၁) မိတ္ထီလာမြို့နယ်
မြို့နယ်၊ မြောက်ပိုင်းလမ်း၊ မြောက်ပိုင်းလမ်းမအလယ်၊ ကုမ္ပဏီအိမ်

Ref # 2182-2112(၁ | ဝယ်) | Apr 04, 10:45 AM |
ငွေ - 15,000 | ဝယ်ခြင်း = 0 | ဝယ်ခွန် = 0



မုဒုံကုမ္ပဏီ(ပတ်ဘလစ်)လီမိတက် (A-၁) မိတ္ထီလာမြို့နယ်
မြို့နယ်၊ မြောက်ပိုင်းလမ်း၊ မြောက်ပိုင်းလမ်းမအလယ်

Nilaryoma (Meikthila)

Salaya Division, Meikthila Township, Kantar
Village, Industry Zone 4th Street 0945-309860

92 Ron Octane

Vr No: 11 01-20250322-2030

Date: 22/03/2025 12:46:01 PM

Pump: Pump 6 Car No: Cycle

Handwritten signature

Cashier : POS1

Gal	Liter	Price	Amount
0.354	1.610	3105	5.000

Thank You. See You again!

Change : 0 Ks

We are selling verily the price , quantity and quality.
Thank you for your purchases by Nilaryoma Meikthila

NYOMA TRADING CO;Ltd

Near Yangon - Mandalay Main Road
Meikthila Industrial Zone (4) Street
Meikthila Township

09-454809860 09-983633587

23/3/2025 (8:34 AM)

Cashier : wai yan

(2014)

Name : m/m

Car Number :

92 Ron



လိပ်	လီတာ	ဈေးနှုန်း	ကျသင့်ငွေ(K)
0.64	2.90	3,105.00	9,005

Total Amount: 9,004 Ks
Discount : Ks
Cash : 9,000 Ks
Change : 0 Ks

We are selling verily the price , quantity and quality.
Thank you for your purchases by Nilaryoma Meikthila



TRAVEL ADVANCE CI

Maung Maung	Estimated Date
STDP	Total Day
RE Service	Destination
IMW (H Sa Maung)	

AKA 888

Petrol Star

Petrol Star (Kundwin)
 : WDPS1426024
 : Ph: 09-970426699/09-790426699
 : 2025-03-25 11:02:45
 No :
 Cashier :

Chief

POP : Cash

Item	Pump Price	Litre	Gallon	Amount
92 RON	P9 3,105	1 610	0 354	5,000

Total Amount: 5,000

Thank you!

Total Amount: 5,000 Ks
 Discount : Ks
 Cash : 5,000 Ks
 Change : 0 Ks

We are selling verily the price , quantity and quality.

NYOMA TRADING CO;Ltd

Near Yangon - Mandalay Main Road
Meikthila Industrial Zone (4) Street
Meikthila Township

09-454809860 09-983633587

[0027]

4/4/2025 (9:37 AM)

Name : k

Cashier : U Nyi Nyi Moe

Car Number :



92 Ron

ရက်	လိတာ	ဈေးနှုန်း	ကျသင့်ငွေ(K)
0.35	1.61	3,115.00	5,015

Total Amount: 5,015 Ks
Discount : Ks
Cash : 5,000 Ks
Change : 0 Ks

We are selling verily the price , quantity and quality.

Thank you for your purchases by Nilaryoma Meikthila

ENERGY

5829 0837 2213 9513



Shubh

Station: (M) Energy (Mekong)
No. Invoice: H 47 20220101 0002
Date: 01/01/2025 5295201
Pump: Fuel
FS No: 09 891755033

Fuel Type	Price x liter		Amount
Regular Gas	3115 x 1.6000	MMK	5,000
Total (Inclusive Tax)		MMK	5,000

Thank You Please come again
Have a safe journey



No.589-592,Bo Aung Kyaw Street,Yangon-Pathein High Way Road,Hlaing Thar Yar Township, Yangon, Myanmar.

Print Date : 08-Apr-2025

Taxi (Bus, Motorcycle, 3-wheel etc...) Charges Form

No	Date	Holding Business	Department	Name	Rental Purpose	Departure Time	Start Location	End Location	Claim Amount	Allowed Amount	Status	Remark
1	2025-04-04	Renewable Energy	Service	Aung Phyo Thu (2) , Aung Than Kyaw (2)	12kW Solar system installation and inspection in Pyawbwe, Wundwin	08:00	No.3 main road (near Denko fuel station) Mingalar Done	Bogyoke (HTY)	30,000	30,000	GA Manager Approved	Tools box 4 box, package



TRAVELLING REPORT

Date : 4.4.25

Report To	Aung Ko Ko Co	
Employee Name	Aung Phyo Thu, Aung Han Kyaw	
Position	STDP, STDP	
Department	Service	
Business	RE	
Departure & Arrival	Departure Date And Time	Arrival Date And Time
	20.8.25	4.4.25
Total Days	16 days	
Trip Information	1. From YBRO To Meiktila	
	2. From Pyawbwe To Myittha	
	3. From Meiktila To YBRO	
Purpose For Travelling	12kW solar system installation & inspection.	
Travel Date	Activities	Remark
	Daily report attached by below.	

Reported by
 Sign : *[Signature]*
 Name : Aung Phyo Thu
 Position : STDP-3

Checked by
 Sign : *[Signature]*
 Name : Aung Ko Ko Co
 Position : ADH

Approved by
 Sign : *[Signature]*
 Name : U Aye Mon Htoon
 Position : *[Signature]* 7/5/25

(DH/AGM/GM)

(COO)

05-CHL-HRM-FRM-064-01

- Over lead time. (standard time - 12 days.)
 Actual - 16 days, Over - 4 days.
 (Cause - ကျွန်ုပ်တို့ အများစုသည် အချိန်မီ အစီအစဉ်များကို အကောင်အထည်ဖော်နိုင်ခြင်း မရှိပါ။) Pass

	Date	Status	Job Types/Number
	20.3.2025	Attend	Went to Meikhtila from Yangon.
2	21.3.2025	Attend	Did morning exercise and joined sale meeting. Went to Pyawbwe customer Daw Sandar Oo site, checked and upgraded the ML 200Ah battery without display 2units. Then charged the batteries with solar, Epc. It's ok. And testrun loads with battery. It's normal at all. Retight the breaker's screws and explained to the customer how to use the system well. Write service report and took the customer sign. Therefore went to customer Daw San Win site to upgrade ML 200Ah battery without display 2units and retight the screws. Then we went to Pyawbwe downtown customer U Myo Min Myat site, checked whether upgraded the ML 200Ah battery with display 3units. Those have been already upgraded. And we made cleaning service the inverter, battery and AC / DC breaker boxes.
3	22.3.2025	Attend	Went to Wun Dwin customer U Tun Lin site to give the Solar structure frame design. Checked the solar accessories and discuss with the solar frame structure maker. Look around to place Inverter, battery and Panel box.
4	23.3.2024	Holiday	Move to Wun Dwin customer U Tun Lin site, checked the arrival accessory list and made starting the plans. There is constructors made plaster the wall where we choose to place the systems. SO that we'll wait at least 1 day to dry and consistant the wall. Made hit the earth rods 4pcs and measure the ohm. It's still 5ohm and we'll continue try it tomorrow.
5	24.3.2025	Attend	Today at U Tun Lin (Wun Dwin) site, hit the earth rods again and made the earthing system. It's fully done. List for needed the Job site accessories and bought those. Then checked the wall that is dry or wet. It's a little bit wetting so that we need to wait untill tomorrow.
6	25.3.2025	Attend	At Wun Dwin customer U Htun Lin site, set up inverter 2pcs and installed AC / DC panel box. Made AC DC wiring system and installed battery cables in the battery bus-bar.
7	26.3.2025	Attend	Set up AC input / output in the Change breaker and made earthing system inverter body, AC / DC panel box. And we do equalize the batteries to equal the battery cells and set up L - feets, Rail rods on the structure.
8	27.3.2025	Holiday	Set up AC input / output in the Change breaker and made earthing system inverter body, AC / DC panel box. And we do equalize the batteries to equal the battery cells and set up L - feets, Rail rods on the structure.
9	28.3.2025	Attend	Today at Wun Dwin customer U Htun Lin site, Installed ML 550W solar panel 24pcs and run for solar cable piping ways. Set up MC4 connector for solar 4 strings. Then test the solar volt in the fuse with meter. It's ok.
10	29.3.2025	Attend	Test the inverter parallel system is normal. It's not normal. So we adjust the setting as manual book. It's still abnormal. Then we checked the inverter's update. It's not updated. And then we upgraded the inverter version. It's ok. The inverter parallel system is normal and adjust the inverter setting. Made charging the batteries with solar. It's ok. At the evening the batteries all have been Soc 100%.
11	30.3.2025	Holiday	Checked the overall site and cleaning the inverter, batteries. Opened and checked the batteries' inside cells, battery bus-bar and other wiring connections. It's normal and each of parts are fine on its own. Then we collect the tools and other site accessories. And Back to Meikhtilar from Wun Dwin.

12	31.3.2025	Attend	Checked the tools and site accessories as a tool list. And then checked the service report and follow up the customers whether using the system condition is good or how it is.
13	1.4.2025	Attend	Went to Wun Dwin customer U Htun Lin site, testrun a 3hp motor with the system. It's good. And explained to customer how to use the system normally. Then went to Myitthar customer Ko Hein Htet Aung site, discussed with the customer about installation. As the customer decision is not still sure, it's pending.
14	2.4.2025	Holiday	Went to Pyawbwe customer Daw Sandar Oo site to check batttery charging low inspection. There is Inverter setting no 7 battery charging amp is changed so that the battery charging was too low. And we change the setting back and charging the batteries. It's ok. Charging rate is high and it's fully from 40% to 100% within 2 hours.
15	3.4.2024	Attend	Went to U Myo Min Myat Pyawbwe site emergency, 200Ah battery 1pcs is suddently burn. So we put down that one with fire extinguisher and checked another 2 batteries' inside cells and battery bus bar, other wiring socket condition. Took back those to Meikhtilar office. As the same time, we checked in the customer Daw San Win Pyawbwe site, test the 6KW inverter 2pcs are normal and adjust the inverter setting. Testing charge the batteries with solar. It's ok.
16	4.4.2025	Attend	Made Morning exercises ,5s and attended meeting at Meiktila branch. Checked Matador lectro 51.2V 280 Ah without display battery and 200Ah with display battery And upgraded at Meiktila branch. Checked and upgraded 51.2V 280Ah with display battery 2pcs at Meiktila branch. Collect the tools and packed accessories box. Went back to Yangon from Meikhtilar.